

15-163-20469-00-00

State Corporation Commission

CONSERVATION DIVISION

(Oil, Gos and Water)
P.O. Box 17027 3830 S. Meridian
WICHITA, KANSAS 67217

VERBAL PERMIT FORM
(To Be Filed By Plugging Agent)

RECEIVED STATE CORPORATION COMMISSION

NOV 1 0 1972

J. Lewis Brock Administrator 500 Insurance Building Wichita, Kansas 67202

Dear Sir:

CONSERVATION DIVISION Wichita, Kansas

date requested permission to plug the following described well: Mr. Fickle guarantees payment of the plugging fee. Operator's full Name: Petroleum Management, Inc. Complete Address: 1515 Vickers KSB&T Bldg., Wichita, Ks. Lease Name: Joy "B" Well No. 1 Location: A SE SW SW Sec. 21 Twp. 7 Rge. (E)(W) 1 County: Rooks Total Depth 3187° Oil Well Gas Well Input Well SWD Well D & AXX Lost Hole Mr. Fickle was instructed to plug the well as follows: Gun pits, circulate heavy mud, set cementing plug at 500° and displace 25 sk cmt thru drill pipe. Heavy mud to 40° set cementing plug, 1/2 sk Khulls and 10 sk cmt to base of cellar.	Mr.	, , , , , , , , , , , , , , , , , , , 	Fickle			of	andersky far formal	Red Tig	ger Drl	g.	has	this
Operator's full Name: Petroleum Management, Inc. Complete Address: 1515 Vickers KSB&T Bldg., Wichita, Ks. Lease Name: Joy "B" Well No. 1 Location: A SE SW SW Sec. 21 Twp. 7 Rge. (E)(W) 1 County: Rooks Total Depth 3187° Oil Well Gas Well Input Well SWD Well D & AXX Lost Hole Mr. Fickle was instructed to plug the well as follows: Gun pits, circulate heavy mud, set cementing plug at 500° and displace 25 sk cmt thru drill pipe. Heavy mud to 40° set cementing plug, 1/2 sk K	date	reque	sted pe	ermis	sion	to p	lug ti	he.foll	owing d	lescri	bed well:	;
Operator's full Name: Petroleum Management, Inc. Complete Address: 1515 Vickers KSB&T Bldg., Wichita, Ks. Lease Name: Joy "B" Well No. 1 Location: A SE SW SW Sec. 21 Twp. 7 Rge. (E)(W) 1 County: Rooks Total Depth 3187° Oil Well Gas Well Input Well SWD Well D & AXX Lost Hole Mr. Fickle was instructed to plug the well as follows: Gun pits, circulate heavy mud, set cementing plug at 500° and displace 25 sk cmt thru drill pipe. Heavy mud to 40° set cementing plug, 1/2 sk K	Mr.	Fic	kle		-	g'	uarani	tees pa	yment c	of the	plugging	fee.
Lease Name: Joy "B" Well No. Location: A SE SW SW Sec. 21 Twp. 7 Rge. County: Rooks Total Depth 3187° Oil Well Gas Well Input Well SWD Well D & AXX Lost Hole Mr. Fickle was instructed to plug the well as follows: Gun pits, circulate heavy mud, set cementing plug at 500° and displace 25 sk cmt thru drill pipe. Heavy mud to 40° set cementing plug, 1/2 sk K												
Location: A SE SW SW Sec. 21 Twp. 7 Rge. (E)(W) 1 County: Rooks Total Depth 3187° Oil Well Gas Well Input Well SWD Well D & AXX Lost Hole Mr. Fickle was instructed to plug the well as follows: Gun pits, circulate heavy mud, set cementing plug at 500° and displace 25 sk cmt thru drill pipe. Heavy mud to 40° set cementing plug, 1/2 sk K	Comp	lete A	ddress		1	515 Vi	ckers	KSB&T	Bldg.,	Wic	hita, Ks	•
Location: A SE SW SW Sec. 21 Twp. 7 Rge. (E)(W) 1 County: Rooks Total Depth 3187° Oil Well Gas Well Input Well SWD Well D & AXX Lost Hole Mr. Fickle was instructed to plug the well as follows: Gun pits, circulate heavy mud, set cementing plug at 500° and displace 25 sk cmt thru drill pipe. Heavy mud to 40° set cementing plug, 1/2 sk K	Leas	e Name		*****		Јоу	"B"		Wel	1 No.	1	
County: Rooks Total Depth 3187° Oil Well Gas Well Input Well SWD Well D & AXX Lost Hole Mr. Fickle was instructed to plug the well as follows: Gun pits, circulate heavy mud, set cementing plug at 500° and displace 25 sk cmt thru drill pipe. Heavy mud to 40° set cementing plug, 1/2 sk K	Loca	tion:_	A	SE	SW							
Mr. Fickle was instructed to plug the well as follows: Gun pits, circulate heavy mud, set cementing plug at 500° and displace 25 sk cmt thru drill pipe. Heavy mud to 40° set cementing plug, 1/2 sk K	Coun	ty:		Roo	ks		water the second second second second					,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,
Gun pits, circulate heavy mud, set cementing plug at 500° and displace 25 sk cmt thru drill pipe. Heavy mud to 40° set cementing plug, 1/2 sk K	Gas '	Well_	Inpu	ıt We	11_	sw	D Well	L	D & AX	X L	ost Hole_	
25 sk cmt thru drill pipe. Heavy mud to 40° set cementing plug, 1/2 sk K	Mr	Fick	Le			was	instr	ructed	to plug	the	well as f	ollows:
	Gun r	oits, o	circula	te h	ea v y	mud,s	et ce	menting	g plug a	at 500	o and di	splace
hulls and 10 sk cmt to base of cellar.	2 <u>5</u> sk	cemt t	thru dr	<u> 111</u>	pipe	. Heav	y mud	to 40	set c	ementi	ng plug,	1/2 sk K
	hulls	and I	l0 sk c	mt t	o ba	se of	cella	r.				essence of the section

Very truly yours,

Conservation Division Agent