## STATE OF KANSAS STATE CORPORATION COMMISSION

## 15-193-20135-00-00

## WELL PLUGGING RECORD

Make Required Affidavit Mail or Deliver Report to		Thomas	Con			
	-		COU	nty. Sec.	<u>14</u> Twp	7 Rge. 31 E/W
Conservation Division	Locati	on as "NE,	CNW A SW A	or foots	ge from 1	ines
State Corporation Comm.	Lease	Our or	C SE			
245 North Water	Lease			Corporat:		7 . 1 1 2 2 7
Wichita, KS 67202		PRODUCTION OF THE PARTY OF THE		chiltz		Well No.
		Address		ngton, Kar		
	Charac	ter or wer	I (Comp.	leted as C	ni, Gas o	or Dry Hole)
	-					On elicitat inflormation and an inflormatical analyses operated by an engage on the security and consequence operated
		ell comple				19
		ation for ation for				19
		ng commend				19 19
	Plugging commenced 8/16/79 Plugging completed 8/22/79					19
						g formation
<del> </del> <del> </del>				deplet	-	P TOT ILLIA C T OVI
	Ifap	roducing w	ell is a	bandoned.	date of	last production
						19
Locale well correctly on above	Vas pe	rmission o	btained	from the	Conservat	ion Division or
Section Pist	its ag	ents befor	e pluggi	ing was co	mmenced?	yes
Name of Conservation Agent who s	upervised	plugging			thazor	
Producing formation	De	pth to top	Вс	ottom	_Total De	pth of Well 4300
Show depth and thickness of all	water, oi	l and gas	formatio	ons.		
OIL, GAS OR WATER RECORDS						
						CASING RECORD
FORMATION (	ONTENT	FROM	то	SIZE	PUT IN	. PULLED OUT
			<u> </u>	8-5/8	545	none
		ļ	ļ	5=11	4299	2268
		<b>_</b>				The second of th
		ame and de	pth plac	ed, from		feet to
Pushed plug to 4100' and sanded 3329', 3258', 2495', 2248', pul	to 4050',	cement to	40081.	Shot pip	e at 3501	f _
Pushed plug to 4100' and sanded	to 4050',	cement to	40081.	Shot nin	e at 3501	f _
Pushed plug to 4100' and sanded 3329', 3258', 2495', 2248', pul 23 sacks gel, plug and 60 sacks	to 4050',	cement to	40081.	Shot nin	e at 3501	f _
Pushed plug to 4100' and sanded 3329', 3258', 2495', 2248', pul	to 4050',	cement to	40081.	Shot nin	e at 3501	f _
Pushed plug to 4100' and sanded 3329', 3258', 2495', 2248', pul 23 sacks gel, plug and 60 sacks	to 4050',	cement to	40081.	Shot nin	e at 3501	f _
Pushed plug to 4100' and sanded 3329', 3258', 2495', 2248', pul 23 sacks gel, plug and 60 sacks	to 4050',	cement to	40081.	Shot nin	e at 3501	cement,
Pushed plug to 4100' and sanded 3329', 3258', 2495', 2248', pul 23 sacks gel, plug and 60 sacks	to 4050',	cement to	40081.	Shot pip	e at 3501 70 sacks	f _
Pushed plug to 4100' and sanded 3329', 3258', 2495', 2248', pul 23 sacks gel, plug and 60 sacks PLUGGING COMPLETE.	to 4050', led 56 jo: cement.	cement to	6 4008'.	Shot pip	e at 3501 70 sacks  Mair REC	cement,
Pushed plug to 4100' and sanded 3329', 3258', 2495', 2248', pul. 23 sacks gel, plug and 60 sacks PLUGGING COMPLETE.  (If additional des	to 4050', led 56 jo cement.	cement to ints. Fump  is necess NG PULLING	0 4008'. oed 3 sa	Shot pip	e at 3501 70 sacks  Mair REC	cement,
Pushed plug to 4100' and sanded 3329', 3258', 2495', 2248', pul. 23 sacks gel, plug and 60 sacks PLUGGING COMPLETE.  (If additional des	to 4050', led 56 jo: cement.	cement to ints. Fump  is necess NG PULLING	0 4008'. oed 3 sa	Shot pip	e at 3501 70 sacks  Mair REC	cement,
Pushed plug to 4100' and sanded 3329', 3258', 2495', 2248', pul 23 sacks gel, plug and 60 sacks PLUGGING COMPLETE.  (If additional des Name of Plugging Contractor Complete Co	to 4050', led 56 jo cement.  scription KELSO CASI HASE, KANS	is necessand Pulling	ary, use	Shot pip	e at 3501 70 sacks  MAIT RECONSTRUCTOR  SEP 1	cement,  2 19 20 10 10 10 10 10 10 10 10 10 10 10 10 10
Pushed plug to 4100' and sanded 3329', 3258', 2495', 2248', pul. 23 sacks gel, plug and 60 sacks  PLUGGING COMPLETE.  (If additional des Name of Plugging Contractor E	to 4050', led 56 jo: cement.  scription KELSO CASI HASE, KANS	is necessation of Pulling	ary, use	Shot pip	e at 3501 70 sacks  MANY RECOMMENTS WEET TO SERVICE WARRY MANY MANY MANY MANY MANY MANY MANY MAN	cement,
Pushed plug to 4100' and sanded 3329', 3258', 2495', 2248', pul 23 sacks gel, plug and 60 sacks PLUGGING COMPLETE.  (If additional des Name of Plugging Contractor Complete Co	to 4050', led 56 jo cement.  scription KELSO CASI HASE, KANS NSAS COUN R. DARREI g first des	is necessand Pulling  TY OF RICLLING  LL KELSO  uly sworn	ary, use	Shot pip cks hulls,  BACK of  ee of own says: T	e at 3501 70 sacks  70 sacks  70 sacks  70 sacks  70 sacks	cement,  2 1970 2 1970 2 1970 2 1970 2 1970 3 1970
Pushed plug to 4100' and sanded 3329', 3258', 2495', 2248', pul. 23 sacks gel, plug and 60 sacks  PLUGGING COMPLETE.  (If additional des Name of Plugging Contractor Complete	to 4050', led 56 jo: cement.  scription KELSO CASI HASE, KANS NSAS COUN R. DARREI g first di s herein due and com	is necessand Pulling  TY OF RICLLING  LL KELSO  uly sworn	ary, use the help me	Shot pip cks hulls,  BACK of  ee of own says: T	e at 3501 70 sacks	cement,  2 1972  1972  1972  1972  1973  ss.  wher or operator e knowledge of escribed well
Pushed plug to 4100' and sanded 3329', 3258', 2495', 2248', pul. 23 sacks gel, plug and 60 sacks  PLUGGING COMPLETE.  (If additional des Name of Plugging Contractor Complete	to 4050', led 56 jo: cement.  scription KELSO CASI HASE, KANS NSAS COUN R. DARREI g first di s herein due and com	is necessand Pulling SAS  TY OF RICAL KEISO uly sworn contained rrect. So	ary, use (employ on oath, and the help me	Shot pip  cks hulls,  BACK of  BACK of  cee of own says: T log of the God.	e at 3501 70 sacks  Og-1  Charles heep  three sheep  er) or (or hat I have e above-de	cement,  2 1979  1979  1979  ss.  where or operator e knowledge of escribed well
Pushed plug to 4100' and sanded 3329', 3258', 2495', 2248', pul. 23 sacks gel, plug and 60 sacks  PLUGGING COMPLETE.  (If additional des Name of Plugging Contractor Complete	to 4050', led 56 jo cement.  scription KELSO CASI HASE, KANS  NSAS COUN R. DARREI g first de s herein ue and co	is necessand Pulling SAS  TY OF RICAL KELSO uly sworn contained rrect. So	ary, use the help me CHAS	Shot pip  cks hulls,  BACK of  BACK of  cee of own says: T log of the God.  SE, KANSAS (A	e at 3501 70 sacks  70 sacks  70 sacks  70 sacks  60 sacks  70 sacks  60 sac	cement,  2999  2999  ss. where or operator e knowledge of escribed well  19 79
Pushed plug to 4100' and sanded 3329', 3258', 2495', 2248', pul. 23 sacks gel, plug and 60 sacks  PLUGGING COMPLETE.  (If additional des Name of Plugging Contractor Gramme of Plugging Contractor Gramme of the above-described well, being the facts, statements, and matters as filed and that the same are transfer of the sa	to 4050', led 56 jo cement.  scription KELSO CASI HASE, KANS  NSAS COUN R. DARREI g first de s herein ue and co	is necessand Pulling SAS  TY OF RICAL KELSO uly sworn contained rrect. So nature)	ary, use the help me CHAS	Shot pip  cks hulls,  BACK of  BACK of  cee of own says: T log of the God.  SE, KANSAS (A	e at 3501 70 sacks  70 sacks  70 sacks  70 sacks  60 sacks  70 sacks  60 sac	cement,  2999  2999  ss. where or operator e knowledge of escribed well  19 79
Pushed plug to 4100' and sanded 3329', 3258', 2495', 2248', pul. 23 sacks gel, plug and 60 sacks  PLUGGING COMPLETE.  (If additional des Name of Plugging Contractor Gramme of Plugging Contractor Gramme of the above-described well, being the facts, statements, and matter as filed and that the same are transfer of the sam	to 4050', led 56 jo cement.  scription KELSO CASI HASE, KANS  NSAS COUN R. DARREI g first de s herein ue and co	is necessand Pulling SAS  TY OF RICULTING CONTAINED TRACE SO THE	ary, use the help me CHAS	Shot pip  cks hulls,  BACK of  BACK of  cee of own says: T log of the God.  SE, KANSAS (A	e at 3501 70 sacks  70 sacks  70 sacks  70 sacks  60 sacks  70 sacks  60 sac	cement,  2 1979 2 1979 3 1979