KANSAS CORPORATION COMMISSION OIL & GAS CONSERVATION DIVISION

WELL PLUGGING APPLICATION

Please TYPE Form and file ONE Copy

Form CP-1 September 2003 This Form must be Typed Form must be Signed All blanks must be Filled

API #15-009-21225-00-00 (Identifier Number of this well).	This must be listed for wells drilled since 1967; if no API # was issued,
Indicate original spud or completion date COMPLETED 1/31/1978	ADV ID 0
WAS BRADEN-DEEM INC. (PLUGGED BY SAMUEL GA Well Operator: ASSOCIATES, INC.) (Owner/Company Name)	KCC License #: 3882 (Operator's)
Address: 1670 BROADWAY, SUITE 3300	City: DENVER
State:	
	Sec. 10 Twp. 16 S. R. 11 East West
NW - SE - SW Spot Location / QQQQ Count	
990 Feet (in exact footage) From North / South (from nea	
1650 Feet (in exact footage) From East / \(\infty \) West (from nea	arest outside section corner) Line of Section (Not Lease Line)
Check Che. Z on von	Water Supply Well
SWD Docket # ENHR Docket #	Other:
Conductor Casing Size: NONE Set at:	Cemented with: Sacks
Surface Casing Size: 8-5/8" Set at: 382'	
Production Casing Size: 5-1/2" Set at: 3360'	Cemented with: 75 Sacks
List (ALL) Perforations and Bridgeplug Sets: FROM BRADEN-DEEM SCOUT C	ARD: OPEN HOLE COMPLETION 3360' - 3370'
1000' El 57 - TD 2270' DETD.	FOT 7002 (NO. E. LOCC BUN)
Elevation: 1889' (G.L. / K.B.) T.D.: 3370' PBTD: A	nhydrite Depth: EST 700' (NO E-LOGS RUN) (Stone Corral Formation)
Condition of Well: Good Poor Casing Leak	nhydrite Depth: EST 700 (NO E-LOGS RUN) (Stone Corral Formation)
	AS DIRECTED BY KCC, Pat Staab MAY 11 2000
Condition of Well: Good Poor Casing Leak	AS DIRECTED BY NOC, Pat Staab May 1
Condition of Well: Good Poor Casing Leak	AS DIRECTED BY NOC, Pat Staab May 1
Condition of Well: Good Poor Casing Leak Proposed Method of Plugging (attach a separate page if additional space is needed): Is Well Log attached to this application as required? Yes No Is ACO-1 filed ASSUME ACO-1 WAS FILED BY ORIGINAL OPERATO	AS DIRECTED BY RCC, Fat Stadb **ACC WICHTA** 17 Yes No OR: BRADEN-DEEM INC; THIS WELL WAS REQUESTED
Condition of Well: Good Poor Casing Leak Proposed Method of Plugging (attach a separate page if additional space is needed): Is Well Log attached to this application as required? Yes No Is ACO-1 filed ASSUME ACO-1 WAS FILED BY ORIGINAL OPERATOR If not explain why? BY THE KCC TO BE PLUGGED BY SAMUEL GARY JR	AS DIRECTED BY RCC, Fat Staab **ACC WICHTA** 17 Yes No DR: BRADEN-DEEM INC; THIS WELL WAS REQUESTED 18 & ASSOCIATES SINCE BRADEN-DEEM REMOVED ALL
Condition of Well: Good Poor Casing Leak Proposed Method of Plugging (attach a separate page if additional space is needed): Is Well Log attached to this application as required? Yes No Is ACO-1 filed ASSUME ACO-1 WAS FILED BY ORIGINAL OPERATO	AS DIRECTED BY RCC, Fat Staab **ACC WICHTA** 17 Yes No DR: BRADEN-DEEM INC; THIS WELL WAS REQUESTED 18 & ASSOCIATES SINCE BRADEN-DEEM REMOVED ALL
Condition of Well: Good Poor Casing Leak Proposed Method of Plugging (attach a separate page if additional space is needed): Is Well Log attached to this application as required? Yes No Is ACO-1 filed ASSUME ACO-1 WAS FILED BY ORIGINAL OPERATO If not explain why? BY THE KCC TO BE PLUGGED BY SAMUEL GARY JEOUR OF THE SURFACE EQUIPMENT BUT NEVER PLUGGED & ABANDO	AS DIRECTED BY RCC, Fat Stady **RCC WICHTA** 17 Yes No OR: BRADEN-DEEM INC; THIS WELL WAS REQUESTED 18 & ASSOCIATES SINCE BRADEN-DEEM REMOVED ALL ONED THE WELL IN 1984. NO E-LOGS WERE RUN BY
Condition of Well: Good Poor Casing Leak Proposed Method of Plugging (attach a separate page if additional space is needed): Is Well Log attached to this application as required? Yes No is ACO-1 filed ASSUME ACO-1 WAS FILED BY ORIGINAL OPERATOR If not explain why? BY THE KCC TO BE PLUGGED BY SAMUEL GARY JE OF THE SURFACE EQUIPMENT BUT NEVER PLUGGED & ABANDO BRADEN-DEEM INC.	AS DIRECTED BY RCC, Fat Stade **RCC WCHTA** 17 Yes No OR: BRADEN-DEEM INC; THIS WELL WAS REQUESTED BY ASSOCIATES SINCE BRADEN-DEEM REMOVED ALL ONED THE WELL IN 1984. NO E-LOGS WERE RUN BY THE Rules and Regulations of the State Corporation Commission.
Condition of Well: Good Poor Casing Leak Proposed Method of Plugging (attach a separate page if additional space is needed): Is Well Log attached to this application as required? Yes No Is ACO-1 filed ASSUME ACO-1 WAS FILED BY ORIGINAL OPERATO If not explain why? BY THE KCC TO BE PLUGGED BY SAMUEL GABY JE OF THE SURFACE EQUIPMENT BUT NEVER PLUGGED & ABANDO BRADEN-DEEM INC. Plugging of this Well will be done in accordance with K.S.A. 55-101 et. Seq. and the	AS DIRECTED BY RCC, Fat Stade **RCC WCHTA** 17 Yes No OR: BRADEN-DEEM INC; THIS WELL WAS REQUESTED BY ASSOCIATES SINCE BRADEN-DEEM REMOVED ALL ONED THE WELL IN 1984. NO E-LOGS WERE RUN BY THE Rules and Regulations of the State Corporation Commission.
Condition of Well: Good Poor Casing Leak Proposed Method of Plugging (attach a separate page if additional space is needed): Is Well Log attached to this application as required? Yes No Is ACO-1 filed ASSUME ACO-1 WAS FILED BY ORIGINAL OPERATO If not explain why? BY THE KCC TO BE PLUGGED BY SAMUEL GABY JE OF THE SURFACE EQUIPMENT BUT NEVER PLUGGED & ABANDO BRADEN-DEEM INC. Plugging of this Well will be done in accordance with K.S.A. 55-101 et. Seq. and the	AS DIRECTED BY RCC, Fat Stady **RCC WCHTA** 1? Yes No OR: BRADEN-DEEM INC; THIS WELL WAS REQUESTED BL& ASSOCIATES SINCE BRADEN-DEEM REMOVED ALL ONED THE WELL IN 1984. NO E-LOGS WERE RUN BY THE Rules and Regulations of the State Corporation Commission. SE KEVIN WILSON
Condition of Well: Good Poor Casing Leak Proposed Method of Plugging (attach a separate page if additional space is needed): Is Well Log attached to this application as required? Yes No is ACO-1 filed ASSUME ACO-1 WAS FILED BY ORIGINAL OPERATOR If not explain why? BY THE KCC TO BE PLUGGED BY SAMUEL GARY JES OF THE SURFACE EQUIPMENT BUT NEVER PLUGGED & ABANDO BRADEN-DEEM INC. Plugging of this Well will be done in accordance with K.S.A. 55-101 et. Seq. and the List Name of Company Representative authorized to be in charge of plugging operations. Address: 562 WEST HIGHWAY 4 Plugging Contractor: EXPRESS WELL SERVICE	AS DIRECTED BY RCC, Fat Stady **RCC WICHTA** 17 Yes No DR: BRADEN-DEEM INC; THIS WELL WAS REQUESTED 18 ASSOCIATES SINCE BRADEN-DEEM REMOVED ALL DNED THE WELL IN 1984. NO E-LOGS WERE RUN BY 19 BRUIES and Regulations of the State Corporation Commission. 19 KEVIN WILSON 19 Phone: (620) 617-6880
Condition of Well: Good Poor Casing Leak Proposed Method of Plugging (attach a separate page if additional space is needed): Is Well Log attached to this application as required? Yes No Is ACO-1 filed ASSUME ACO-1 WAS FILED BY ORIGINAL OPERATOR If not explain why? BY THE KCC TO BE PLUGGED BY SAMUEL GARY JES OF THE SURFACE EQUIPMENT BUT NEVER PLUGGED & ABANDO BRADEN-DEEM INC. Plugging of this Well will be done in accordance with K.S.A. 55-101 et. Seq. and the List Name of Company Representative authorized to be in charge of plugging operations. Address: 562 WEST HIGHWAY 4	AS DIRECTED BY RCC, Fat Stady **CC WCHTA** 17 Yes No DR: BRADEN-DEEM INC; THIS WELL WAS REQUESTED B: ASSOCIATES SINCE BRADEN-DEEM REMOVED ALL DNED THE WELL IN 1984. NO E-LOGS WERE RUN BY THE Rules and Regulations of the State Corporation Commission. SE
Condition of Well: Good Poor Casing Leak Proposed Method of Plugging (attach a separate page if additional space is needed): Is Well Log attached to this application as required? Yes No is ACO-1 filed ASSUME ACO-1 WAS FILED BY ORIGINAL OPERATOR If not explain why? BY THE KCC TO BE PLUGGED BY SAMUEL GARY JEST OF THE SURFACE EQUIPMENT BUT NEVER PLUGGED & ABANDO BRADEN-DEEM INC. Plugging of this Well will be done in accordance with K.S.A. 55-101 et. Seq. and the List Name of Company Representative authorized to be in charge of plugging operations. Address: 562 WEST HIGHWAY 4 Plugging Contractor: EXPRESS WELL SERVICE (Company Name)	AS DIRECTED BY RCC, Fat Stady **CC WCHTA** 17 Yes No DR: BRADEN-DEEM INC; THIS WELL WAS REQUESTED BY ASSOCIATES SINCE BRADEN-DEEM REMOVED ALL DNED THE WELL IN 1984. NO E-LOGS WERE RUN BY 18 Rules and Regulations of the State Corporation Commission. 18 KEVIN WILSON Phone: (620) 617-6880 City / State: OLMITZ, KS 67564 KCC License #: 6426
Condition of Well: Good Poor Casing Leak Proposed Method of Plugging (attach a separate page if additional space is needed): Is Well Log attached to this application as required? Yes No Is ACO-1 filed ASSUME ACO-1 WAS FILED BY ORIGINAL OPERATO If not explain why? BY THE KCC TO BE PI UGGED BY SAMUEL GARY JE OF THE SURFACE EQUIPMENT BUT NEVER PLUGGED & ABANDO BRADEN-DEEM INC. Plugging of this Well will be done in accordance with K.S.A. 55-101 et. Seq. and the List Name of Company Representative authorized to be in charge of plugging operations Address: 562 WEST HIGHWAY 4 Plugging Contractor: EXPRESS WELL SERVICE (Company Name) Address: P O BOX 19, VICTORIA, KS 67671 Proposed Date and Hour of Plugging (if known?): 1 PM APRIL 21, 2006 Payment of the Plugging Fee (K.A.R. 82-3-118) will be guaranteed by Operator or Page 12.	AS DIRECTED BY RCC, Fat Stady **RCC WCHTA** 17 Yes No OR: BRADEN-DEEM INC; THIS WELL WAS REQUESTED 18 ASSOCIATES SINCE BRADEN-DEEM REMOVED ALL ONED THE WELL IN 1984. NO E-LOGS WERE RUN BY 19 Rules and Regulations of the State Corporation Commission. 19 State:

Mail to: KCC - Conservation Division, 130 S. Market - Room 2078, Wichita, Kansas 67202

He Well already plugged 194/21/06- 50

D157.06