KANSAS CORPORATION COMMISSION OIL & GAS CONSERVATION DIVISION

WELL PLUGGING APPLICATION

Please TYPE Form and File ONE Copy

Form CP-1 September 2003 This Form must be Typed Form must be Signed All blanks must be Filled

Well Operator: KENNETH S. WHITE		KCC License #:_3	0128
Address: 2400 N. Woodlawn, Suite 115	/Company Name)	Roo Electriss # City:_Wichita	(Operator's)
	Zin Code: 67220	Contact Phone:(316)	682 - 6300
_{Lease:} Zink		Sec. 4	4.4
NW - SE - SEspc		nty: Pratt	S. R. 11 East V West
990 Feet (in exact footage) From			
990 Feet (in exact footage) From	-	rest outside section corner) Line of strest outside section corner) Line of stress of stress contents.	•
Check One: V Oil Well Gas Well	D&A Cathodic	Water Supply Well	
SWD Docket #	ENHR Docket #		ther:
Conductor Casing Size:	Set at:	Cemented with:	Sacks
Surface Casing Size: 10-3/4"	Set at: _255	Cemented with: 22	5Sacks
Production Casing Size: 5-1/2"	Set at: 4166	Cemented with: _17	5 Sacks
List (ALL) Perforations and Bridgeplug Sets: 4010-4			
	•		
Elevation: 1840 (G.L. / K.B.) T.D.: 4170 Condition of Well: Good Poor Proposed Method of Plugging (attach a separate page if a casing for recovery, pull casing and plug @	Casing Leak J	_{unk in Hole} with sand to 3900' and dum	· · · · · · · · · · · · · · · · · · ·
			RECEIVED
•	Yes V No Is ACO-1 file	d? Ves No	RECEIVED MAR 0 2 2006
Is Well Log attached to this application as required? If not explain why? Sent in when well drilled	Yes V No Is ACO-1 file	d? 🗸 Yes 🗌 No	MAR 0 2 2006
If not explain why? Sent in when well drilled			MAR 0 2 2006 KCC WICHITA
If not explain why? Sent in when well drilled Plugging of this Well will be done in accordance with	h K.S.A. 55-101 <u>et, seq</u> . and the	Rules and Regulations of the S	MAR 0 2 2006 KCC WICHITA
If not explain why? Sent in when well drilled	h K.S.A. 55-101 <u>et, seq</u> . and the	Rules and Regulations of the S	MAR 0 2 2006 KCC WICHITA tate Corporation Commission.
Plugging of this Well will be done in accordance with List Name of Company Representative authorized to be Herb Durant	h K.S.A. 55-101 <u>et, seq</u> . and the	Rules and Regulations of the S ns:Phone: (620) 886	MAR 0 2 2006 KCC WICHITA tate Corporation Commission. - 5463
If not explain why? Sent in when well drilled Plugging of this Well will be done in accordance with List Name of Company Representative authorized to be Herb Durant Address: P.O. Box 251	h K.S.A. 55-101 <u>et.</u> <u>seq</u>. and the e in charge of plugging operatio	Phone: (620) 886 City / State: Medicine Loc	MAR 0 2 2006 KCC WICHITA tate Corporation Commission. - 5463
If not explain why? Sent in when well drilled Plugging of this Well will be done in accordance with List Name of Company Representative authorized to be Herb Durant Address: P.O. Box 251 Plugging Contractor: Mike's Testing & Salvage,	h K.S.A. 55-101 <u>et.</u> <u>seq</u>. and the e in charge of plugging operatio	Phone: (620) 886 City / State: Medicine Loc KCC License #: 31529	MAR 0 2 2006 KCC WICHITA tate Corporation Commission. - 5463 dge KS 67104 (Contractor's)
If not explain why? Sent in when well drilled Plugging of this Well will be done in accordance with List Name of Company Representative authorized to be Herb Durant Address: P.O. Box 251 Plugging Contractor: Mike's Testing & Salvage, (Compand Address: P.O. Box 467, Chase KS 67524	h K.S.A. 55-101 et, seq. and the e in charge of plugging operation in charge of plugging opera	Phone: (620) 938 City / State: Medicine Loc KCC License #: 31529	MAR 0 2 2006 KCC WICHITA tate Corporation Commission. - 5463 dge KS 67104
If not explain why? Sent in when well drilled Plugging of this Well will be done in accordance with List Name of Company Representative authorized to be Herb Durant Address: P.O. Box 251 Plugging Contractor: Mike's Testing & Salvage,	h K.S.A. 55-101 et, seq. and the e in charge of plugging operation $Inc.$ $Inc.$ $Ing Name = 2.30 $	Phone: (620) 886 City / State: Medicine Loc KCC License #: 31529 Phone: (620) 938	MAR 0 2 2006 KCC WICHITA tate Corporation Commission. - 5463 dge KS 67104 (Contractor's)

* Well already plugged-Dig.