5-19 4-<u>061077</u>

TO:	API Number: 15-141-20,336 -00-0
STATE CORPORATION COMMISSION	
CONSERVATION DIVISION - PLUGGING	SE SE NE /4 SEC. 25 , 08 S, 12
130 SOUTH MARKET, SUITE 2078	2970 feet from S section lin
WICHITA, KANSAS 67202	feet from E section lin
Operator license# <u>3956</u>	Lease <u>Louise Bader</u> Well # <u> </u>
Operator: Brungardt Oil & Leasing	County: Osborne 105
Address: Box 871	Well total depth3250
Russell, Kansas 67665	Conductor Pipe: 0 inch @ 0
	Surface pipe 8 5/8 Inch @ 206
Aband. oil well, Gas well, Input we	ell, SWD, D & A_X_
Plugging contractor: Shields Oil Produce	License# 5184
Address: Russell, Kansas 67665	· · · · · · · · · · · · · · · · · · ·
Company to plug at: Hour: 2:00 A.M. Day:	19 Month: May Year: 1997
Plugging proposal received from:	
Company:	Phone:
	l with 1/4# floseal per sack.
Were: <u>Order 150 sxs 60/40 posmix - 6% g</u> e	l with 1/4# floseal per sack.
Were: Order 150 sxs 60/40 posmix - 6% ge Space all plugs with heavy drilling	l with 1/4# floseal per sack. mud through drill pipe.
Were: Order 150 sxs 60/40 posmix - 6% ge Space all plugs with heavy drilling	with 1/4# floseal per sack. mud through drill pipe.
Nere: Order 150 sxs 60/40 posmix - 6% ge Space all plugs with heavy drilling Plugging Proposal Received by: Herb Deine Plugging operations attended by agent? All	with 1/4# floseal per sack. mud through drill pipe. ss [], Part[], None[X]
Were: Order 150 sxs 60/40 posmix - 6% get Space all plugs with heavy drilling Plugging Proposal Received by: Herb Deine Plugging operations attended by agent? All Completed: Hour: 4:30 A.M. , Day: 19, Mo	with 1/4# floseal per sack. mud through drill pipe. ss [], Part[], None[X]
Were: Order 150 sxs 60/40 posmix - 6% ge Space all plugs with heavy drilling Plugging Proposal Received by: Herb Deine Plugging operations attended by agent? All Completed: Hour: 4:30 A.M. , Day: 19, Mo	with 1/4# floseal per sack. mud through drill pipe. ss [], Part[], None[x] nth: May , Year: 1997
Were: Order 150 sxs 60/40 posmix - 6% ge Space all plugs with heavy drilling Plugging Proposal Received by: Herb Deine Plugging operations attended by agent? All Completed: Hour: 4:30 A.M. , Day: 19, Mo Actual plugging report: Lst. Plug at 810' w/25 sxs. Anhydrite 79	with 1/4# floseal per sack. mud through drill pipe. ss [], Part[], None[X] nth: May , Year: 1997
Were: Order 150 sxs 60/40 posmix - 6% get Space all plugs with heavy drilling Plugging Proposal Received by: Herb Deine Plugging operations attended by agent? All Completed: Hour: 4:30 A.M., Day: 19, McActual plugging report: 1st. Plug at 810' w/25 sxs. Anhydrite 79 2nd. Plug at 635' w/90 sxs. Dakota 331'	with 1/4# floseal per sack. mud through drill pipe. ss [], Part[], None[X] onth: May , Year: 1997.
Nere: Order 150 sxs 60/40 posmix - 6% get Space all plugs with heavy drilling Plugging Proposal Received by: Herb Deine Plugging operations attended by agent? All Completed: Hour: 4:30 A.M., Day: 19, McActual plugging report: Lst. Plug at 810' w/25 sxs. Anhydrite 79 2nd. Plug at 635' w/90 sxs. Dakota 331' - 3rd. Plug at 40' w/10 sxs. Surface pipe	with 1/4# floseal per sack. mud through drill pipe. [], Part[], None[X] mth: May , Year: 1997. 0' - 823'. 631'. 206'.
Plugging Proposal Received by: Herb Deine Plugging operations attended by agent? All Completed: Hour: 4:30 A.M., Day: 19, McActual plugging report: Lst. Plug at 810' w/25 sxs. Anhydrite 79 2nd. Plug at 635' w/90 sxs. Dakota 331' - 3rd. Plug at 40' w/10 sxs. Surface pipe 15 sxs in rathole.	with 1/4# floseal per sack. mud through drill pipe. [], Part[], None[X] mth: May , Year: 1997. 0' - 823'. 631'. 206'.
Were: Order 150 sxs 60/40 posmix - 6% get Space all plugs with heavy drilling Plugging Proposal Received by: Herb Deine Plugging operations attended by agent? All Completed: Hour: 4:30 A.M. , Day: 19, Mc Actual plugging report: 1st. Plug at 810' w/25 sxs. Anhydrite 79 2nd. Plug at 635' w/90 sxs. Dakota 331' - 3rd. Plug at 40' w/10 sxs. Surface pipe 15 sxs in rathole.	with 1/4# floseal per sack. mud through drill pipe. [], Part[], None[X] mth: May , Year: 1997. 0' - 823'. 631'. 206'.
Nere: Order 150 sxs 60/40 posmix - 6% ges Space all plugs with heavy drilling Plugging Proposal Received by: Herb Deine Plugging operations attended by agent? All Completed: Hour: 4:30 A.M. , Day: 19, Mo Actual plugging report: Lst. Plug at 810' w/25 sxs. Anhydrite 79 2nd. Plug at 635' w/90 sxs. Dakota 331' - Brd. Plug at 40' w/10 sxs. Surface pipe L5 sxs in rathole.	with 1/4# floseal per sack. mud through drill pipe. [], Part[], None[X] mth: May , Year: 1997. 0' - 823'. 631'. 206'.
Were: Order 150 sxs 60/40 posmix - 6% get Space all plugs with heavy drilling Plugging Proposal Received by: Herb Deine Plugging operations attended by agent? All Completed: Hour: 4:30 A.M., Day: 19, Mc Actual plugging report: 1st. Plug at 810' w/25 sxs. Anhydrite 79 2nd. Plug at 635' w/90 sxs. Dakota 331' - 3rd. Plug at 40' w/10 sxs. Surface pipe 15 sxs in rathole. 10 sxs in mousehole	with 1/4# floseal per sack. mud through drill pipe. [], Part[], None[X] mth: May , Year: 1997. 0' - 823'. 631'. 206'.
Were: Order 150 sxs 60/40 posmix - 6% get Space all plugs with heavy drilling Plugging Proposal Received by: Herb Deine Plugging operations attended by agent? All Completed: Hour: 4:30 A.M., Day: 19, Mc Actual plugging report: 1st. Plug at 810' w/25 sxs. Anhydrite 79 2nd. Plug at 635' w/90 sxs. Dakota 331' - 3rd. Plug at 40' w/10 sxs. Surface pipe 15 sxs in rathole. 10 sxs in mousehole Remarks: Allied Cementing.	with 1/4# floseal per sack. mud through drill pipe. ss [], Part[], None[X] onth: May , Year: 1997. O' - 823'. 631'. 206'.
Were: Order 150 sxs 60/40 posmix - 6% gestions all plugs with heavy drilling Plugging Proposal Received by: Herb Deine Plugging operations attended by agent? All Completed: Hour: 4:30 A.M., Day: 19, Mo Actual plugging report: 1st. Plug at 810' w/25 sxs. Anhydrite 79 2nd. Plug at 635' w/90 sxs. Dakota 331'- 3rd. Plug at 40' w/10 sxs. Surface pipe 15 sxs in rathole. 10 sxs in mousehole Remarks: Allied Cementing. Condition of casing(in hole): GOOD X BAD	with 1/4# floseal per sack. mud through drill pipe. ss [], Part[], None[X] nth: May , Year: 1997
Were: Order 150 sxs 60/40 posmix - 6% gestions all plugs with heavy drilling Plugging Proposal Received by: Herb Deine Plugging operations attended by agent? All Completed: Hour: 4:30 A.M., Day: 19, Mo Actual plugging report: 1st. Plug at 810' w/25 sxs. Anhydrite 79 2nd. Plug at 635' w/90 sxs. Dakota 331' - 3rd. Plug at 40' w/10 sxs. Surface pipe 15 sxs in rathole. 10 sxs in mousehole Remarks: Allied Cementing. Condition of casing(in hole): GOOD X BAD Bottom plug(in place): YES_, CALC_, NO X	with 1/4# floseal per sack. mud through drill pipe. [], Part[], None[X] nth: May , Year: 1997
Were: Order 150 sxs 60/40 posmix - 6% gestions all plugs with heavy drilling Plugging Proposal Received by: Herb Deine Plugging operations attended by agent? All Completed: Hour: 4:30 A.M., Day: 19, Mo Actual plugging report: 1st. Plug at 810' w/25 sxs. Anhydrite 79 2nd. Plug at 635' w/90 sxs. Dakota 331' - 3rd. Plug at 40' w/10 sxs. Surface pipe 15 sxs in rathole. 10 sxs in mousehole Remarks: Allied Cementing. Condition of casing(in hole): GOOD X BAD Bottom plug(in place): YES_, CALC_, NO X	with 1/4# floseal per sack. mud through drill pipe. [], Part[], None[X] nth: May , Year: 1997
Were: Order 150 sxs 60/40 posmix - 6% ge Space all plugs with heavy drilling Plugging Proposal Received by: Herb Deine Plugging operations attended by agent? All Completed: Hour: 4:30 A.M., Day: 19, Mo Actual plugging report: 1st. Plug at 810' w/25 sxs. Anhydrite 79 2nd. Plug at 635' w/90 sxs. Dakota 331' - 3rd. Plug at 635' w/90 sxs. Surface pipe 15 sxs in rathole. 10 sxs in mousehole Remarks: Allied Cementing. Condition of casing(in hole): GOOD X BAD Bottom plug(in place): YES, CALC, NO_X Plugged through VBING, CASING	I with 1/4# floseal per sack. mud through drill pipe. [], Part[], None[X] nth: May , Year: 1997 O' - 823'. 631'. 206'. Anhy.plug: YES X NO Dakota plug: YES X , NO Elevation: 1681
Were: Order 150 sxs 60/40 posmix - 6% ge Space all plugs with heavy drilling Plugging Proposal Received by: Herb Deine Plugging operations attended by agent? All Completed: Hour: 4:30 A.M. , Day: 19, Mo Actual plugging report: 1st. Plug at 810' w/25 sxs. Anhydrite 79 2nd. Plug at 635' w/90 sxs. Dakota 331'- 3rd. Plug at 40' w/10 sxs. Surface pipe 15 sxs in rathole. 10 sxs in mousehole Remarks: Allied Cementing. Condition of casing(in hole): GOOD X BAD Bottom plug(in place): YES, CALC, NO_X Plugged through TUBING, CASING	and through drill pipe. Is selected by the sack. In much through drill pipe. Is selected by the sack. In much through drill pipe. Is selected by the sack. In much through drill pipe. Is selected by the sack. Is selecte
Were: Order 150 sxs 60/40 posmix - 6% ge Space all plugs with heavy drilling Plugging Proposal Received by: Herb Deine Plugging operations attended by agent? All Completed: Hour: 4:30 A.M., Day: 19, Mo Actual plugging report: 1st. Plug at 810' w/25 sxs. Anhydrite 79 2nd. Plug at 635' w/90 sxs. Dakota 331' - 3rd. Plug at 40' w/10 sxs. Surface pipe 15 sxs in rathole. 10 sxs in mousehole Remarks: Allied Cementing. Condition of casing(in hole): GOOD X BAD Bottom plug(in place): YES, CALC, NO_X Plugged through VBING, CASING	I with 1/4# floseal per sack. mud through drill pipe. [], Part[], None[X] nth: May , Year: 1997 O' - 823'. 631'. 206'. Anhy.plug: YES X NO Dakota plug: YES X , NO Elevation: 1681