## KANSAS CORPORATION COMMISSION OIL & GAS CONSERVATION DIVISION

## **WELL PLUGGING APPLICATION**

Please TYPE Form and File ONE Copy

Form CP-1 September 2003 This Form must be Typed Form must be Signed All blanks must be Filled

API # 15 - 055 00163 -00-00	RECEIVED (Identifie KANSAS CORPORATION TO STATE WELLS drilled since 1967; if no API # was issued
Indicate original spud or completion date 11/26/5	58 AUG 3 0 2006
Well Operator: CHESAPEAKE OPERAT	TING ING
Address: P. O. BOX 18496	Owner/Company Name)  CONSERVATION DIVISOR LAHOMA CITY  (Operator's)  WICHITA, KGIY: OKLAHOMA CITY
Stale: OK	Zip Code: 73154-0496 Contact Phone: (405 ) 848 - 8000
C NIT	Spot Location / QQQQ County: FINNEY
1320 Feet (in exact footage) From	North / South (from nearest outside section corner) Line of Section (Not Lease Line)
Feet (in exact footage) From	East / West (from nearest outside section corner) Line of Section (Not Lease Line)
Check One: Oil Well Gas Well	D&A Cathodic Water Supply Well
SWD Docket #	ENHR Docket # Other:
Conductor Casing Size:	Set at: Cemented with; Sacks
Surface Casing Size: 8-5/8	Set at: 3731 Cemented with: 200 Sacks
Production Casing Size: 5-1/2	Set at: 2750
List (ALL) Perforations and Bridgepiug Sets: 266	
Elevation: 2894 ([G.L./ K.B.J T.D.: 27	50 PBTD: Anhydrite Depth:
	(Slone Corral Formation)
Condition of Well:  Good Poor	Casing Leak   Junk in Hole
Proposed Method of Plugging (attach a separate pag	ge if additional space is needed): MIRU Wireline, set CIBP @1000', POOH, MIRU pump truck, load & test csg to 300 psig.
Proposed Method of Plugging (attach a separate page RIH, perf as close to CIBP as possible, POOH. M	ge if additional space is needed): MIRU Wireline, set CIBP @1000', POOH, MIRU pump truck, load & test csg to 300 psig.  MIRU cementers, dig out bradenhead, EIR down 5-1/2", pump 210 sx 60/40 Poz w/6% gel down 5-1/2" csg.,
Proposed Method of Plugging (attach a separate pag RIH, perf as close to CIBP as possible, POOH. M Tie onto 5-1/2"x8-5/8" annulus, attempt to esta	ge if additional space is needed): MIRU Wireline, set CIBP @1000', POOH, MIRU pump truck, load & test csg to 300 psig.  MIRU cementers, dig out bradenhead, EIR down 5-1/2", pump 210 sx 60/40 Poz w/6% gel down 5-1/2" csg., ablish pump in & if able to pump into annulus, pump 150 sx cmt. RDMO. Weld on cap, clean location.
Proposed Method of Plugging (attach a separate page RIH, perf as close to CIBP as possible, POOH. M Tie onto 5-1/2"x8-5/8" annulus, attempt to esta	ge if additional space is needed):  MIRU Wireline, set CIBP @1000', POOH, MIRU pump truck, load & test csg to 300 psig.  MIRU cementers, dig out bradenhead, EIR down 5-1/2", pump 210 sx 60/40 Poz w/6% gel down 5-1/2" csg., ablish pump in & if able to pump into annulus, pump 150 sx cmt. RDMO. Weld on cap, clean location.
Proposed Method of Plugging (attach a separate pag RIH, perf as close to CIBP as possible, POOH. M Tie onto 5-1/2"x8-5/8" annulus, attempt to esta	ge if additional space is needed): MIRU Wireline, set CIBP @1000', POOH, MIRU pump truck, load & test csg to 300 psig.  MIRU cementers, dig out bradenhead, EIR down 5-1/2", pump 210 sx 60/40 Poz w/6% gel down 5-1/2" csg., ablish pump in & if able to pump into annulus, pump 150 sx cmt. RDMO. Weld on cap, clean location.
Proposed Method of Plugging (attach a separate page RIH, perf as close to CIBP as possible, POOH. M Tie onto 5-1/2"x8-5/8" annulus, attempt to estate the Well Log attached to this application as required? If not explain why?	ge if additional space is needed):  MIRU Wireline, set CIBP @1000', POOH, MIRU pump truck, load & test csg to 300 psig.  MIRU cementers, dig out bradenhead, EIR down 5-1/2", pump 210 sx 60/40 Poz w/6% gel down 5-1/2" csg., ablish pump in & if able to pump into annulus, pump 150 sx cmt. RDMO. Weld on cap, clean location.  Yes No Is ACO-1 filed? Yes No
Proposed Method of Plugging (attach a separate page RIH, perf as close to CIBP as possible, POOH. M Tie onto 5-1/2"x8-5/8" annulus, attempt to estate the Well Log attached to this application as required? If not explain why?	ge if additional space is needed): MIRU Wireline, set CIBP @1000', POOH, MIRU pump truck, load & test csg to 300 psig.  MIRU cementers, dig out bradenhead, EIR down 5-1/2", pump 210 sx 60/40 Poz w/6% gel down 5-1/2" csg., ablish pump in & if able to pump into annulus, pump 150 sx cmt. RDMO. Weld on cap, clean location.
Proposed Method of Plugging (attach a separate page RIH, perf as close to CIBP as possible, POOH. M Tie onto 5-1/2"x8-5/8" annulus, attempt to estate Is Well Log attached to this application as required? If not explain why?  Plugging of this Well will be done in accordance List Name of Company Representative authorized	ge if additional space is needed): MIRU Wireline, set CIBP @1000', POOH, MIRU pump truck, load & test csg to 300 psig.  AIRU cementers, dig out bradenhead, EIR down 5-1/2", pump 210 sx 60/40 Poz w/6% gel down 5-1/2" csg., ablish pump in & if able to pump into annulus, pump 150 sx cmt. RDMO. Weld on cap, clean location.  Pyes V No is ACO-1 filed? Yes No
Proposed Method of Plugging (attach a separate page RIH, perf as close to CIBP as possible, POOH. M Tie onto 5-1/2"x8-5/8" annulus, attempt to estate Well Log attached to this application as required?  If not explain why?  Plugging of this Well will be done in accordance	ge if additional space is needed): MIRU Wireline, set CIBP @1000', POOH, MIRU pump truck, load & test csg to 300 psig.  AIRU cementers, dig out bradenhead, EIR down 5-1/2", pump 210 sx 60/40 Poz w/6% gel down 5-1/2" csg., ablish pump in & if able to pump into annulus, pump 150 sx cmt. RDMO. Weld on cap, clean location.  Pyes V No is ACO-1 filed? Yes No
Proposed Method of Plugging (attach a separate page RIH, perf as close to CIBP as possible, POOH. M Tie onto 5-1/2"x8-5/8" annulus, attempt to estate Is Well Log attached to this application as required? If not explain why?  Plugging of this Well will be done in accordance List Name of Company Representative authorized	ge if additional space is needed):  MIRU Wireline, set CIBP @1000', POOH, MIRU pump truck, load & test csg to 300 psig.  MIRU cementers, dig out bradenhead, EIR down 5-1/2", pump 210 sx 60/40 Poz w/6% get down 5-1/2" csg., ablish pump in & if able to pump into annulus, pump 150 sx cmt. RDMO. Weld on cap, clean location.  Per Yes No is ACO-1 filed? Yes No  With K.S.A. 55-101 et. seq. and the Rules and Regulations of the State Corporation Commission.  To be in charge of plugging operations:  Phone: (620 ) 277 - 0803
Proposed Method of Plugging (attach a separate page RIH, perf as close to CIBP as possible, POOH. M Tie onto 5-1/2"x8-5/8" annulus, attempt to estate Is Well Log attached to this application as required? If not explain why?  Plugging of this Well will be done in accordance List Name of Company Representative authorized Bud Neff  Address: 4532 W. Jones Avenue  Plugging Contractor: Allied Cementing Co.,	ge if additional space is needed): MIRU Wireline, set CIBP @1000', POOH, MIRU pump truck, load & test csg to 300 psig.  MIRU cementers, dig out bradenhead, EIR down 5-1/2", pump 210 sx 60/40 Poz w/6% gel down 5-1/2" csg., ablish pump in & if able to pump into annulus, pump 150 sx cmt. RDMO. Weld on cap, clean location.  Pe with K.S.A. 55-101 et. seq. and the Rules and Regulations of the State Corporation Commission.  To be in charge of plugging operations:  Phone: (620 ) 277 - 0803  City / State: Garden City, KS 67846  Inc.
Proposed Method of Plugging (attach a separate page RIH, perf as close to CIBP as possible, POOH. M Tie onto 5-1/2"x8-5/8" annulus, attempt to estate Is Well Log attached to this application as required? If not explain why?  Plugging of this Well will be done in accordance List Name of Company Representative authorized Bud Neff  Address: 4532 W. Jones Avenue  Plugging Contractor: Allied Cementing Co.,	ge if additional space is needed): MIRU Wireline, set CIBP @1000', POOH, MIRU pump truck, load & test csg to 300 psig.  MIRU cementers, dig out bradenhead, EIR down 5-1/2", pump 210 sx 60/40 Poz w/6% get down 5-1/2" csg., ablish pump in & if able to pump into annulus, pump 150 sx cmt. RDMO. Weld on cap, clean location.  Pe with K.S.A. 55-101 et. seq. and the Rules and Regulations of the State Corporation Commission.  To be in charge of plugging operations:  Phone: (620) 277 - 0803  City / State: Garden City, KS 67846  Inc.  Company Name)
Proposed Method of Plugging (attach a separate page RIH, perf as close to CIBP as possible, POOH. M Tie onto 5-1/2"x8-5/8" annulus, attempt to estate Is Well Log attached to this application as required? If not explain why?  Plugging of this Well will be done in accordance List Name of Company Representative authorized Bud Neff  Address: 4532 W. Jones Avenue  Plugging Contractor: Allied Cementing Co.,	ge if additional space is needed): MIRU Wireline, set CIBP @1000', POOH, MIRU pump truck, load & test csg to 300 psig.  MIRU cementers, dig out bradenhead, EIR down 5-1/2", pump 210 sx 60/40 Poz w/6% get down 5-1/2" csg., ablish pump in & if able to pump into annulus, pump 150 sx cmt. RDMO. Weld on cap, clean location.  Pyes No Is ACO-1 filed? Pyes No  with K.S.A. 55-101 et, seq. and the Rules and Regulations of the State Corporation Commission.  to be in charge of plugging operations:  Phone: (620) 277 - 0803  City / State: Garden City, KS 67846  Inc.  Company Name)  Contractor's)  Phone: (100) Contractor's)
Proposed Method of Plugging (attach a separate page RIH, perf as close to CIBP as possible, POOH. M Tie onto 5-1/2"x8-5/8" annulus, attempt to estate Is Well Log attached to this application as required? If not explain why?  Plugging of this Well will be done in accordance List Name of Company Representative authorized Bud Neff  Address: 4532 W. Jones Avenue  Plugging Contractor: Allied Cementing Co., Address: P. O. Box 31, Rusself, KS 6766.	MIRU Wireline, set CIBP @1000', POOH, MIRU pump truck, load & test csg to 300 psig.  MIRU cementers, dig out bradenhead, EIR down 5-1/2", pump 210 sx 60/40 Poz w/6% gel down 5-1/2" csg., ablish pump in & if able to pump into annulus, pump 150 sx cmt. RDMO. Weld on cap, clean location.  Pyes No Is ACO-1 filed? Yes No  with K.S.A. 55-101 et, seq. and the Rules and Regulations of the State Corporation Commission.  to be in charge of plugging operations:  Phone: (620) 277 - 0803  City / State: Garden City, KS 67846  Inc.  Company Name)  Phone: (7) - (1000)  Contractor's)  Phone: (800) - (1000)  Contractor's)
Proposed Method of Plugging (attach a separate page RIH, perf as close to CIBP as possible, POOH. M Tie onto 5-1/2"x8-5/8" annulus, attempt to estate Is Well Log attached to this application as required? If not explain why?  Plugging of this Well will be done in accordance List Name of Company Representative authorized Bud Neff  Address: 4532 W. Jones Avenue  Plugging Contractor: Allied Cementing Co., (Address: P. O. Box 31, Rusself, KS 6766.)  Proposed Date and Hour of Plugging (if known?):	ge if additional space is needed): MIRU Wireline, set CIBP @1000', POOH, MIRU pump truck, load & test csg to 300 psig.  MIRU cementers, dig out bradenhead, EIR down 5-1/2", pump 210 sx 60/40 Poz w/6% gel down 5-1/2" csg., ablish pump in & if able to pump into annulus, pump 150 sx cmt. RDMO. Weld on cap, clean location.  Pyes V No is ACO-1 filed? Vyes No  with K.S.A. 55-101 et, seq. and the Rules and Regulations of the State Corporation Commission.  Phone: (620) 277 - 0803  City / State: Garden City, KS 67846  Inc.  Company Name)  Phone: (Contractor's)  Phone: (Contractor's)

vision, 130 S. Market - Room 2078, Wichita, Kansas 67202
FOR Jim Reisch, Asset Manage

CORPORATION COMMISSION

Kathleen Sebelius, Governor

Brian J. Moline, Chair

Robert E. Krehbiel, Commissioner

Michael C. Moffet, Commissioner

## NOTICE OF RECEIPT OF WELL PLUGGING APPLICATION (CP-1)

Chesapeake Operating, Inc. PO Box 18496 6200 N Western Ave. Oklahoma City, OK 73154-0496

September 01, 2006

Re: J E GREATHOUSE #1-32 API 15-055-00163-00-00 NE 32-21S-32W, 1320 FNL 1320 FEL

FINNEY COUNTY, KANSAS

## Dear Operator:

This letter is to notify you that the Conservation Division is in receipt of your plugging proposal, form CP-1, for the above-captioned well.

Your CP-1 has been reviewed by the Conservation Division central office for completeness and to verify license numbers. The plugging proposal will now be forwarded to the district office listed below for review of your proposed method of plugging.

Please contact the district office for approval of your proposed plugging method at least five (5) days before plugging the well, pursuant to K.A.R. 82-3-113 (b). If a workover pit will be used during the plugging of the well it must be permitted. A CDP-1 form must be filed and approved prior to the use of the pit.

The Conservation Division's review of form CP-1, either in the central or district office, does not include an inquiry into well ownership or the filing operator's legal right to plug the well.

This notice in no way constitutes authorization to plug the above-captioned well by persons not having legal rights of ownership or interest in the well. This notice is void after ninety (90) days from the above date.

Sincerely

David P. Williams

Production Supervisor

District: #1 210 E Frontview, Suite A Dodge City, KS 67801 (620) 225-8888