

CARD MUST BE SIGNED

МНС/КОПЕ 6-25-84

RECEIVED
STATE CORPORATION COMMISSION

JUN 25 1984

6-25-84
OBSERVATION DIVISION
Wichita, Kansas

Important procedures to follow

- 1. Notify District office before setting surface casing.**
- 2. Set surface casing by circulating cement to the top.**
- 3. File completion forms ACO-1 with K.C.C. within 90 days of well completion, following instructions on ACO-1, side 1, and including copies of wireline logs.**
- 4. Notify District office 48 hours prior to old well workover or re-entry.**
- 5. Prior to plugging, prepare a plugging plan, then obtain agreement from the appropriate district office for an approved plugging plan.**
- 6. Submit plugging report (CP-4) to K.C.C. after plugging is completed.**
- 7. Obtain an approved injection docket number before disposing of salt water.**
- 8. Notify K.C.C. within 10 days when injection commences or terminates.**
- 9. If an alternate 2 completion, cement in the production pipe from below any usable water to surface within 120 days of spud date.**

**State Corporation Commission of Kansas
Conservation Division
200 Colorado Derby Building
Wichita, Kansas 67202
(316) 263-3238**

