Notice: Fill out COMPLETELY and return to Conservation Division at the address below within 60 days from plugging date.

KANSAS CORPORATION COMMISSION OIL & GAS CONSERVATION DIVISION

WELL PLUGGING RECORD K.A.R. 82-3-117

Form CP-4
December 2003
Type or Print on this Form
Form must be Signed
All blanks must be Filled

API Number: ____15 -_ 185-20605 -- 01 Lease Operator: Citation Oil & Gas Corp. Elinor Krampe Address: P O Box 690688, Houston, Texas 77269 Phone: (281) 517 -7800 Operator License #: 3553 Well Number: Type of Well: ENHR - SW - NE Spot Location (QQQQ): ____ 1550 (Oil. Gas D&A, SWD, ENHR, Water Supply Well, Cathodic, Other) Feet from North / South Section Line The plugging proposal was approved on: August 21, 2006 990 Feet from V East / West Section Line by: Richard W. Lacey __ Twp. 21 S. R. 14 ☐ East ✓ West (KCC District Agent's Name) Is ACO-1 filed? ✓ Yes No If not, is well log attached? 10/31/1975 Producing Formation(s): List All (If needed attach another sheet) Date Well Completed: Depth to Top: 3555 Bottom: 3622 T.D. 3860 10/25/2006 Plugging Commenced: Bottom: _ 10/27/2006 Plugging Completed: Depth to Top: Bottom: Show depth and thickness of all water, oil and gas formations. Oil, Gas or Water Records Casing Record (Surface Conductor & Production) Content То Size Put In Pulled Out Formation From LKC 8 5/8" OIL 3554 3622 298' 5 1/2" 3869' 350' Describe in detail the manner in which the well is plugged, indicating where the mud fluid was placed and the method or methods used in introducing it into the hole. If cement or other plugs were used, state the character of same depth placed from (bottom), to (top) for each plug set. MIRU PU & Plugging equipment. Opened well and flowed back w/1bbl wtr. ND WH. NU BOP. Released Baker A-3 Loc-set pkr @ 3509. POOH & LD 2 3/8" IPC tbg (111 jts) & pkr. MIRU WL unit. RIH & set CIBP @ 3500'. Capped CIBP w/2 sxs cement via dump bailer. RD MO WL. Dug out cellar. RU csg jacks. Pulled csg out of slips. Csg pulled in two. POOH & LD w/350' 5 1/2" csg. Lower portion corroded. RIH w/ 2 3/8" WL & stacked out @ 700'. Could not work downhole. Contacted KCC & obtained permission to plug w/700' to surface. (see back) Name of Plugging Contractor: Mike's Testing and Salvage Sharon ward 11/6/0 License #: 31529 Address: 323 S. Main St. / PO Box 209, Chase, KS 67524 PK9 Name of Party Responsible for Plugging Fees: Citation Oil & Gas Corp. State of Texas Sharon Ward (Employee of Operator) or (Operator) on above-described well, being first duly sworn on oath, says: That I have knowledge of the facts statements, and matters herein contained, and the log of the above-described well is as filed, and the same are true and correct, so help me God. (Address) P O Box 690688 Houston, Texas 77269 SUBSCRIBED and SWORN TO before me this 31st day of October 3-2-01 My Commission Expires:

Mail to: KCC - Conservation Division, 130 S. Market - Room 2078, Wichita, Kansas 67202

NOV 0 3 2006 PKKCC WICHITA

Mixed and pumped 350 sxs 60/40 Poz w/6% gel from 700' to surface. POOH & LD 2 3/8" WS. Topped off csg w/35 sxs 60/40 Poz w/6% gel. RD cementers. P&A witnessed by KCC representative Mike Meyers. RD MO P&A equipment. Will cut off casing and reclaim location at a later date. Well Plugged and abandoned on 10/27/06.

RECEIVED NOV 0 6 2006 KCC WICHITA