

CARD MUST BE SIGNED

(see rules on reverse side)

Conductor Pipe Required feet; Minimum Surface Pipe Required feet per Alt. 2
This Authorization Expires 3-19-87 Approved By E. P. [Signature]


feet per Alt ~~200~~ 200
.....
200/200

Must be filed with the K.C.C. five (5) days prior to commencing well
This card void if drilling not started within six (6) months of date received by K.C.C.

Important procedures to follow:

1. Notify District office before setting surface casing.
2. Set surface casing by circulating cement to the top.
3. File completion forms ACO-1 with K.C.C. within 90 days of well completion, following instructions on ACO-1, side 1, and including copies of wireline logs.
4. Notify District office 48 hours prior to old well workover or re-entry.
5. Prior to filing Intent, prepare a proposed plugging plan in case well is D & A, then obtain approval of plan when calling district office prior to setting surface pipe.
6. Submit plugging report (CP-4) to K.C.C. after plugging is completed.
7. Obtain an approved injection docket number before disposing of salt water.
8. Notify K.C.C. within 10 days when injection commences or terminates.

A Regular Section of Land 1 Mile = 5,280 Ft.



RECEIVED
STATE CORPORATION COMMISSION
SEP 19 1986
9-19-86
CONSERVATION DIVISION
Wichita, Kansas

State Corporation Commission of Kansas
Conservation Division
200 Colorado Derby Building
Wichita, Kansas 67202
(316) 263-3238

If an alternate 2 completion, cement in the production pipe from below any usable water to surface within 120 days of spud date.