Kansas Corporation Commission Oil & Gas Conservation Division

WELL PLUGGING APPLICATION

Please TYPE Form and File ONE Copy

Form CP-1 September 2003 This Form must be Typed Form must be Signed All blanks must be Filled

Address: P.O. Box 550 19209 S.W. Maryland Rd. Plugging Contractor: Spalne Pulling and Roustabout Services (Company Name)	Bernie Rockers Phone: (785) 448 - 4816 City / State: Welda, KS. 66091 KCC License #: 6372 Phone: (620) 431 - 1359
Plugging of this Well will be done in accordance with K.S.A. 55-101 et. seq. and the Richard of Company Representative authorized to be in charge of plugging operations: Southern Star Central Gas Pipeline Address: P.O. Box 550 19209 S.W. Maryland Rd. Plugging Contractor: Spalne Pulling and Roustabout Services (Company Name) Address: P.O. Box 386 Chanute, Ks. 66720	Bernie Rockers Phone: (785) 448 - 4816 City / State: Welda, KS. 66091 KCC License #: 6372 Phone: (620) 431 - 1359
Plugging of this Well will be done in accordance with K.S.A. 55-101 et. seq. and the Ruster Name of Company Representative authorized to be in charge of plugging operations: Southern Star Central Gas Pipeline Address: P.O. Box 550 19209 S.W. Maryland Rd. Plugging Contractor: Spalne Pulling and Roustabout Services	Bernie Rockers Phone: (785) 448 - 4816 City / State: Welda, KS. 66091 KCC License #: 6372
Plugging of this Well will be done in accordance with K.S.A. 55-101 et. seq. and the Rust Name of Company Representative authorized to be in charge of plugging operations: Southern Star Central Gas Pipeline Address: P.O. Box 550 19209 S.W. Maryland Rd.	Bernie Rockers Phone: (785) 448 - 4816 City / State: Welda, KS. 66091
Plugging of this Well will be done in accordance with K.S.A. 55-101 et. seq. and the Rulist Name of Company Representative authorized to be in charge of plugging operations:. Southern Star Central Gas Pipeline	Bernie Rockers
If not explain why?	
List (ALL) Perforations and Bridgeplug Sets: Perforated 1512.5'-1514.5' Elevation: 1084 (G.L. / K.B.) T.D.: PBTD: Anhydrite Depth: (Stone Corral Formation) Condition of Well: Good Poor Casing Leak Junk in Hole Proposed Method of Plugging (attach a separate page if additional space is needed): Clean out to total depth. Plug solid with cement. Cut casing 4' below ground. Backfill and reclaim.	
Surface Casing Size: 8 5/8" Set at: 103'	Computed with 75
-	Companied
Check One: Oil Well Gas Well D&A Cathodic V	Water Supply Well Other: Gas Storage Observation
190 165 Feet (in exact footage) From V Fast / West (from page)	st outside section corner) Line of Section (Not Lease Line) st outside section corner) Line of Section (Not Lease Line)
- NE - SE - SE Spot Location / QQQQ County	_{/:} Jefferson
Lease: McClouth Gas Storage Field Well #: 0-131	Sec. 30 Twp. 9 S. R. 20 Fast Wesl
State: Kentucky Zip Code: 42304	Contact Phone: (270) 852 - 4490
Address:	City: Owensboro (Operator's)
4700 Llightner EC D O D (Owner/Company Name)	KCC License #: 33097
4700 Llightungu CC D O D (Owner/Company Name)	
well Operator: Southern Star Central Gas Pipeline	This must be listed for wells drilled since 1967; if no API # was issued

WeelPlugged 10/3/2006 Kacops

CONSERVATION DIVISION WICHITA, KS