

Notice: Fill out COMPLETELY and return to Conservation Division at the address below within 60 days from plugging date.

KANSAS CORPORATION COMMISSION
OIL & GAS CONSERVATION DIVISION
WELL PLUGGING RECORD
K.A.R. 82-3-117

Form CP-4
December 2003
Type or Print on this Form
Form must be Signed
All blanks must be Filled

Lease Operator: K & N Petroleum, Inc.
Address: 1105 Walnut
Phone: (620) 793-6005 Operator License #: 3208
Type of Well: Oil Well Docket #: _____
(Oil, Gas D&A, SWD, ENHR, Water Supply Well, Cathodic, Other) *(If SWD or ENHR)*
The plugging proposal was approved on: 2/24/07 (Date)
by: Steve Durant (KCC District Agent's Name)
Is ACO-1 filed? Yes No If not, is well log attached? Yes No
Producing Formation(s): List All (If needed attach another sheet)

Depth to Top: _____ Bottom: _____ T.D. _____

Depth to Top: _____ Bottom: _____ T.D. _____

Depth to Top: _____ Bottom: _____ T.D. _____

API Number: 15-185-26313 ¹⁹⁰⁰⁻⁰⁰⁻⁰⁰
Lease Name: Manning B
Well Number: #3
Spot Location (QQQQ): NE - SE - SW -
990 Feet from North / South Section Line GPS
300-2961 Feet from East / West Section Line Loc
Sec. 9 Twp. 21 S. R. 11 East West
County: Stafford
Date Well Completed: 08/10/1964
Plugging Commenced: 02/27/07
Plugging Completed: 02/27/07

Show depth and thickness of all water, oil and gas formations.

Oil, Gas or Water Records		Casing Record (Surface Conductor & Production)				
Formation	Content	From	To	Size	Put In	Pulled Out
	Surface	0'	271'	8-5/8"	271'	0'
	Production	0'	3459'	4-1/2"	3459'	0'

Describe in detail the manner in which the well is plugged, indicating where the mud fluid was placed and the method or methods used in introducing it into the hole. If cement or other plugs were used, state the character of same depth placed from (bottom), to (top) for each plug set.


Move in and rig up. Discuss daily safety issues. Unload tubing - 113 jts. 2-3/8". Wait while welder put connection on surface pipe. Break off production head. Put on working head. Run in with 110 jts. 2-3/8" tubing. Tag bottom, pull 1 joint and wait on cement truck. Spot 25 sacks cement on bottom. Pull 91 jts tubing. Hook up and circulate cement to surface. Pull out rest of tubing. Hook up to surface pipe. Pump 100 sacks cement. Top off casing with cement. Tear down.

Name of Plugging Contractor: D.S. & W. Well Servicing, Inc. License #: 6901
Address: P.O. Box 231, Claflin, KS 67525

Name of Party Responsible for Plugging Fees: K & N Petroleum, Inc.
State of Kansas County, Barton, ss.

Edward S. Nernich

(Employee of Operator) or (Operator) on above-described well, being first duly sworn on oath, says: That I have knowledge of the facts statements, and matters herein contained, and the log of the above-described well is as filed, and the same are true and correct, so help me God.


KAREN J. MITCHELL
Notary Public - State of Kansas
My Appt. Expires 4/13/2010

(Signature) E. Nernich
(Address) 1105 Walnut, Great Bend, KS 67530

SUBSCRIBED and SWORN TO before me this 6th day of March, 20 07

Karen J. Mitchell
Notary Public My Commission Expires: 4/13/2010

Mail to: KCC - Conservation Division, 130 S. Market - Room 2078, Wichita, Kansas 67202

RECEIVED
MAR 07 2007
KCC WICHITA

PRT