## STATE OF KANSAS STATE CORPORATION COMMISSION

Give All Information Completely
Make Required Affidavit
Mail or Deliver Report to:
Conservation Division
State Corporation Commission
211 No. Broadway
Wichita, Kansas

## WELL PLUGGING RECORD

Wichita, Kansas		T 1 ( T T T T T T T T T T T T T T T T T	f	v. 6	ter ares ares	
NORTH	Location as "NI					
NEW COLD BANK AND THE MEMORY OF SOME AND		Lease Owner Theodore Gore  Lease Name Ruder Well No. 3				
			Nationa			hita 2, Kansas
	*			r Dry Hole)		
	Date well comp			and the same of th	tember 19,	<b>1948</b> 19
	Application for	plugging filed_		Jan	uary 5, 19	<b>)62</b> 19
	Application for	plugging approv	red	<u>Jan</u>	uary 8, 19	9 <b>62</b> 19
	Plugging comm	enced		Jan	uary 8, 19	962 19
				Jan g formation		
	Reason for abar		t to wat		TO THE RESIDENCE OF THE PROPERTY OF THE PROPER	
1	If a producing	well is abandon	ed, date of la	st production_	December	28, 19 <b>61</b>
The state of the s	Was permission					fore plugging was com
Locate well correctly on above Section Plat	menced?	yes			COLUMN STATE COMMENSATION COLUMN COLUMN STATE ST	1849 180 241 mil 77 California many seria dipinany ampananaji 1944 milyona amang 1944 milyon milyon ang 1944 milyon
me of Conservation Agent who	supervised plugging of thi	s well	Eldon P	etty		
oducing formation Kansas			TO Botton	n	Total Depth of	f Well 3473 Fee
ow depth and thickness of all w		15.				
OIL, CAS OR WATER REC	ORDS	et an garant en terret de l'accoupe an aussand 3 de la banacion en de la distribution de l'accoupe an anno en				CASING RECORD
FORMATION	CONTENT	FROM	ŢΟ	SIZE	PUT IN	PULLED OUT
				8 5//8"	164	none
			<del> </del>	5 1/2"	3473	2800*
				<u> </u>		
Pushed cement up to spipe to	plug down to 319 with dump bailer 550*; pumped 25 s 5 160*; pumped 20	Shot pi acks mud a sacks cen	up to 3 pe loose ind 20 sa ient, pul	150°; dump at 2800°; cks cement led pipe o	ed 4 sacks pulled pi ; pulled out. Baile	s ipe ed
feet for each place pushed cement up to so pipe to mud down	ug set.  plug down to 319 with dump bailer 550°; pumped 25 s	00°; sanded . Shot pi acks mud a sacks cen bridge; du	up to 3 pe loose nd 20 sa ent, pul mp 10 sa	150°; dump at 2800°; cks cement led pipe o	ed 4 sacks pulled pi ; pulled out. Baile	s ipe ed
feet for each place plac	plug down to 319 with dump bailer 550*; pumped 25 s 160*; pumped 20 wn, set 10* rock	00°; sanded . Shot pi acks mud a sacks cen bridge; du	up to 3 pe loose nd 20 sa ent, pul mp 10 sa	150°; dump at 2800°; cks cement led pipe o	ed 4 sacks pulled pi ; pulled out. Baile	s ipe ed
feet for each placement up to so pipe to mud down	plug down to 319 with dump bailer 550*; pumped 25 s 160*; pumped 20 wn, set 10* rock	00°; sanded . Shot pi acks mud a sacks cen bridge; du	up to 3 pe loose nd 20 sa ent, pul mp 10 sa	150°; dump at 2800°; cks cement led pipe o	ed 4 sacks pulled pi ; pulled out. Baile	s ipe ed
feet for each placement up to so pipe to mud down	plug down to 319 with dump bailer 550*; pumped 25 s 160*; pumped 20 wn, set 10* rock	00°; sanded . Shot pi acks mud a sacks cen bridge; du	up to 3 pe loose nd 20 sa ent, pul mp 10 sa	150°; dump at 2800°; cks cement led pipe o	ed 4 sacks pulled pi ; pulled out. Baile	s ipe ed
feet for each placement up to find the property of the propert	plug down to 319 with dump bailer 550*; pumped 25 s 160*; pumped 20 wn, set 10* rock	00°; sanded . Shot pi acks mud a sacks cen bridge; du	up to 3 pe loose nd 20 sa ent, pul mp 10 sa	150°; dump at 2800°; cks cement led pipe o	ed 4 sacks pulled pi ; pulled out. Baile	s ipe ed
feet for each placement up to find the property of the propert	plug down to 319 with dump bailer 550*; pumped 25 s 160*; pumped 20 wn, set 10* rock	00°; sanded . Shot pi acks mud a sacks cen bridge; du	up to 3 pe loose nd 20 sa ent, pul mp 10 sa	150°; dump at 2800°; cks cement led pipe o	pulled principal pulled put. Baile to base of	s ipe ed of
feet for each placement up to so pipe to mud down	plug down to 319 with dump bailer 550*; pumped 25 s 160*; pumped 20 wn, set 10* rock	00°; sanded . Shot pi acks mud a sacks cen bridge; du	up to 3 pe loose nd 20 sa ent, pul mp 10 sa	150*; dump at 2800*; cks cement led pipe o cks cement	pulled programmed but. Bailes to base of	sipe  ed  of
feet for each placement up to find the property of the propert	plug down to 319 with dump bailer 550*; pumped 25 s 160*; pumped 20 wn, set 10* rock	00°; sanded . Shot pi acks mud a sacks cen bridge; du	up to 3 pe loose nd 20 sa ent, pul mp 10 sa	150*; dump at 2800*; cks cement led pipe o cks cement	pulled programmed but. Bailes to base of	sipe  ed  of
feet for each placement up to find the property of the propert	plug down to 319 with dump bailer 550*; pumped 25 s 160*; pumped 20 wn, set 10* rock	00°; sanded . Shot pi acks mud a sacks cen bridge; du	up to 3 pe loose nd 20 sa ent, pul mp 10 sa	150*; dump at 2800*; cks cement led pipe o cks cement	pulled printing pulled but. Baile to base of	s ipe  ed  of  502
feet for each placement up to find the property of the propert	plug down to 319 with dump bailer 550*; pumped 25 s 160*; pumped 20 wn, set 10* rock	00°; sanded . Shot pi acks mud a sacks cen bridge; du	up to 3 pe loose nd 20 sa ent, pul mp 10 sa	150*; dump at 2800*; cks cement led pipe o cks cement	pulled printing pulled put. Baile to base of pulled put. Baile put. Baile pulled put. Baile	s ipe  ed  of  502
feet for each planed cement up to spipe to mud down cellar.	plug down to 319 with dump bailer 550*; pumped 25 s 5 160*; pumped 20 wn, set 10* rock	oo*; sanded sacks mud a sacks cen bridge; du	pe loose nd 20 sa ent, pul mp 10 sa	150*; dump at 2800*; cks cement led pipe o cks cement  STATE	pulled programmed but. Bailed	sipe  ed  of
Pushed cement up to 5 pipe to mud dov cellar.	plug down to 319 with dump bailer 550*; pumped 25 s 5 160*; pumped 20 wn, set 10* rock  (If additional Arnett	clescription is nece	up to 3 pe loose nd 20 sa ent, pul mp 10 sa ssary, use BACR lling Co	150'; dump at 2800'; cks cement led pipe o cks cement  STATE C	pulled programmed but. Bailed	sipe  ed  of
Pushed cement up to 5 pipe to mud dov cellar.	plug down to 319 with dump bailer 550*; pumped 25 s 5 160*; pumped 20 wn, set 10* rock  (If additional Arnett	oo*; sanded sacks mud a sacks cen bridge; du	up to 3 pe loose nd 20 sa ent, pul mp 10 sa ssary, use BACR lling Co	150'; dump at 2800'; cks cement led pipe o cks cement  STATE C	pulled programmed but. Bailed	sipe  ed  of
Pushed cement up to s pipe to mud dov cellar.	plug down to 319 with dump bailer 550*; pumped 25 s 5 160*; pumped 20 wn, set 10* rock  (If additional Arnett Ho	cosciption is nece	up to 3 pe loose nd 20 sa ent, pul mp 10 sa ssary, use BACR lling Co Kansas	150°; dump at 2800°; cks cement led pipe o cks cement  STATE C	pulled principal pulled put. Baile to base of the put. Baile to base of the pulled put. Baile to base of the put. Baile to base of the put. Baile to baile to base of the put. Baile to base of the put. Baile to baile to baile to base of the put. Baile to baile t	sipe  ed  of
Pushed cement up to 5 pipe to mud dov cellar.  ame of Plugging Contractor ldress	plug down to 319 with dump bailer 550*; pumped 25 s 0 160*; pumped 20 wn, set 10* rock  (If additional Arnett Ho	cosing Puistington,	up to 3 pe loose nd 20 sa ent, pul mp 10 sa ssary, use BACK lling Co Kansas	150*; dump at 2800*; cks cement led pipe o cks cement  STATE CON	pulled printing pulled put. Baile to base of put. Baile to baile to base of put. Baile to baile to base of put. Baile to baile to base of put. Baile to	sipe  ed  of
me of Plugging Contractordress	plug down to 319 with dump bailer 550*; pumped 25 s 5 160*; pumped 20 wn, set 10* rock  (If additional Arnett Ho	description is nece  Casing Puistington,	pe loose nd 20 sa ent, pul mp 10 sa ssary, use BACK lling Co Kansas	150°; dump at 2800°; cks cement led pipe ocks cement STATE CON	pulled printing pulled put. Baile to base of servation wichita.	of the above describe
me of Plugging Contractor_dress	plug down to 319 with dump bailer 550*; pumped 25 s 0 160*; pumped 20 wn, set 10* rock  (If additional Arnett Ho  ce Gore ath, says: That I have kn	description is nece  Casing Puistington,  Ook; sanded Casing Sacks centre of the control of the	up to 3 pe loose nd 20 sa tent, pul mp 10 sa ssary, use BACR lling Co Kansas EDGWICK	150°; dump at 2800°; cks cement led pipe ocks cement STATE CON Cof this sheet) mpany	pulled printing pulled put. Baile to base of servation wichita.	of the above describe
Pushed cement up to 5 pipe to mud dov cellar.  ame of Plugging Contractor ldress	plug down to 319 with dump bailer 550*; pumped 25 s 160*; pumped 20 wn, set 10* rock  (If additional Arnett Ho	description is nece Casing Pu istington,  O'; sanded cacks mud a cacks cen bridge; du description is nece Casing Pu istington,  Owledge of the description is nece Casing Pu	up to 3 pe loose nd 20 sa tent, pul mp 10 sa ssary, use BACR lling Co Kansas EDGWICK	150°; dump at 2800°; cks cement led pipe ocks cement STATE CON Cof this sheet) mpany	pulled printing pulled put. Baile to base of servation wichita.	of the above describe
me of Plugging Contractor_ddress	plug down to 319 with dump bailer 550*; pumped 25 s 160*; pumped 20 wn, set 10* rock  (If additional Arnett Ho	description is nece  Casing Puistington,  (Signature)	ssary, use BACK lling Co Kansas  EDGWICK  Statement of the control	at 2800'; dump at 2800'; cks cement led pipe ocks cement STATE CON CON Cof this sheet) mpany	pulled printing pulled put. Bailed put. Ba	of the above-describe ned and the log of the
me of Plugging Contractor_ddress	plug down to 319 with dump bailer 550*; pumped 25 s 160*; pumped 20 wn, set 10* rock  (If additional Arnett Ho	description is nece  Casing Puistington,  (Signature)	ssary, use BACK lling Co Kansas  EDGWICK  Statement of the control	at 2800'; dump at 2800'; cks cement led pipe ocks cement STATE CON CON CON CONTROL OF This sheet) mpany	pulled printing pulled put. Baile to base of service pulled put. Baile to base of service put. Baile put. Ba	of the above describe
me of Plugging Contractor_ddress	plug down to 319 with dump bailer 550*; pumped 25 s 5 160*; pumped 20 wn, set 10* rock  (If additional Arnett Ho  Te Gore ath, says: That I have kn that the same are true an	description is nece  Casing Puistington,  (Signature)	pe loose nd 20 sa ent, pul mp 10 sa ent, pul mp	at 2800'; dump at 2800'; cks cement led pipe ocks cement state of this sheet)  Tof this sheet)	pulled printing pulled put. Baile to base of services with the pulled put. Baile to base of services pulled put. Baile to base of services pulled put. Baile to base of services put. Services pulled put. Baile put. Bai	of the above-describe ined and the log of the Wichita 2, Ka
me of Plugging Contractor	plug down to 319 with dump bailer 550*; pumped 25 s 5 160*; pumped 20 wn, set 10* rock  (If additional Arnett Ho  Te Gore ath, says: That I have kn that the same are true an	description is nece Casing Puistington,  (NTY OF	pe loose nd 20 sa ent, pul mp 10 sa ent, pul mp	at 2800'; dump at 2800'; cks cement led pipe ocks cement state of this sheet)  Tof this sheet)	pulled printing pulled put. Baile to base of service pulled put. Baile to base of service put. Baile put. Ba	of the above-describe ined and the log of the Wichita 2, Ka
me of Plugging Contractor	plug down to 319 with dump bailer 550*; pumped 25 s 160*; pumped 20 wn, set 10* rock  (If additional Arnett Ho  Te Gore ath, says: That I have kn that the same are true an	description is nece  Casing Puistington,  (Signature)  day of	pe loose nd 20 sa ent, pul mp 10 sa ent, pul mp	at 2800'; dump at 2800'; cks cement led pipe of cks cement state of this sheet) mpany  State of this sheet) mpany  State of this sheet) mpany  State of this sheet of this	pulled printing pulled put. Baile to base of services with the pulled put. Baile to base of services pulled put. Baile to base of services pulled put. Baile to base of services put. Services pulled put. Baile put. Bai	of the above-describe ined and the log of the Wichita 2, Ka

Harry Gore RUDER #5 Total Depth 3472

Casing 8 5/8" Set@ 164' W/ 150 Sax 5 1/2" Set@ 3471'W/ 100 Sax

Comm: 9/8/48 Comp: 9/19/48

Yed Sou Ye Sec.14, Twp. 9, Rge. 19 Rooks County, Kansas

Tops Heebner Shale - 3191' Lansing K.C. #1-3210! Lansing K.C. #2-3230! Arbuckle 3470!

Anhydrite	Formation:	Depth:	
Arbuckie 3472	Sand Shale & Shells Sand Shale & Shells Sand & Shale Sand Red Bed & Shale Anhydrite Shale & Shells Lime & Shale Lime Lime Lime	75 350 400 710 915 1210 1424 1466 1895 3165 3210 3221 3410 3470	MATERIAL 1962 2-13-62 2010 DIVISION

STATE OF KANSAS) SS RUSSELL COUNTY )

I Hereby certify that the above information is true and correct to the best of my knowledge.

Subscribed and sworn to before me this 22nd day of September, 1948.

My Comm. expires 6/17/50