# STATE OF KANSAS STATE CORPORATION COMMISSION

#### WELL PLUGGING RECORD

or

Give All Information Completely
Make Required Affidavit
Mail or Deliver Report to:
Conservation Division
State Correction Completely

## FORMATION PLUGGING RECORD Strike out upper line when reporting plugging off formations.

e of Conservation Agent who supervised plugging of this well.  Depth to top. Bottom. Total Depth of Well. 3678 Feet of depth and thickness of all water, oil and gas formations.  L, GAS OR WATER RECORDS  CASING RECORD  Formation  Content  From  To  Size  Put In  Pulled Out  Describe in detail the manner in which the well was plugged, indicating where the mud fluid was placed and the method or methods used in ducing it into the hold. If cement or other plugs were used, state the character of same and depth placed, from feet to feet for each plug set.  Surface Pipe 8 5/8"240"cemented all around plug set at 240" and 15 sacks of cement on top through the drill pipeSurface plug 20" below the face and 10 sacks of cement used filling hole to surface. Hole the	ate Corporation Commission 0 Bitting Building ichita, Kansas	Ro	ooks	Coun	ty. Sec. 25	. Twp9 Rge	$\frac{18}{W}$
Lease Name. Scharndt Well No. 1 Office Address. Cherryvale, Ks. Character of Well (completed as Oil, Gas or Dry Hole) Date well completed. 7-22-47 19. Application for plugging filed. 7-22-47 19. Plugging commenced. 7-20-47 19. Plugging commenced. 7-20-47 19. Reason for abandonment of well or producing formation. Dry Hole  If a producing well is abandoned, date of last production. Dry Hole Was permission obtained from the Conservation Division or its agents before plugging was commenced?  Wes permission obtained from the Conservation Division or its agents before plugging was commenced?  Total Depth of Well 2678 Feet of Conservation Agent who supervised plugging of this well. Depth to top. Bottom. Total Depth of Well 2678  CASING RECORD  Formation  Content From To Size Fut In Pulled Out  Describe in detail the manner in which the well was plugged, indicating where the mud fluid was placed and the method or methods used in feet for each plug set.  Surface Pipe 8. 5/8"-240!ce mented all around plug set at 240! and 15 search of the comment of the conservation plug conservation of the conserv	NORTH	Location as "NE'41  Lease Owner	Veeder	or footage fro Sup. &	Dev. Co.	DW DW OT	1
Office Address GRETTYV21E, AS.  Character of Well (completed as Oil, Gas or Dry Hole)  Date well completed.  Application for plugging filed.  7-22-47.  Application for plugging approved.  7-22-47.  Plugging commenced.  7-20-47.  Plugging completed.  Reason for abandonment of well or producing formation.  Dry Hole  If a producing well is abandoned, date of last production.  Dry Hole  Was permission obtained from the Conservation Division or its agents before plugging was commenced?.  C. D. Stough  weing formation.  Depth to top.  Bottom.  Total Depth of Well 2678.  Feed Address.  CASING RECORD  Describe in detail the manner in which the well was plugged, indicating where the mud fluid was placed and the method or methods used in the dealth. If cement or other plugs were used, state the character of same and depth placed, from.  Surface Pipe 8. 5/8"-240!cemented all around plug set at 240! and 15 access and 10 sacks of cement. On top through the drill pipe-surface plug 20! below the face and 10 sacks of cement. Used filling hole to surface plug 20! below the face and 10 sacks of cement.		Lease Name	Scharn	dt			Well No 1
Date well completed. 19. Application for plugging filed. 7-22-47 19. Application for plugging approved. 7-22-47 19. Plugging commenced. 7-20-47 19. Plugging completed. 7-20-47 19. Reason for abandonment of well or producing formation. Dry Hole  If a producing well is abandoned, date of last production. Dry Hole  If a producing well is abandoned, date of last production. Dry Hole  If a producing well is abandoned, date of last production. Dry Hole  Was permission obtained from the Conservation Division or its agents before plugging was commenced?  Yes  To D. Stough  Was permission obtained from the Conservation Division or its agents before plugging was commenced?  To D. Stough  Depth to top. Bottom. Total Depth of Well 3678 Feet weight and thickness of all water, oil and gas formations.  L, GAS OR WATER RECORDS  CASING RECORD  Formation  Content  From  To Size  Put In  Pulled Out  Describe in detail the manner in which the well was plugged, indicating where the mud fluid was placed and the method or methods used in ducing it into the hold. If cement or other plugs were used, state the character of same and depth placed, from feet to feet for each plug set.  Surface Pipe 8 5/8"—240!—cemented all around plug set at 240! and 15 sacks of cement on top through the drill pipe—Surface, Plug 20! below the face and 10 sacks of cement used filling hole to surface.		Office Address	Cherry	vale, K	S .	David U. 1	
Application for plugging filed. 7=22-47 19.  Application for plugging approved 7=22-47 19.  Plugging commenced 7=20-47 19.  Plugging completed. 7=20-47 19.  Reason for abandonment of well or production. Dry Hole  If a producing well is abandoned, date of last production. Dry Hole 19.  Was permission obtained from the Conservation Division or its agents before plugging was commenced? Yes  The of Conservation Agent who supervised plugging of this well.  Depth to top Bottom Total Depth of Well 3678 Feet  Weeth and thickness of all water, oil and gas formations.  II., GAS OR WATER RECORDS  CASING RECORD  Formation  Content From To Size Put In Pulled Out  Describe in detail the manner in which the well was plugged, indicating where the mud fluid was placed and the method or methods used in ducing it into the hold. If cement or other plugs were used, state the character of same and depth placed, from feet for each plug set.  Surface Pipe 8 5/8"21,0!cemented all around plug set at 240! and 15 sacks of cement on top through the drill pipe-Surface plug 20! below the face and 10 sacks of cement used filling hole to surface. Hole of the face and 10 sacks of cement used filling hole to surface. Hole of the late of the face and 10 sacks of cement used filling hole to surface. Hole of the late of the face and 10 sacks of cement used filling hole to surface. Hole of the late of the face and 10 sacks of cement used filling hole to surface. Hole of the late of the face and 10 sacks of cement used filling hole to surface. Hole of the late of the face and 10 sacks of cement used filling hole to surface. Hole of the late of the face and 10 sacks of cement used filling hole to surface. Hole of the late of the face and 10 sacks of cement used filling hole to surface. Hole of the face and 10 sacks of cement used filling hole to surface. Hole of the face and 10 sacks of cement used filling hole to surface. Hole of the face and 10 sacks of cement used filling hole to surface. Hole of the face and 10 sacks of the face and 10 sacks o							
Application for plugging approved 7-22-47 19. Plugging commenced 7-20-47 19. Plugging commenced 7-20-47 19. Plugging commenced 7-20-47 19. Plugging commenced 7-20-47 19. Reason for abandonment of well or producing formation. Dry Hole  If a producing well is abandoned, date of last production Dry Hole 19. Was permission obtained from the Conservation Division or its agents before plugging was commenced?  Was permission obtained from the Conservation Division or its agents before plugging was commenced?  Was permission obtained from the Conservation Division or its agents before plugging was commenced?  To Depth to top. Bottom. Total Depth of Well 3678 Feet when the permission of all water, oil and gas formations.  IL, GAS OR WATER RECORDS  CASING RECORD  Pormation Content From To Size Put In Pulled Out  Describe in detail the manner in which the well was plugged, indicating where the mud fluid was placed and the method or methods used in inducing it into the hold. If cement or other plugs were used, state the character of same and depth placed, from feet to feet for each plugset.  Surface Pipe 8 5/8"—240!—cemented all around plug set at 240! and 15 sacks of cement on top through the drill pipe—Surface plug 20! below the face and 10 sacks of cement used filling hole to surface. Hole fall to the late of the surface was present to surface the surface plug 20! below the face and 10 sacks of cement used filling hole to surface.		Application for plus	ging filed	7.	-22-47		19
Plugging commenced							
Reason for abandonment of well or producing formation Dry Hole  If a producing well is abandoned, date of last production Dry Hole  Was permission obtained from the Conservation Division or its agents before plugging was commenced?  Yes  ne of Conservation Agent who supervised plugging of this well  Was permission obtained from the Conservation Division or its agents before plugging was commenced?  Yes  ne of Conservation Agent who supervised plugging of this well  Oc. D. Stough  Depth to top  Bottom  Total Depth of Well 3678  Feet  CASING RECORD  Formation  Content  From  To Size  Put In  Pulled Out  Describe in detail the manner in which the well was plugged, indicating where the mud fluid was placed and the method or methods used in oducing it into the hold. If cement or other plugs were used, state the character of same and depth placed, from  feet for each plug set.  Surface Pipe 8 5/8"—240"—cemented all around plug set at 240! and 15  sacks of cement on top through the drill pipe—Surface plug 20! below the face and 10 sacks of cement used filling hole to surface Plug 20! below the		Plugging commence	ed	7	-20-47		19
Locate well correctly on above Was permission obtained from the Conservation Division or its agents before plugging was commenced? Depth to top Bottom Total Depth of Well 3678 Feet whether and thickness of all water, oil and gas formations.  LL, GAS OR WATER RECORDS  Content From To Size Put In Pulled Out  Describe in detail the manner in which the well was plugged, indicating where the mud fluid was placed and the method or methods used in ducing it into the hold. If cement or other plugs were used, state the character of same and depth placed, from feet for each plug set.  Surface Pipe 8 5/8"—240"——ccemented all around plug set at 240" and 15 sacks of cement on top through the drill pipe—Surface plug 20" below the face and 10 sacks of cement used filling hole to surface. Hole of will a supplied out the face and 10 sacks of cement used filling hole to surface.		Plugging completed	L		-20-47	D U- 1-	19
Locate well correctly on above Section Plat   Was permission obtained from the Conservation Division or its agents before plugging was commenced?							
Locate well correctly on above section Plat  The conservation Agent who supervised plugging of this well.  Depth to top.  Depth to top.  Depth to top.  Depth to top.  Bottom.  Total Depth of Well. 3578  Feet  CASING RECORD  Formation.  Content  From  To  Size  Put In  Pulled Out  Describe in detail the manner in which the well was plugged, indicating where the mud fluid was placed and the method or methods used in deducing it into the hold. If cement or other plugs were used, state the character of same and depth placed, from.  Surface Pipe 8 5/8"—240"—cemented all around plug set at 240" and 15 sacks of cement, used filling hole to surface. Hole the fall of the face and 10 sacks of cement, used filling hole to surface. Hole the fall of the face and 10 sacks of cement, used filling hole to surface.		If a producing well	is abandoned	l date of last	t production	Dry Hole	10
menced? Yes  menced? To Do Stough  conservation Agent who supervised plugging of this well. Total Depth of Well 3678 Feet  wheth and thickness of all water, oil and gas formations.  IL, GAS OR WATER RECORDS  CASING RECORD  Formation  Content  From  To Size  Put In  Pulled Out  Describe in detail the manner in which the well was plugged, indicating where the mud fluid was placed and the method or methods used in oducing it into the hold. If cement or other plugs were used, state the character of same and depth placed, from feet to feet for each plug set.  Surface Pipe 8 5/8"—240"—cemented all around plug set at 240" and 15 sacks of cement. On top through the drill pipe—Surface plug 20" below the face and 10 sacks of cement used filling hole to surface. Hole full of the face and the filling face are surface. Hole full of the face and the filling hole to surface.							
we depth and thickness of all water, oil and gas formations.  IL, GAS OR WATER RECORDS  CASING RECORD  Formation  Content  From  To  Size  Put In  Pulled Out  Describe in detail the manner in which the well was plugged, indicating where the mud fluid was placed and the method or methods used in oducing it into the hold. If cement or other plugs were used, state the character of same and depth placed, from  feet for each plug set.  Surface Pipe 8 5/8"240!cemented all around plug set at 240! and 15 sacks of cement on top through the drill pipeSurface plug 20! below the face and 10 sacks of cement used filling hole to surface. Hole full of	Locate well correctly on above Section Plat				V -		
weight and thickness of all water, oil and gas formations.  IL, GAS OR WATER RECORDS  CASING RECORD  Formation  Content  From  To  Size  Put In  Pulled Out  Describe in detail the manner in which the well was plugged, indicating where the mud fluid was placed and the method or methods used in oducing it into the hold. If cement or other plugs were used, state the character of same and depth placed, from  feet to  feet for each plug set.  Surface Pipe 8 5/8"240!cemented all around plug set at 240! and 15  sacks of cement, on top through the drill pipe.	ne of Conservation Agent who sup-	ervised plugging of this we	ell	<b></b>	<u> </u>	D. Stoug	n 3678
Formation Content From To Size Put In Pulled Out  Describe in detail the manner in which the well was plugged, indicating where the mud fluid was placed and the method or methods used in oducing it into the hold. If cement or other plugs were used, state the character of same and depth placed, from feet for each plug set.  Surface Pipe 8 5/8"240'cemented all around plug set at 240' and 15 sacks of cement on top through the drill pipeSurface plug 20' below the face and 10 sacks of cement used filling hole to surface. Hole full of	w depth and thickness of all water,	oil and gas formations.	top	Botton	n '	Total Depth of V	Well 5076 Feet
Describe in detail the manner in which the well was plugged, indicating where the mud fluid was placed and the method or methods used in oducing it into the hold. If cement or other plugs were used, state the character of same and depth placed, from feet to feet for each plug set.  Surface Pipe 8 5/8"240'cemented all around plug set at 240' and 15 sacks of cement on top through the drill pipeSurface plug 20' below the face and 10 sacks of cement used filling hole to surface. Hole full of						(	CASING RECORD
Describe in detail the manner in which the well was plugged, indicating where the mud fluid was placed and the method or methods used in oducing it into the hold. If cement or other plugs were used, state the character of same and depth placed, from feet to feet for each plug set.  Surface Pipe 8 5/8"240'cemented all around plug set at 240' and 15 sacks of cement on top through the drill pipe-Surface plug 20' below the face and 10 sacks of cement used filling hole to surface. Hole full of	Formation	Content	From	То	Size	Put In	Pulled Out
Describe in detail the manner in which the well was plugged, indicating where the mud fluid was placed and the method or methods used in oducing it into the hold. If cement or other plugs were used, state the character of same and depth placed, from feet to feet for each plug set.  Surface Pipe 8 5/8"240'cemented all around plug set at 240' and 15 sacks of cement on top through the drill pipeSurface plug 20' below the face and 10 sacks of cement used filling hole to surface. Hole full of	1						
Describe in detail the manner in which the well was plugged, indicating where the mud fluid was placed and the method or methods used in oducing it into the hold. If cement or other plugs were used, state the character of same and depth placed, from feet to feet for each plug set.  Surface Pipe 8 5/8"240'cemented all around plug set at 240' and 15 sacks of cement on top through the drill pipeSurface plug 20' below the face and 10 sacks of cement used filling hole to surface. Hole full of	!						
Describe in detail the manner in which the well was plugged, indicating where the mud fluid was placed and the method or methods used in oducing it into the hold. If cement or other plugs were used, state the character of same and depth placed, from feet to feet for each plug set.  Surface Pipe 8 5/8"240!cemented all around plug set at 240! and 15 sacks of cement on top through the drill pipeSurface plug 20! below the face and 10 sacks of cement used filling hole to surface. Hole full of							
Describe in detail the manner in which the well was plugged, indicating where the mud fluid was placed and the method or methods used in oducing it into the hold. If cement or other plugs were used, state the character of same and depth placed, from feet to feet for each plug set.  Surface Pipe 8 5/8"240!cemented all around plug set at 240! and 15 sacks of cement on top through the drill pipeSurface plug 20! below the face and 10 sacks of cement used filling hole to surface. Hole full of							
Describe in detail the manner in which the well was plugged, indicating where the mud fluid was placed and the method or methods used in oducing it into the hold. If cement or other plugs were used, state the character of same and depth placed, from feet to feet for each plug set.  Surface Pipe 8 5/8"240'cemented all around plug set at 240' and 15 sacks of cement on top through the drill pipeSurface plug 20' below the face and 10 sacks of cement used filling hole to surface. Hole full of							
Describe in detail the manner in which the well was plugged, indicating where the mud fluid was placed and the method or methods used in oducing it into the hold. If cement or other plugs were used, state the character of same and depth placed, from feet to feet for each plug set.  Surface Pipe 8 5/8"240'cemented all around plug set at 240' and 15 sacks of cement on top through the drill pipeSurface plug 20' below the face and 10 sacks of cement used filling hole to surface. Hole full of							
3-17-48						X	
3-17-48							
-						3-17-48	<u> </u>
		~~~		1	yvares		
J one riy vare, 'S'	, ,			djur	<b>V</b> , s	s.	
TE OF COUNTY OF Selfury ss.	g first duly sworn on oath, says: T	hat I have knowledge of	the facts, st	atements, and	or (owner or	operator) of the	above-described well,
TE OF COUNTY OF County of county of the above-described well	ribed well as filed and that the sam	ne are true and correct. S	so help me G	ρ¢Ω	/ marrens herem	contained and t	ne log of the above-
		/a:	. 01	) ,	1 8	. 1	$\wedge$
ATE OF COUNTY OF Seminary (employed of course) or (owner or operator) of the above-described well, ag first duly sworn on oath, says: That I have knowledge of the facts, statements, and matters herein contained and the log of the above-cribed well as filed and that the same are true and correct. So help me God:				loodo.		to but as	20 1/2 Ca.
COUNTY OF, ss, ss			nature)	ledge	while	Joly & D	Pene Co.
COUNTY OF		H (Sig	nature)	ledge To The	wifned a	ply to	Pené Co.
COUNTY OF	Subscribed and Sworn to before r	.th		Niere	La CAC	Jaly J Colores	Pené Co.
COUNTY OF	SUBSCRIBED AND SWORN TO before I	.th		Nare	l (AC	ply The lair ddress)	Pené Co.
TE OF	Markeda	.th		Nove	la Choa	ply of Coloress)  19.4	Pené Co.
TE OF. COUNTY OF (employed of cour) or (owner or operator) of the above-described well, g first duly sworn on oath, says: That I have knowledge of the facts, statements, and matters herein contained and the log of the above-ribed well as filed and that the same are true and correct. So help me God (Signature)	S) COAR AGA	.th	day of	Mare J.O	Mujnie U (A)	poly of Coloress)  19.4	Notary Public.

BOOK PAGE! YLLEGIP. 四部以来できまって、常多様 リーンハーション こうしい



#### Veeder Supply & Dev'l. Co.



### Cherryvale, Kansas

Drilled for _ N. Appleman & Co.	Farm _Schrandt	No1 Depth_3678
Contractor _ VEEDER SUPPLW & DEV*L. CO.	Pipe _ 243' of 8 5/8 Gag	
Location SW SW SE	Sec	25 Twp. 9 Range 18W
Commenced 7-7-47 Completed 7-20-47	County Rooks	State _ Kansas
Surface soil sand       0       70       100         Shale shells       100       365       755       915         Sand       755       915       990       1095       581       990       1095       1300       1300       1350       1117       1005       1300       1350       1117       1117       1117       1117       1117       1117       1117       1117       1117       1117       1117       1117       1117       1117       1117       1117       1117       1117       1117       1117       1117       1117       1117       1117       1117       1117       1117       1117       1117       1117       1117       1117       1117       1117       1117       1117       1117       1117       1117       1117       1117       1117       1117       1117       1117       1117       1117       1117       1117       1117       1117       1117       1117       1117       1117       1117       1117       1117       1117       1117       1117       1117       1117       1117       1117       1117       1117       1117       1117       1117       1117       1117       1117       1117       1117	70 30 265 390 160 75 105 295 50 97 18 360 60 90 205 80 120 23 132 155 315 70 55 365 30 30 30 30 30	State Kangas
AFTIDAV	The second secon	
STATE OF KANSAS		

MONTGOMERY COUNTY SS:

EMMETT C. VEEDER, of lawful age, being duly and solemnly sworn on oath says; I am a resident of Cherryvale, Montgomery County, Kansas, and I hereby know and on oath state, that the above drilling log covering the Schrandt # 1 Well in section 25-9-18W Rooks County, Kansas, is true and correct.

Further affiant saith not.

THE VERDER SUPPLY & DEVELOPMENT COMPANY

Subscribed and sworn to before me this 29 th day of July 1947