Kansas Corporation Commission Oil & Gas Conservation Division

WELL PLUGGING APPLICATION

Please TYPE Form and File ONE Copy

Form CP-1 September 2003 This Form must be Typed Form must be Signed All blanks must be Filled

API # 15 - 007-01198-00 -00	(Identifier Number of this we	II). This must be listed for wells drilled si	nce 1967; if no API # was issued,
indicate original spud or completion date			
Well Operator: PETROLEUM PROPERTY SERVICES INC.		KCC License #: 31142	
Address: 125 N. MARKET, SUITE 1251	er / Company Name)	City:_WICHITA	(Operator's)
State: KANSAS	Zip Code: 67202	Contact Phone:(316) 26	5 - 3351
*· //· · · · · · · · · · · · · · · · · ·		Sec. 3 Twp. 32 S	
SW - SE - SWs	spot Location / QQQQ Cou	unty: BARBER	
Feet (in exact footage) From [arest outside section corner) Line of Section	on (Not Lease Line)
1650 Feet (in exact footage) From	East / 🗸 West (from ne	arest outside section corner) Line of Section	on (Not Lease Line)
Check One: V Oil Well Gas Well	D&A Cathodic	Water Supply Well	
SWD Docket #	ENHR Docket # _	Other:	
Conductor Casing Size:	Set at:	Cemented with:	Sacks
Surface Casing Size: 8-5/8"	Set at: 306'	Cemented with: 225	Sacks
Production Casing Size: 5-1/2"	Set at: 4867'	Cemented with: 75	Sacks
List (ALL) Perforations and Bridgeplug Sets: OPE	N HOLE		
Proposed Method of Plugging (attach a separate page	if additional space is needed): AS	PER KCC INSTRUCTIONS. S	EE ATTACHED.
Is Well Log attached to this application as required? If not explain why? BEFORE ACO-1.	Yes V No Is ACO-1 fil	led? Yes V No	
Plugging of this Well will be done in accordance w		DOM COUDAEDED/LEON	
List Name of Company Representative authorized to	be in charge of plugging operati	0113,	
		/ 316 \ 265 2	351
125 N MARKET SHITE 1251		Phone: (316) 265 - 3	
Address: 125 N. MARKET, SUITE 1251,	ne -	City / State: WICHITA, KS 6	
Plugging Contractor: QUALITY WELL SERVIC	npany Name)	City / State: WICHITA, KS 6	7202 (Contractor's)
Plugging Contractor: QUALITY WELL SERVICE	npany Name) IOD KS	City / State: WICHITA, KS 6 KCC License #: 31925 Phone: (620) 727 - 3	7202

Mail to: KCC - Conservation Division, 130 S. Market - Room 2078, Wichita, Kansas 67202

Authorized Operator / Agent:

Date: 8/15/07

AUG 1 5 2007

CONSERVATION DIVISION WICHITA KS



Kathleen Sebelius, Governor Thomas E. Wright, Chairman Michael C. Moffet, Commissioner Joseph F. Harkins, Commissioner

NOTICE OF RECEIPT OF WELL PLUGGING APPLICATION (CP-1)

PETROLEUM PROPERTY SERVICES, INC. 125 N MARKET, STE 1251 WICHITA, KS 67202

August 22, 2007

Re: SKINNER D #7

API 15-007-01198-00-00

3-32S-15W, 330 FSL 1650 FWL BARBER COUNTY, KANSAS

Dear Operator:

This letter is to notify you that the Conservation Division has received your plugging proposal, form CP-1, for the above well and has reviewed the proposal for completeness. The central office will now forward your CP-1 to the district office listed below for review of the proposed plugging method. Please contact the district office for approval of your proposed plugging method at least five (5) days before plugging the well, pursuant to K.A.R. 82-3-113(b). If a workover pit will be used during the plugging of the well it must be permitted. A CDP-1 form must be filed and approved prior to the use of the pit in accordance with K.A.R. 82-3-600.

The Conservation Division's review of form CP-1, either in the central or district office, does not include an inquiry into well ownership or the filing operator's legal right to plug the well. This notice in no way constitutes authorization to plug the above well by persons not having legal rights of ownership or interest in the well.

This notice is void after February 18, 2008. The CP-1 filing does not bring the above well into compliance with K.A.R. 82-3-111 with regard to the Commission's temporary abandonment requirements.

Sincerely,

Steve Bond

Steve Bond

Production Department Supervisor

District: #1 210 E Frontview, Suite A Dodge City, KS 67801 (620) 225-8888

Ron Schraeder

From: Steve Durrant [s.durrant@kcc.ks.gov]

Sent: Monday, August 06, 2007 1:10 PM

To: Ron Schraeder

Subject: SKINNER D #7 P & A

Bottom Plug:

a.) if no gas pressure at the surface, sand 51/2" to 4817' + 5sx. cmt with bailer.

b.) pump bottom with 200#'s cotton seed hulls + 25 sx. cmt. displaced to bottom. (est. injection rate prior to pumping plug.)

c.) set CIBP@ 4800' + 2 sx. cmt with a bailer.

Top Plug:

a.) Test casing after bottom plug has been set to 300#. Free pt. casing and pull to 1200'. Load hole w/gelled water and pump 50sx. cmt.(2nd. plug) Pull casing to 600'. Load hole with gelled water and pump 50 sx. cmt. (3rd.plug) pull casing to 330'.Load hole with gelled water and pump 50 sx. cmt. (4th plug) pull casing to 40' and circ. cmt. to surface.

b.) Test casing to 300 #, perf. casing at 1200' and circ. cmt. back to surface.

Thanks, SD

RECEIVED KANSAS CORPORATION COMMISSION

AUG 15 2007

CONSERVATION DIVISION WICHITA, KS