Iail or Deliver Report to: Conservation Division State Corporation Commission								
211 No. Broadway Wichita, Kansas	ROO	THE RESERVE OF THE PERSON NAMED OF THE PERSON	Couni	y. Sec. 32	rwp. 83 Rge	<u>19W</u> (E)(W)	
NORTH		Location as "NE/CNW%SW%" or footage from lines SW SE SE						
	ı	Lease Owner EXCALIBER CORPORATION Lease Name HORNER Well No. 7						
		Office Address 324 Mc Cullo3h Bldg Okmulger, Oklahoma					10. <u> </u>	
	Character of We							
		Date well completed APRTL 3,					1963	
	Application for p							
	Application for p							
	Plugging commer	Plugging commenced APRIL 3,				196		
		Plugging completed APRIL 3, Reason for abandonment of well or producing formation DRY HOLE					19 63	
	If a producing w	vell is abandor	ed, date of la	st production_			19	
Locate well correctly on above	Was permission	obtained from	the Conserv	ation Division o	or its agents bef	ore plugg	ing was com	
Section Plat me of Conservation Agent who	menced?	11 F	<u>YY</u> nnsac 1600 T		7 4375 401			
ducing formation	supervised plugging of this	well 12	LIUN PET	Y, MAYS, I	CANSAS		0220	
ow depth and thickness of all w	vater, oil and gas formations	pm to top	Botton	1	Total Depth of	Well	3550 Fee	
OIL, GAS OR WATER REC		•			•	CASING	RECORD	
FORMATION	CONTENT	FROM	то	SIZE	PUT IN		LED OUT	
ND, CLAY & SHALE	SURFACE CASING	_0_	2061	8-5/8**	2061)NE	
							7111	
			-					
			-					
						<u> </u>		
			-					
Describe in detail the manne introducing it into the hole. If	cement or other plugs were	ugged, indicati e used, state th	ing where the	mud fluid was p f same and dept	laced and the m	nethod or 1	methods used feet to	
introducing it into the hole. If	plugged HOLE:	e used, state th	ne character o	f same and dept	h placed, from	aethod or 1	methods used feet to	
introducing it into the hole. If	PLUGGED HOIF: Filled hole wit	e used, state the	ne character of	same and dept	h placed, from	nethod or i	methods used	
introducing it into the hole. If	PLUGGED HOIF: Filled hole wit Set plug, 1/4 s cement through	th heavy notes he heavy notes he heavy notes he	mid from Hallibu	same and dept	o 540!.	nethod or i	methods used feet to	
introducing it into the hole. If	PLUGGED HOLF: Filled hole wit Set plug, 1/4 s cement through mud up to 200'.	h heavy mk. hulls, drill pip	mid from Hallibur De. Fill	3550' up tron plug, d hole wi	o 540:. 20 sx. th heavy	nethod or i	methods used	
introducing it into the hole. If	PLUGGED HOIF; Filled hole wit Set plug, 1/4 s cement through mud up to 200', burton plug, 20	h heavy nk. hulls, drill pip	mid from Hallibu be. Fill lg, 1/4 si	3550' up tron plug, ed hole wik. hulls,	o 5401. 20 sx. th heavy	nethod or r	methods use	
introducing it into the hole. If	PLUGGED HOIF: Filled hole wit Set plug, 1/4 s cement through mud up to 200'. burton plug, 20 Filled hole to	th heavy mak. hulls, drill ping Set plus sx. ceme 40' with	mid from Hallibu De. Fill Eg, 1/4 s Ent throu	3550' up tron plug, ad hole wik. hulls, gh drill p	o 540!. 20 sx. th heavy Halli- ipe.	nethod or r	methods used	
introducing it into the hole. If	PLUGGED HOIF: Filled hole wit Set plug, 1/4 s cement through mud up to 200'. burton plug, 20 Filled hole to sk. hulls, Hall	th heavy mak. hulls, drill ping Set plus sx. ceme 40' with	mid from Hallibu De. Fill Eg, 1/4 s Ent throu	3550' up tron plug, ad hole wik. hulls, gh drill p	o 540!. 20 sx. th heavy Halli- ipe.	nethod or i	methods used	
introducing it into the hole. If	PLUGGED HOIF: Filled hole wit Set plug, 1/4 s cement through mud up to 200'. burton plug, 20 Filled hole to	th heavy mak. hulls, drill ping Set plus sx. ceme 40' with	mid from Hallibu De. Fill Eg, 1/4 s Ent throu	3550' up tron plug, ad hole wik. hulls, gh drill p	o 540!. 20 sx. th heavy Halli- ipe.	nethod or n	methods use	
introducing it into the hole. If	PLUGGED HOIF: Filled hole wit Set plug, 1/4 s cement through mud up to 200'. burton plug, 20 Filled hole to sk. hulls, Hall	h he avy mak. hulls, drill pip Set plus sx. ceme 40' with iburton p	mid from Hallibu be. Fill lg, 1/4 s ent throu heavy mu lug, 10	3550' up tron plug, ad hole wik. hulls, gh drill p	o 540!. 20 sx. th heavy Halli- ipe.	nethod or n	methods use	
introducing it into the hole. If	Filled hole wit Set plug, 1/4 s cement through mud up to 200'. burton plug, 20 Filled hole to sk. hulls, Hall cellar zero.	h he avy mak. hulls, drill pip Set plus sx. ceme 40' with iburton p	mid from Hallibu be. Fill lg, 1/4 s ent throu heavy mu lug, 10	3550' up tron plug, ad hole wik. hulls, gh drill p	o 540!. 20 sx. th heavy Halli- ipe.	nethod or n	methods use	
ntroducing it into the hole. If	Filled hole wit Set plug, 1/4 s cement through mud up to 200'. burton plug, 20 Filled hole to sk. hulls, Hall cellar zero.	h he avy mak. hulls, drill pip Set plus sx. ceme 40' with iburton p	mid from Hallibu be. Fill lg, 1/4 s ent throu heavy mu lug, 10	3550' up tron plug, ad hole wik. hulls, gh drill p	o 540!. 20 sx. th heavy Halli- ipe.	RAHON T	methods use feet t	
introducing it into the hole. If	Filled hole wit Set plug, 1/4 s cement through mud up to 200'. burton plug, 20 Filled hole to sk. hulls, Hall cellar zero.	h he avy mak. hulls, drill pip Set plus sx. ceme 40' with iburton p	mid from Hallibu be. Fill lg, 1/4 s ent throu heavy mu lug, 10	3550' up tron plug, ad hole wik. hulls, gh drill p	o 540'. 20 sx. th heavy Halli- ipe. ug, 1/2 up to	RAHON T	feet to	
introducing it into the hole. If	Filled hole wit Set plug, 1/4 s cement through mud up to 200'. burton plug, 20 Filled hole to sk. hulls, Hall cellar zero.	h he avy mak. hulls, drill pip Set plus sx. ceme 40' with iburton p	mid from Hallibu be. Fill lg, 1/4 s ent throu heavy mu lug, 10	3550' up tron plug, ad hole wik. hulls, gh drill p	o 540'. 20 sx. th heavy Halli- ipe. ug, 1/2 up to APF	RAHON T	feet to	
introducing it into the hole. If	PLUGGED HOLE: Filled hole wit Set plug, 1/4 s cement through mud up to 200'. burton plug, 20 Filled hole to sk. hulls, Hall cellar zero. Job completed:	h heavy mak. hulls, drill pip Set plus sx. ceme 40' with iburton p	mid from Hallibu be. Fill lg, 1/4 s ant throu heavy mu lug, 10	3550' up tron plug, ed hole wik. hulls, gh drill plus, set plus, cement	o 540'. 20 sx. th heavy Halli- ipe. ug, 1/2 up to APF	RAHON T	feet to	
ne of Plugging Contractor	PLUGGED HOLE: Filled hole wit Set plug, 1/4 s cement through mud up to 200'. burton plug, 20 Filled hole to sk. hulls, Hall cellar zero. Job completed: (If additional de	ch heavy mak. hulls, drill pip Set plu sx. ceme 40' with iburton p	mid from Hallibu be. Fill lg, 1/4 s ent throu heavy mu lug, 10 -3-63.	f same and dept 3550' up t rton plug, ed hole wi k. hulls, gh drill p d. Set pl sx. cement	o 540'. 20 sx. th heavy Halli- ipe. ug, 1/2 up to APF	RAHON T	feet to	
ne of Plugging Contractor	PLUGGED HOLE: Filled hole wit Set plug, 1/4 s cement through mud up to 200'. burton plug, 20 Filled hole to sk. hulls, Hall cellar zero. Job completed: (If additional de	ch heavy mak. hulls, drill pip Set plu sx. ceme 40' with iburton p	mid from Hallibu be. Fill lg, 1/4 s ent throu heavy mu lug, 10 -3-63.	f same and dept 3550' up t rton plug, ed hole wi k. hulls, gh drill p d. Set pl sx. cement	o 540'. 20 sx. th heavy Halli- ipe. ug, 1/2 up to APF	RAHON T	feet t	
ne of Plugging Contractor	PLUGGED HOLF: Filled hole wit Set plug, 1/4 s cement through mud up to 200'. burton plug, 20 Filled hole to sk. hulls, Hall cellar zero. Job completed:	ch heavy mak. hulls, drill pip Set plu sx. ceme 40' with iburton p	mid from Hallibu be. Fill lg, 1/4 s ent throu heavy mu lug, 10 -3-63.	f same and dept 3550' up t rton plug, ed hole wi k. hulls, gh drill p d. Set pl sx. cement	o 540'. 20 sx. th heavy Halli- ipe. ug, 1/2 up to APF	RAHON T	feet t	
ne of Plugging Contractorlress	PLUGGED HOIF: Filled hole wit Set plug, 1/4 s cement through mud up to 200'. burton plug, 20 Filled hole to sk. hulls, Hall cellar zero. Job completed: (If additional de STERRA PETROIFUM EN 208 PETROIFUM EN	ch heavy notes he heavy notes he heavy notes he heavy notes he	mid from Hallibu be. Fill lg, 1/4 s ent throu heavy mu heavy mu lug, 10 -3-63.	f same and dept 3550' up tron plug, ed hole wi k. hulls, gh drill p d. Set pl Sx. cement of this sheet) KANSAS	o 540'. 20 sx. th heavy Halli- ipe. ug, 1/2 up to APF	RAHON T	963	
ntroducing it into the hole. If feet for each plu feet for each plu ne of Plugging Contractor ress TE OF	PLUGGED HOLE: Filled hole wit Set plug, 1/4 s cement through mud up to 200'. burton plug, 20 Filled hole to sk. hulls, Hall cellar zero. Job completed: (If additional de STERRA PETROLEU) 208 PETROLEUM BE	th heavy not hea	mid from Hallibu be. Fill lg, 1/4 s ent throu heavy mu hlug, 10 -3-63. Sary, use BACK of C. WICHITA, RUSSELI	f same and dept 3550' up t rton plug, ed hole wi k. hulls, gh drill p d. Set pl sx. cement of this sheet) KANSAS	o 540'. 20 sx. th heavy Halli- ipe. ug, 1/2 up to APF CONSER With	RAHON TO	963	
ne of Plugging Contractor ress TE OF	PLUGGED HOIF; Filled hole wit Set plug, 1/4 s cement through mud up to 200'. burton plug, 20 Filled hole to sk. hulls, Hall cellar zero. Job completed: (If additional de SIERRA PETROIFUM ED COUNT) 208 PETROIFUM ED COUNT, DRILLING SUPERIS	th heavy mak. hulls, drill pip Set plu Sx. ceme 40' with iburton put 4 p.m. 4 p	mid from Hallibu be. Fill lg, 1/4 s ent throu heavy mu heavy mu lug, 10 -3-63. Sary, use BACK of C. WICHITA, RUSSELI mployee of or acis, statement	f same and dept 3550' up t rton plug, ed hole wi k. hulls, gh drill p d. Set pl sx. cement of this sheet) KANSAS	o 540'. 20 sx. th heavy Halli- ipe. ug, 1/2 up to APF CONSER With	RAHON TO	963	
ne of Plugging Contractorlress	PLUGGED HOIF: Filled hole wit Set plug, 1/4 s cement through mud up to 200'. burton plug, 20 Filled hole to sk. hulls, Hall cellar zero. Job completed: (If additional de STERRA PETROIFUM EN COUNT) 208 PETROIFUM EN COUNT, DRILLING SUPERT! th, says: That I have know that the same are true and countered to see the same are true	sused, state the back, hulls, drill pip Set plu Sx. ceme 40' with iburton pure 40' with iburton pure 40' with iburton pure 50' with	mid from Hallibu be. Fill lg, 1/4 s ant throu heavy mu llug, 10 -3-63. Sary, use BACK of C. WICHITA, RUSSELI mployee of ovacts, statemer elp me God.	asame and dept 3550' up t rton plug, ad hole wi k. hulls, gh drill p d. Set pl sx. cement of this sheet) KANSAS wher) or (owne tts, and matters	o 540'. 20 sx. th heavy Halli- ipe. up to API CONSER With ss. r or operator) of herein contained	of the aboved and the	963 ve-described e log of the	
me of Plugging Contractorlress	PLUGGED HOIF: Filled hole wit Set plug, 1/4 s cement through mud up to 200'. burton plug, 20 Filled hole to sk. hulls, Hall cellar zero. Job completed: (If additional de STERRA PETROIFUM EN COUNT) 208 PETROIFUM EN COUNT, DRILLING SUPERT! th, says: That I have know that the same are true and countered to see the same are true	th heavy mak. hulls, drill pip Set plu Sx. ceme 40' with iburton put 4 p.m. 4 p	mid from Hallibu be. Fill lg, 1/4 s ant throu heavy mu llug, 10 -3-63. Sary, use BACK of C. WICHITA, RUSSELI mployee of ovacts, statemer elp me God.	asame and dept 3550' up t rton plug, ad hole wi k. hulls, gh drill p d. Set pl sx. cement of this sheet) KANSAS wher) or (owne tts, and matters	o 5401. 20 sx. th heavy Halli- ipe. ug, 1/2 up to API CONSER with ss. r or operator) of herein contained C. T. HON	RAHON C	ye-described e log of the	
ne of Plugging Contractorlress	PLUGGED HOIF: Filled hole wit Set plug, 1/4 s cement through mud up to 200'. burton plug, 20 Filled hole to sk. hulls, Hall cellar zero. Job completed: (If additional de STERRA PETROIFIUM BETTERNA PETROI	h heavy mak. hulls, drill pip Set plu Sx. ceme 40' with iburton put 4 p.m. 4 p.	mid from Hallibu be. Fill lg, 1/4 s ant throu heavy mu llug, 10 -3-63. RUSSELI mployee of ov acts, statemer elp me God.	asame and dept 3550' up t rton plug, ed hole wi k. hulls, gh drill p d. Set pl sx. cement of this sheet) KANSAS wher) or (owne ets, and matters	o 540'. 20 sx. th heavy Halli- ipe. up to API CONSER With ss. r or operator) of herein contained	RAHON C	ye-described e log of the	
ne of Plugging Contractor	PLUGGED HOIF: Filled hole wit Set plug, 1/4 s cement through mud up to 200'. burton plug, 20 Filled hole to sk. hulls, Hall cellar zero. Job completed: (If additional de STERRA PETROIFIUM BETTERNA PETROI	sused, state the back, hulls, drill pip Set plu Sx. ceme 40' with iburton pure 40' with iburton pure 40' with iburton pure 50' with	mid from Hallibu be. Fill lg, 1/4 s ant throu heavy mu llug, 10 -3-63. RUSSELI mployee of ov acts, statemer elp me God.	asame and depth assume and depth assume and depth assume a	o 5401. 20 sx. th heavy Halli- ipe. ug, 1/2 up to API CONSER Win ss. r or operator) of herein contained C. T. HON BOX 232,	RAHON C	ye-described e log of the	
ne of Plugging Contractor	PLUGGED HOLE: Filled hole wit Set plug, 1/4 s cement through mud up to 200'. burton plug, 20 Filled hole to sk. hulls, Hall cellar zero. Job completed: COUNT 208 PETROLEU 208 PETROLEU 208 PETROLEU 6, says: That I have know that the same are true and country in the same are true and country for the same are t	h heavy mak. hulls, drill pip Set plu Sx. ceme 40' with iburton put 4 p.m. 4 p.	mid from Hallibu be. Fill lg, 1/4 s ant throu heavy mu llug, 10 -3-63. RUSSELI mployee of ov acts, statemer elp me God.	asame and dept 3550' up t rton plug, ed hole wi k. hulls, gh drill p d. Set pl sx. cement of this sheet) KANSAS wher) or (owne ets, and matters	o 5401. 20 sx. th heavy Halli- ipe. ug, 1/2 up to API CONSER Win ss. r or operator) of herein contained C. T. HON BOX 232,	of the aboved and the RUSSEI	ye-described e log of the	

324 Mc Culloch Older Obmulyce, Oblas EXCALIBER CORPORATION - Operator

|5-163-01079-00-00 SIERRA PETRO. CO., INC. - Contractor

HORNER #1 SW SE SE

Sec. 32-85-19W

Rooks County, Kansas

Commenced: 3-27-63 Completed: 4-3-63

Casing:

Cement:

8-5/8" Set at 206'

FORMATION

with 135 sx. Pozmix

T. D.: 3550' Elev.: 2038' D.F.

Sand & Clay Shale
Sand & Shale
Red Bed
Anhydrite
Shale & Shells
Lime & Shale
Lime
Lime & Shale
Arbuckle

JEP?	'H
160)
955	5
1180)
1461	
1493	}
2215	,
3010	1
3465	;
3520	!
3550	

STATE CORPORATION COMMISSION APR 5 1963 CONSERVATION DIVIN Wichita, Kansas

STATE OF KANSAS SS: COUNTY OF RUSSELL

1963.

I hereby certify that the above information is true and correct to the best of my knowledge.

Subscribed and sworn to before me this 4th day of April,

My commission expires: 10-17-63