3 To:		at this well was drilled in the 1980's 15-205- \9433-00-00
STATE CORPORATION COMMISSION		Sec/Twp/Rge <u>26-29-15E</u>
Wichita State Office Bldg PLUGGING SECTION		) feet from south section line
130 S. Market, Room 2078 Wichita, Kansas 67202	4950	geet from east section line 35.
TECHNICIAN'S PLUGGING REPORT	Lease/Well#	Hall # 4
Operator License # 33074	County	Wilson
Operator: Dart Cherokee Basin Operating	Well Total Depth	1100 feet
Name & 211 W. Myrtle	Production Pipe:	4.5 Size Feet1100
Address Independence, KS 67301	Surface Casing:	7 Size Feet20
AB oil well XXXXXX Gas Well SWD	Well/ Input Well	D&A
Other well as hereinafter indicated:		
Plugging Contractor: WW Production Company		Lic. #5491
Address: 1150 Highway 39, Chanute, Kansas 66720		
Company to plug at: Hour: Day:	11	Month:1 2007
Plugging proposal received from: Tony Williams		
Company Name: Dart Cherokee Basin Operating		Phone: 620-331-7870
Were: Run cement string to TD and plug from btm to	top thru cement	string.
Plugging Proposal Re	ceived by:	John Almond
	•	TECHNICIAN
Plugging attended by Agent: All	Part	TECHNICIAN None XXXXXX
Plugging attended by Agent: All  Operations Completed: Hour: Day:	Part 11	TECHNICIAN   None   XXXXXX
Plugging attended by Agent:  Operations Completed: Hour:  Actual Plugging Report:  A one inch cement str	Part 11 ing was lowered d	TECHNICIAN None XXXXXX  Month: 1 2007 own the inside of the 4.5 inch pipe
Plugging attended by Agent:  Operations Completed: Hour:  Actual Plugging Report:  A one inch cement str.  to 1100 ft. The well was plugged from btm to top thru this	Part 11 ing was lowered descement string. T	TECHNICIAN None XXXXXX  Month: 1 2007 own the inside of the 4.5 inch pipe The one inch cement string was
Plugging attended by Agent: All  Operations Completed: Hour: Day:  Actual Plugging Report: A one inch cement str  to 1100 ft. The well was plugged from btm to top thru this removed and the well topped with cement. Altogether, 1	Part  11 ing was lowered descement string. To the content of the c	Month: 1 2007  own the inside of the 4.5 inch pipe The one inch cement string was and cement were used to plug well.
Plugging attended by Agent:  Operations Completed: Hour:  Actual Plugging Report:  A one inch cement str.  to 1100 ft. The well was plugged from btm to top thru this	Part  11 ing was lowered descement string. To the content of the c	TECHNICIAN None XXXXXX  Month: 1 2007  own the inside of the 4.5 inch pipe The one inch cement string was and cement were used to plug well.
Plugging attended by Agent: All  Operations Completed: Hour: Day:  Actual Plugging Report: A one inch cement str  to 1100 ft. The well was plugged from btm to top thru this removed and the well topped with cement. Altogether, 1	Part  11 ing was lowered descement string. To the content of the c	Month: 1 2007  own the inside of the 4.5 inch pipe The one inch cement string was and cement were used to plug well.
Plugging attended by Agent: All  Operations Completed: Hour: Day:  Actual Plugging Report: A one inch cement str  to 1100 ft. The well was plugged from btm to top thru this removed and the well topped with cement. Altogether, 1	Part  11 ing was lowered descement string. To the content of the c	TECHNICIAN None XXXXXX  Month: 1 2007  own the inside of the 4.5 inch pipe The one inch cement string was not cement were used to plug well.  RECEIVED KANSAS CORPORATION COMMISSION  AUG 8 6 2007  CONSERVATION DIVISION
Plugging attended by Agent:  Operations Completed: Hour:  Actual Plugging Report:  A one inch cement str.  The well was plugged from btm to top thru this removed and the well topped with cement. Altogether, 1.  The wellhead was cut off below plow depth and the locat Remarks: Unsure of previous operator.	Part  11  ing was lowered does cement string. To the sacks of portlar ion restored.  DATE OF THE SAME	TECHNICIAN None XXXXXX  Month: 1 2007  own the inside of the 4.5 inch pipe The one inch cement string was and cement were used to plug well.  RECEIVED KANSAS CORPORATION COMMISSION  AUG 8 6 2007
Plugging attended by Agent: All  Operations Completed: Hour: Day:  Actual Plugging Report: A one inch cement str to 1100 ft. The well was plugged from btm to top thru this removed and the well topped with cement. Altogether, 1  The wellhead was cut off below plow depth and the locat  Remarks: Unsure of previous operator.  (If additional description is necessary, use	Part  11  ing was lowered does cement string. To the sacks of portlar ion restored.  DATE OF THE SAME	TECHNICIAN None XXXXXX  Month: 1 2007  own the inside of the 4.5 inch pipe The one inch cement string was not cement were used to plug well.  RECEIVED KANSAS CORPORATION COMMISSION  AUG 8 6 2007  CONSERVATION DIVISION
Plugging attended by Agent:  Operations Completed: Hour:  Actual Plugging Report:  A one inch cement str.  The well was plugged from btm to top thru this removed and the well topped with cement. Altogether, 1.  The wellhead was cut off below plow depth and the locat Remarks: Unsure of previous operator.	Part  11  ing was lowered does cement string. To the sacks of portlar ion restored.  DATE OF THE SAME	TECHNICIAN None XXXXXX  Month: 1 2007  own the inside of the 4.5 inch pipe The one inch cement string was not cement were used to plug well.  RECEIVED KANSAS CORPORATION COMMISSION  AUG 8 6 2007  CONSERVATION DIVISION