

KANSAS

Form CP-3
REREX 1 V6-42-68
STATE CONFORMISSION

STATE CORPORATION COMMISSION

CONSERVATION DIVISION AGENT'S REPORT

FEB 1 1 1977

CONSERVATION DIVISION

Wichita, Kansas

J. Lewis Brock
Administrator
245 North Water
Wichita, KS 67202

4626-6

MV. NO. _

API Number 15 - 163 - 20,676-00-00 (of this well)

Complete Address	117 E. 10th.	lavs. Kansas	
State Agencia State Stat			
Lease Name	Schmidt	Well No. 1	····
Location	nw se sw	Sec30 _{Twp} 10 _{Rge} (E)	_(W)
County	Rooks	Total Depth 3325°	
Abandoned Oil Well	Gas Well	Input Well SWD Well D &	A X
Other well as hereafte	er indicated		
Plugging Contractor_			ATT MINE O. COLOM
Address	Wichita, Kansas	License No.	·····
Operation Completed:	Hour 7 P	y 9 Month 2 Year 19	
		des parties des la company de l'apparent de l'apparent	· · · · · ·
The above well was plu	gged as follows:		
		Plg. Mat. 50-50 poz 6% total gal	
RTD 3325 8 5/8 csg	set 210° cwc 140 sx.	Plg. Mat. 50-50 poz 6% total gel.	, and the desirement of the second
RTD 3325! 8 5/8 csg	set 210° cwc 140 sx.	Plg. Mat. 50-50 poz 6% total gel. k cmt plug at 600° thru drill pipe.	
RTD 3325 8 5/8 csg	set 210° cwc 140 sx. d heavy mud, set 70 s	k cmt plug at 600° thru drill pipe.	en der Vollen und den aus
RTD 3325 8 5/8 csg Gunned pits, circulate Heavy mud to 185° set	set 210° cwc 140 sx. d heavy mud, set 70 s 20 sk cmt plug thru d	k cmt plug at 600° thru drill pipe. rill pipe. Heavy mud to 40° set solid	
Gunned pits, circulate	set 210° cwc 140 sx. d heavy mud, set 70 s 20 sk cmt plug thru d	k cmt plug at 600° thru drill pipe.	
RTD 3325 8 5/8 csg Gunned pits, circulate Heavy mud to 185° set	set 210° cwc 140 sx. d heavy mud, set 70 s 20 sk cmt plug thru d	k cmt plug at 600° thru drill pipe. rill pipe. Heavy mud to 40° set solid	
RTD 3325 8 5/8 csg Gunned pits, circulate Heavy mud to 185° set	set 210° cwc 140 sx. d heavy mud, set 70 s 20 sk cmt plug thru d	k cmt plug at 600° thru drill pipe. rill pipe. Heavy mud to 40° set solid	
RTD 3325 8 5/8 csg Gunned pits, circulate Heavy mud to 185° set	set 210° cwc 140 sx. d heavy mud, set 70 s 20 sk cmt plug thru d	k cmt plug at 600° thru drill pipe. rill pipe. Heavy mud to 40° set solid	
RTD 3325 8 5/8 csg Gunned pits, circulate Heavy mud to 185° set	set 210° cwc 140 sx. d heavy mud, set 70 s 20 sk cmt plug thru d	k cmt plug at 600° thru drill pipe. rill pipe. Heavy mud to 40° set solid	
RTD 3325 8 5/8 csg Gunned pits, circulate Heavy mud to 185° set	set 210° cwc 140 sx. d heavy mud, set 70 s 20 sk cmt plug thru d	k cmt plug at 600° thru drill pipe. rill pipe. Heavy mud to 40° set solid	
RTD 3325 8 5/8 csg Gunned pits, circulate Heavy mud to 185° set bridge & 10 sk cmt plu	set 210° cwc 140 sx. d heavy mud, set 70 s 20 sk cmt plug thru c g to base of cellar.	k cmt plug at 600° thru drill pipe. rill pipe. Heavy mud to 40° set solid	
RTD 3325 8 5/8 csg Gunned pits, circulate Heavy mud to 185° set oridge & 10 sk cmt plu	set 210° cwc 140 sx. d heavy mud, set 70 s 20 sk cmt plug thru c g to base of cellar.	k cmt plug at 600° thru drill pipe. rill pipe. Heavy mud to 40° set solid	