

Notice: Fill out COMPLETELY and return to Conservation Division at the address below within 60 days from plugging date.

**KANSAS CORPORATION COMMISSION
OIL & GAS CONSERVATION DIVISION
WELL PLUGGING RECORD
K.A.R. 82-3-117**

Form CP-4
December 2003
**Type or Print on this Form
Form must be Signed
All blanks must be Filled**

Lease Operator: Siroky Oil Management, Inc.
 Address: P.O. Box 464, Pratt, KS 67124
 Phone: (620) 672 -5625 Operator License #: 3959
 Type of Well: oil Docket #: _____
 (Oil, Gas D&A, SWD, ENHR, Water Supply Well, Cathodic, Other) (If SWD or ENHR)
 The plugging proposal was approved on: _____ (Date)
 by: _____ (KCC District Agent's Name)
 Is ACO-1 filed? Yes No If not, is well log attached? Yes No
 Producing Formation(s): List All (If needed attach another sheet)
 _____ Depth to Top: _____ Bottom: _____ T.D. _____
 _____ Depth to Top: _____ Bottom: _____ T.D. _____
 _____ Depth to Top: _____ Bottom: _____ T.D. _____

API Number: 15 - 097-20778-00-00
 Lease Name: Hoff
 Well Number: #1-13
 Spot Location (QQQQ): SE - NE - - -
3300 Feet from North / South Section Line **KCC PKT**
660 Feet from East / West Section Line **PN CP43**
 Sec. 13 Twp. 27 S. R. 16 East West
 County: Kiowa
 Date Well Completed: _____
 Plugging Commenced: 09/20/07
 Plugging Completed: 09/24/07

Show depth and thickness of all water, oil and gas formations.

Oil, Gas or Water Records		Casing Record (Surface Conductor & Production)				
Formation	Content	From	To	Size	Put In	Pulled Out

Describe in detail the manner in which the well is plugged, indicating where the mud fluid was placed and the method or methods used in introducing it into the hole. If cement or other plugs were used, state the character of same depth placed from (bottom), to (top) for each plug set.

To location and rigged up sand pump. Tagged btm @ 4500' down. Pulled sand pump and poured 140 of sand. Went down w/ bailer, btm is 3900' down. Pulled bailer and poured 4 sks cement. Pulled csg slips. Work csg up & down then ran csg knife and knocked csg @ 2100'. Work it and came up @ 2000'. Knock csg out and pulled 23 Jts-4 1/2" csg. Pour cement, then pulled 15 Jts-4 1/2" csg. Poured cement, then pulled 12'-4 1/2" csg. Poured cement to surface. - 135 sks 60.40 poz

Name of Plugging Contractor: Genesis Well Service, Inc. License #: 33093
 Address: P.O. Box 464, Pratt, KS 67124

**RECEIVED
KANSAS CORPORATION COMMISSION**

Name of Party Responsible for Plugging Fees: Siroky Oil Management, Inc.
 State of Kansas County, Pratt, ss.
Brian Siroky, President
 (Employee or Operator) or (Operator) on above-described Well, being first duly

NOV 07 2007

**CONSERVATION DIVISION
WICHITA, KS**

sworn on oath, says: That I have knowledge of the facts statements, and matters herein contained, and the log of the above-described well is as filed, and the same are true and correct, so help me God.

(Signature) [Signature]
 (Address) P.O. Box 464, Pratt, KS 67124

SUBSCRIBED and SWORN TO before me this 2 day of November
[Signature] My Commission Expires: _____
 Notary Public

AMY S. ROBERTSON
 Notary Public - State of Kansas
 My Appt. Expires 3/13/08

Mail to: KCC - Conservation Division, 130 S. Market - Room 2078, Wichita, Kansas 67202

[Handwritten initials]