

Re-entry of Plugged, Abandoned Well

J02

15-163-21806-00-01

O.W.W.O.

Mr. _____ of Ostrom Well Service (Contractor)Address Drawer 368 Plainville, Ks Contact Person _____ Phone: 434-2707KCC License Number 5680 Rig Tag # 296 API # of Intent 15-163-21806-AOPERATOR Kenny Brown Enterprises (5537) Elevation 1957 Fla 2 R.B. G.L.ADDRESS P.O. Drawer 340 Plainville, Ks 67663Contact Person Kenny Brown Phone No. 434-7236LEASE NAME Maddy #1 WELL NO. W64 Sec. 15 Twp 8 Rge 18Spud in Time noon Spud in Date 11/29/82 Rocks

Remarks:

179' S.P.

If a State Representative is not on location: Keep track of where you hit and run out of each plug. Take one sample of cement from each plug, and put sample in a bag, label it and record the top and bottom depth of each plug. (below)

A field agent will contact you and pick up the samples.

Initial Plug (completed by field agent)Drill out Plug (completed by driller)1st plug @ 0 ft. to 40 ft.1st plug 0 ft. to 39 ft.2nd plug @ 80 ft. to 240 ft.2nd plug 210 ft. to 342 ft. hard offset3rd plug @ 380 ft. to 780 ft.3rd plug 654 ft. to 841 ft.4th plug @ 1270 ft. to 1350 ft.4th plug 1297 ft. to 1299 ft.

DRILLING SUPERVISOR

Signature

Signed Field Agent

P.S. Mail this report to: KDHE - KCC Field Office, 1014 Cody, Hays, Kansas 67601

Phone: 913-628-1200

100' Slip on 2 & 3 plugs
200' loss on 3 plugs

RECEIVED
STATE REPRESENTATIVE COMMISSION
12/6/82
DEC 6 1982
CONSERVATION DIVISION
Wichita, Kansas

OK
DUB

(Signature)

Kenny Brown