

STATE OF KANSAS  
STATE CORPORATION COMMISSION  
CONSERVATION DIVISION  
800 BITTING BUILDING  
WICHITA, KANSAS

WELL PLUGGING APPLICATION FORM

File One Copy

Lease Owner Westgate-Greenland Address 1009 Central Bldg, Wichita, Ks  
(Applicant)

Lease (Farm Name) Frazier Well No. 1

Well Location NW NE SW Sec. 33 Twp. 9 Rge 21 (E)-(W)

County Graham Field Name (if any) wildcat

Total Depth 3975 Oil  Gas  Dry Hole X

Was well log filed with application? yes. If not, explain:

Date and hour plugging is desired to begin February 21, 1953

Plugging of the well will be done in accordance with the Rules and Regulations of the State Corporation Commission, or with the approval of the following exceptions: Explain fully any exceptions desired.  
(Use an additional sheet if necessary)

Name of the person on the lease in charge of well for owner

Oscar Bridge Address Great Bend, Kansas

Name of Plugging Contractor Westgate Drilling Corporation

Address 1009 Central Building, Wichita 2, Kansas

Invoice covering assessment for plugging this well should be sent to Westgate-Greenland Oil Co Address 1009 Central Building, Wichita, Ks and payment will be guaranteed by applicant.

**PLUGGING**  
FILE SEC 33 T 9 R 21  
BOOK PAGE 81 LINE 3

RECEIVED  
STATE CORP. COMMISSION  
2/28/53  
FEB 28 1953

Harold A. Burt  
Applicant or Acting Agent

Date February 26, 1953



STATE OF KANSAS  
STATE CORPORATION COMMISSION  
CONSERVATION DIVISION  
800 BITTING BUILDING  
WICHITA, KANSAS

February 24, 1953

Well No.	1
Lease	Prezier
Description	N <sup>1</sup> NE SW 33-9-21W
County	Graham
File No.	81-3

Westgate-Greenland Oil Company  
109 Central Bldg.  
Wichita, Kansas

Settlement:

This letter is your authority to plug the above subject well, in accordance with the Rules and Regulations of the State Corporation Commission. When you are ready to plug this well, please contact our District Plugging Supervisor, Mr. Eldon Petty, Box 326, Hays, Kansas.

STATE CORPORATION COMMISSION  
CONSERVATION DIVISION

BY J. P. Roberts  
J. P. ROBERTS

cc: DISTRICT PLUGGING SUPERVISOR