4-5 15-163-19135-00-00

D-11,031

API number: 15- - 1-28-64 TOR STATE CORPORATION COMMISSION SW NW NE /4 SEC. 31 , 08 S, 17 W CONSERVATION DIVISION - PLUGGING feet from S section line 200 COLORADO DERBY BUILDING __ feet from E section line 2310 WICHITA, KANSAS 67202 Lease_Iruss well #_2 Operator license# 4074 County Rooks Operator: Innes Petroleum, Inc. Ron Innes ____ Well total depth <u>3500</u> feet Address: 229 East William O'Rourke Title Building Conductor Pipe: 0 inch @ 0 feet Wichita, Kansas 67202 Surface pipe 8 5/8 Inch @ 102 feet Aband. oil well ____, Gas well ____, Input well ____, SWD _X_, D & A ____ Plugging contractor: Northwest Well Service License# -Address: Hill City, Kansas 67642 Company to plug at: Hour: 11:00A.M Day: 5 Month: April Year: 95 Plugging proposal received from: Mike Vanausdale Company: Northwest Well Service Phone: 913-674-2852 Order 100 sxs. common cement and 300 sxs. 60/40 posmix - 8% gelwith 1/4# flocele per sack. Perforate at 1730'. Recovered 1889' of corroded, caked tubing with first hole at 960'. Tubing had corrosion holes, but was not "swiss cheese". Tubing parted at collar with collar looking up. Emergency permission to plug with rig over hole. Plugging Proposal Received by: Herb Deines Plugging operations attended by agent? All[X], Part[], None[Completed: Hour: 5:00P.M., Day: 5 , Month: April , Year: 95 Actual plugging report: 10 3/4" to 102' with 75 sxs. 7" to 3446'. D.V. at 1318' cemented to surface. Cleaned out bad tubing to 1889. Ran tubing to top of fish and pumped 100 sxs. common cement with 100# hulls at end of batch. Pulled tubing. Tied onto annulus and pumped 30 sxs. cement. Max. P.S.I. 400#. S.I.P. 25#. Tied onto production casing and pumped 270 sxs. cement with 150# hulls. Well on medium vacuum. Calculated volume fill, not enough to reach

TD. Ordered 250 sxs. 60/40 posmix - 10% gel and 500# hulls. Let well set for 3 hours. Tied onto production casing and

pumped 250 sxs. cement with 500# hulls. Max. P.S.I. 300#. S.I.P. 25#. Checked 3/4 hour later and still had pressure. Used total of 650 sxs. cement. Hole stable and full of cement. STATE CORPORATION COMMISSION APR / 2 1995 Remarks: Halliburton Cementing.

Condition of casing(in hole):GOOD BAD X Anhy.plug:YES X NO WICHTA KANSAG

Bottom plug(in place):YES ,CALC X ,NO Dakota plug:YES X ,NO Plugged through TUBING X , CASING X . Elevation: 1980 GL did not[] observe the plugging. DATE 4-13-95 例(agent) Form CP-2/3