Notice: Fill out COMPLETELY and return to Conservation Division at the address below within 60 days from plugging date.

Steven R Hash

same are true and correct, so help me God.

KANSAS CORPORATION COMMISSION OIL & GAS CONSERVATION DIVISION

WELL PLUGGING RECORD

Form CP-4 December 2003 Type or Print on this Form Form must be Signed All blanks must be Filled

K.A.R. 82-3-117 API Number: ____15 -_ .197.20256.00.00 Lease Operator: Berry Petroleum Company Lease Name:_SS Farms Address: 5201 Truxton Avanue, Suite 300 Bakersfield, CA 93309 8-23 Well Number: Phone: (661) 616 -3900 __ Operator License #: 33116 Spot Location (QQQQ): N2 - SE Type of Well: Gas D&A Docket #: -(Oil, Gas D&A, SWD, ENHR, Water Supply Well, Cathodic, Other) (If SWD or ENHR) Feet from North / South Section Line The plugging proposal was approved on: $\frac{5/17/07}{}$ Feet from East / West Section Line Twp.__ bv: Taylor Herman ____ (KCC District Agent's Name) If not, is well log attached? Is ACO-1 filed? Yes No Producing Formation(s): List All (If needed attach another sheet) Date Well Completed: ______ Depth to Top: 1800 Bottom: _____ T.D. _ Plugging Commenced: _ Bottom: ____ ____ T.D. _ Depth to Top:_ Plugging Completed: __ Bottom: ___ Depth to Top: __ Show depth and thickness of all water, oil and gas formations. Casing Record (Surface Conductor & Production) Oil, Gas or Water Records Pulled Out Content From То Size Put In Formation 352 0 0 352 8 5/8 Pleasanton 0 5 1/2 2342 0 2342 Marmaton Cherokee Mississippian Describe in detail the manner in which the well is plugged, indicating where the mud fluid was placed and the method or methods used in introducing it into the hole. If cement or other plugs were used, state the character of same depth placed from (bottom), to (top) for each plug set. Pump 17 bbl gelled water ahead of 25 sacks cement, spot bottom plug at 2158-2022', pull 22 jts tubing spot middle plug with 15 sacks cement at 1380-1260' POOH with 70 total its total 2 7/8" tubing. RIH perforate 1/ft, 4spf, 2 1/8" strip charges at 350' for squeeze holes Establish circulation, mix and pump 80 sacks cement thru perforations at 350' to surface. Cut off 8 5/8 and 5 1/2. Weld plate on top of 8-5/8 with date & API# SS Farms 8-23 plugged and abandoned 6/7/2007 per KCC regulations. RECEIVED KANSAS CORPORATION COMMISSION Name of Plugging Contractor: Consolidated Oil Well Services Address: 2631 Eisenhower Ave., Ottawa, Ks. 66067 FEB 0 1 2008 Name of Party Responsible for Plugging Fees: Berry Petroleum Company CONSERVATION DIVISION WICHITA, KS State of Oklahoma

> Steven R. Hash (Address) EXACT Engineering, Inc., 20 E 5th St, Ste 310, Tulsa, OK 74103 (918) 599-9400

SUBSCRIBED and SWORN, TO before me this 30th day of January

__ My Commission Expires: ____ Notary Public

_ (Employee of Operator) or (Operator) on above-described well, being first duly

Mail to: KCC - Conservation Division, 130 S. Market - Room 2078, Wichita, Kansas 67202

sworn on oath, says: That I have knowledge of the facts statements, and matters herein contained, and the log of the above-described well is as filed, and the

