

STATE OF KANSAS
STATE CORPORATION COMMISSION
CONSERVATION DIVISION
211 NORTH BROADWAY
WICHITA, KANSAS

WELL PLUGGING APPLICATION FORM

File one Copy

Lease Owner Aurora Gasoline Co. Address 802 Union Nat'l Bank Bldg. Wichita, Kans.
(applicant)

Lease (Farm Name) Dreiling Well No. 1

Well Location NW/4 NW/4 SW/4 Sec. 29 Twp. 8S Rge. 22 (~~E~~) - (W)

County Graham Field Name (if any) _____

Total Depth 3855 Oil ___ Gas ___ Dry Hole ___ Dry Hole ___

Was well log filed with application? Yes If not, explain: _____

Date and hour plugging is desired to begin August 18, 1955

Plugging of the well will be done in accordance with the Rules and Regulations of the State Corporation Commission.

Name of the person on the lease in charge of well for owner _____

Louis Bernd Address McPherson, Kansas

Plugging Contractor Veeder Supply & Development Co.

Plugging Contractor's License No. 115

Address Box 201, Cherryvale, Kansas

Invoice covering assessment for plugging this well should be sent to _____

Aurora Gasoline Co. Address 802 Union Nat'l Bank Bldg. Wichita, Kansas

and payment will be guaranteed by applicant.

RECEIVED
STATE CORPORATION COMMISSION

AUG 26 1955
AUG 26 1955
CONSERVATION DIVISION
Wichita, Kansas

Leo G. Veeder

Applicant or Acting Agent

Date August 20, 1955

PLUGGING
FILE SEC 29 T 8 R 22 W
BOOK PAGE 144 LINE 8



STATE OF KANSAS
STATE CORPORATION COMMISSION
CONSERVATION DIVISION
211 NORTH BROADWAY
WICHITA, KANSAS

August 22, 1955

Well No. 1
Lease J. P. Drilling
Description NW NW SW 29-8-12W
County Graham
File No. 114-8

Aurora Gasoline Company
802 Union National Bank Bldg.,
Wichita, Kansas

Gentlemen:

This letter is your authority to plug the above subject well, in accordance with the Rules and Regulations of the State Corporation Commission. When you are ready to plug this well, please contact our District Plugging Supervisor, Mr. Warren H. Horner, Box 207, Great Bend, Kansas.

STATE CORPORATION COMMISSION
CONSERVATION DIVISION

BY: S. S. Greider
S. S. Greider
WELL PLUGGING SUPERVISOR

cc:
District Plugging Supervisor