30 S. Market, Roc Vichita, KS 6720			-04-)-	117	API NUI	MBER 15-1	63-232910000										
					LEASE 1	NAME Gra	aham										
€		TYPE OF			WELL NI	UMBER 1											
	*• • •	TICE: Fill of and return	to Co	as. Dly			Section										
	• .	office with	hin 30	days.		· · · -	Section										
LEASE OPERATOR Thoroughbred Associates ADORESS 10 Colonial Court Wichita, KS 67207 PHONE/(316) 685-1512 OPERATORS LICENSE NO. 31514 Character of Well D & A						SEC. 12 TWP. 95 RGE. 16 (E) or (W											
					COUNTY Rooks												
									(OII, Gas, D&A, 5	SWD, Input, Water	Supply Well	I)				12-9-9	
										posal was approve			6				
by Ken							Agent's Na										
Is ACO-1 filed?							gen i s nai	14/									
	ion						7.5 3.504	,									
	hickness of all w						1.0. 3,304										
		rater, Gil ar	id gas		•		·										
OIL, GAS OR WATE					CASING RECO												
Formation	Content	From	To S	i ze	Put in	Pulled ou	it										
•				8 5/8"	217'	Cmtd_v	w/140 sax '										
185CFIDS IN CETAL				, ,,,,,,,,,,	iu, indicai			10									
Push plug to 1,	e the character 330', spot 25 sax dug thru drill ping to 40', dump 10	of same and cement on p	roduci d dep lug thi ug to 2	ing it ing it ing it in place ru drill 220', pu	into the home of the pipe. Pus	feet to h plug to 8	feet eac 340', pump 10	h :									
Push plug to 1, sax cement on p pipe. Push plu sax cement down	e the character 330', spot 25 sax alug thru drill ping to 40', dump 10 mouse hole.	cement on p	roduci d dep lug thi ug to 2 on pluc	ing it in the place of the plac	into the home of the pipe. Pus	feet to h plug to 8	feet eac 340', pump 10	h s									
Push plug to 1, sax cement on p pine Push plu sax cement down	aethod or methods e the character 330', spot 25 sax slug thru drill pi g to 40', dump 10 mouse hole. Contractor	cement on poe. Push place sax cement. Shields Dril	roduci d dep lug thi ug to 2 on pluc	ing it in the place of the plac	nte the he ed, from pipe. Pus mp 40 sax 15 sax cem	feet to h plug to 8	feet eac 340', pump 10 plug thru dr at hole and	h s									
Push plug to 1, sax cement on p pipe. Push plu sax cement down	e the character 330', spot 25 sax alug thru drill ping to 40', dump 10 mouse hole.	cement on poe. Push place sax cement. Shields Dril	roduci d dep lug thi ug to 2 on pluc	ing it in the place of the plac	nte the he ed, from pipe. Pus mp 40 sax 15 sax cem	h plug to 8 cement on rent down ra	feet eac 340', pump 10 plug thrw dr at hole and	h s									
Push plug to 1, sax cement on p pipe Push plug sax cement down lame of Plugging Address Shield	aethod or methods e the character 330', spot 25 sax slug thru drill pi g to 40', dump 10 mouse hole. Contractor	cement on poe. Push place sax cement Shields Dril	roducind dep lug through to 2 on plug	ing it lith place ru drill 220', pur g, dump	nte the he ed, from pipe. Pus mp 40 sax 15 sax cem	feet to h plug to 8 cement on re ent down ra	feet eac 340', pump 10 plug thrw dr at hole and	h s									
Push plug to 1, sax cement on p pipe Push plug sax cement down Name of Plugging Address Shield	contractor ds Bldg., Russell SPONSIBLE FOR PLU	cement on poe. Push place sax cement Shields Dril	roducind dep lug through to 2 on plug	ing it lith place ru drill 220', pur g, dump	nto the hosed, from pipe. Pusump 40 sax 15 sax cem	feet to h plug to 8 cement on re ent down ra	feet eac 340', pump 10 plug thrw dr at hole and	h s									