*	4-06
TO: 9-7	
STATE CORPORATION COMMISSION CONSERVATION DIVISION - PLUGGING	
130 SOUTH MARKET, SUITE 2078 WICHITA, KANSAS 67202	
Operator license#	
Operator: State of Kansas Fee Fund	
Address: 2301 E. 13th Street Hays, Kansas 67601	We: -
Petro-Pak Corporation	

Company: Kansas Corporation Commission

WLFL at 300'. WLTD 1180'.

Address:____

API Number: 15-163-21,199-00-00

____/4 SEC._____30_,_09__S,_20__W ____ feet from S section line 3960 3960 _____ feet from E section line Lease: Robertson-Baldwin Well # 1 County: Rooks __ Well total depth_____ feet Conductor Pipe: 0 inch @ 0 feet Surface pipe 8 5/8 Inch @ 244 feet Aband. oil well____, Gas well____, Input well____, SWD____, D & A_____ License# Plugging contractor: Company to plug at: Hour: 3:30 P.M. Day: 7 Month: September Year: 1995 Plugging proposal received from: District Staff #4 Phone: 913-628-1200 Were: Order 300 sxs 60/40 posmix - 10% gel and hulls. During clean out we encountered a lot of fas and hit metal at one point in lower Cedar Hills Sand. Appeared to be casing. RECEIVED STATE CORPORATION COMMISSION CON MANUALITY OF STORY Plugging Proposal Received by: Herb Deines Plugging operations attended by agent? All[X], Part[], None[Completed: Hour: <u>6:45 P.M.</u>, Day: <u>7</u>, Month: <u>September</u>, Year: <u>1995</u> Actual plugging report: 8 5/8" to 244' with 165 sxs. 4 1/2" to 3904' with 200 sxs. Cleaned out to 1829' with tubing and bit. Heavy build-up of iron sulfide in wellbore. Hole open with some tight spots remaining. Perforated at 1020' and 1800'. Ran tubing to 1829'. Mixed and pumped 50 sxs cement with 100# hulls. Pulled tubing to 900' and circulated cement with 50 sxs. Tied onto annulus and pumped 75 sxs cement with 100# hulls. Max. P.S.I. 500#. S.I.P. 250#. Tied onto production casing and pumped 125 sxs cement with 300# hulls. Max. Remarks: Allied Cementing-Randy's Well Service-Leo's Tank Service-Mercury Wireline. Condition of casing(in hole): GOOD_____ BAD_ X Anhy.plug: YES_ X NO__ Bottom plug(in place): YES X , CALC _____, NO_____ Dakota plug: YES X , NO__ Plugged through TUBING X , CASING . . Elevation:

I did[X] / did not[] observe the plugging.

P.S.I. 1000#. S.I.P. 500#.

(agent)

Form CP-2/3