Notice: Fill out COMPLETELY and return to Conservation Division at the address below within 60 days from plugging date.

Kansas Corporation Commission Oil & Gas Conservation Division

WELL PLUGGING RECORD K.A.R. 82-3-117

Form CP-4
December 2003
Type or Print on this Form
Form must be Signed
All blanks must be Filled

Address: 15820 Plymouth Road Wichita, Kansas 67230 Phone: (316) 733 - 5280	Lease Name: Nordhus-Drouhard Well Number: 2	
Type of Well: (Oil, Gas D&A, SWD, ENHR, Water Supply Well, Cathodic, Other) Docket #: (If SWD or ENHR)	1 2	
Type of Well: (Oil, Gas D&A, SWD, ENHR, Water Supply Well, Cathodic, Other) Docket #: (If SWD or ENHR)		
(If SWD or ENHR)	Spot Location (QQQQ): W2 - NW - SE -	sw \
The plugging proposal was approved on:(Date	1010 Feet from North / South Section	7
1-71	4540	-11
by: Steve Van Gieson (KCC District Agent's Name		. \
Is ACO-1 filed? Yes No If not, is well log attached? Yes No	County: Harper	y west
Producing Formation(s): List All (If needed attach another sheet)		
Depth to Top:Bottom: T.D.	Date Well Completed: 8-26-08	, <u>राष्ट्र</u> स
Depth to Top: Bottom: T.D	Plugging Commenced:	
Depth to Top: Bottom: T.D	Plugging Completed: 8-29-08	
Show depth and thickness of all water, oil and gas formations.		
	rd (Surface Conductor & Production)	
Formation Content From To Size	Put In Pulled Out	
8-5/8"	222 None	
5-1/2"	4661 3588	
ole. If cement or other plugs were used, state the character of same depth placed from (b	bottom), to (top) for each plug set.	nto the
nole. If cement or other plugs were used, state the character of same depth placed from (b. Plugged off bottom wiht sand to 4570' and 5 sxs. cement. Cut casing loose @3588',	pulled up to 1400', pumped 35 sxs cement, pulled up to	
nole. If cement or other plugs were used, state the character of same depth placed from (b. Plugged off bottom wiht sand to 4570' and 5 sxs. cement. Cut casing loose @3588',	pulled up to 1400', pumped 35 sxs cement, pulled up to surface. 60/40 pos, 4% gel. Plugging Comple	te.
note. If cement or other plugs were used, state the character of same depth placed from (be Plugged off bottom wiht sand to 4570' and 5 sxs. cement. Cut casing loose @3588', 900', pumped 35 sxs., pulled up to 270' and circulated 80 sxs. cement to	pulled up to 1400', pumped 35 sxs cement, pulled up to surface. 60/40 pos, 4% gel. Plugging Comple	te.
Plugged off bottom wiht sand to 4570' and 5 sxs. cement. Cut casing loose @3588', 900', pumped 35 sxs., pulled up to 270' and circulated 80 sxs. cement to same of Plugging Contractor. Mike's Testing & Salvage, inc.	pulled up to 1400', pumped 35 sxs cement, pulled up to so surface. 60/40 pos, 4% gel. Plugging Comple KANSAS CORPORAT License #: 31529 SEP 24	te. IVEL ION COM
Plugging Contractor: Mike's Testing & Salvage, inc. Plugging Contractor: Mike's Testing & Salvage, inc. Plugging P.O. Box 467 Chase, Kansas 67524	pulled up to 1400', pumped 35 sxs cement, pulled up to surface. 60/40 pos, 4% gel. Plugging Comple	IVEL ION COM
Describe in detail the manner in which the well is plugged, indicating where the mud fluid wannels. If cement or other plugs were used, state the character of same depth placed from (b. Plugged off bottom wiht sand to 4570' and 5 sxs. cement. Cut casing loose @3588', 900', pumped 35 sxs., pulled up to 270' and circulated 80 sxs. cement to same of Plugging Contractor. Mike's Testing & Salvage, inc. Name of Plugging Contractor. Mike's Testing & Salvage, inc. Address: P.O. Box 467 Chase, Kansas 67524 Name of Party Responsible for Plugging Fees: Bullseye Petroleum, Inc. State of Kansas County, Rice	pulled up to 1400', pumped 35 sxs cement, pulled up to so surface. 60/40 pos, 4% gel. Plugging Comple KANSAS CORPORAT License #: 31529 CONSERVATION	IVEL ION COM