	API number: 15-193-20,622-00-00
STATE CORPORATION COMMISSION	li
CONSERVATION DIVISION - PLUGGING	NE SE SE /4 SEC. 36 , 09 S, 32 W
200 COLORADO DERBY BUILDING	feet from S section line
WICHITA, KANSAS 67202	feet from E section line
	1
Operator license# <u>30407</u>	Lease Nye well # 2
	į.
Operator: Black Petroleum Company	County Thomas
Operator: Black Petroleum Company Address: P.O. Box 12922	(0,2)
Address: P.O. Box 12922	Well total depth 4626 feet
Wichita, Kansas 67277	Conductor Pipe: 0 inch @ 0 feet
Thomas E. Black	Surface pipe 8 5/8 Inch @ 315 feet
	· · · · · · · · · · · · · · · · · · ·
Aband. oil well, Gas well, Inpu	ut well , SWD , D & A X
· •	
Plugging contractor: White & Ellis Dri	lling License#
Address: Great Bend, Kansas 67530	
	le .
Company to plug at: Hour: P.M. Day:	27 Month: April Year: 94
Plugging proposal received from: Judy a	and Don Demel
	!
Company: White & Ellis Drilling	Phone: 316-942-2741
Were: 8 5/8" - 315' 8.P. cwc. w/190	sxs. 60/40 pozmix - 2% gel - 3%
C.C. By Allied Cement. Elv. @ 3062' -	- Anhy @ 2616' - Miss well - No
circulation problems - Mud condition 63	l vis 9.3 wt 1500 ppm cl.
Proposal 190 sxs. 60/40 pozmix - 6% gel	l and 1 sx. flocele - circulate
hole - spot and displace all cement thi	rough tubing - boson mud between
	roudh cubing - neavy mud between
all plugs - no arbuckle. 25 sxs. @ 2620	order tubing - heavy mud between 1 - 100 sxs. w/1 sx. flocele @
all plugs - no arbuckle. 25 sxs. @ 2620)' - 100 sxs. w/1 sx. flocele @
all plugs - no arbuckle. 25 sxs. @ 2620 1810' - 40 sxs. @ 360' - 10 sxs. @ 40')' - 100 sxs. w/1 sx. flocele @
all plugs - no arbuckle. 25 sxs. @ 2620 1810' - 40 sxs. @ 360' - 10 sxs. @ 40'	- 100 sxs. w/1 sx. flocele @ - 15 sxs. in rathole (circulate)
all plugs - no arbuckle. 25 sxs. @ 2620 1810' - 40 sxs. @ 360' - 10 sxs. @ 40' Plugging Proposal Received by: Marion	J. Schmidt
all plugs - no arbuckle. 25 sxs. @ 2620 1810' - 40 sxs. @ 360' - 10 sxs. @ 40'	J. Schmidt
all plugs - no arbuckle. 25 sxs. @ 2620 1810' - 40 sxs. @ 360' - 10 sxs. @ 40' Plugging Proposal Received by: Marion Plugging operations attended by agent?	J. Schmidt All[], Part[], None[X]
all plugs - no arbuckle. 25 sxs. @ 2620 1810' - 40 sxs. @ 360' - 10 sxs. @ 40' Plugging Proposal Received by: Marion	J. Schmidt All[], Part[], None[X]
all plugs - no arbuckle. 25 sxs. @ 2620 1810' - 40 sxs. @ 360' - 10 sxs. @ 40' Plugging Proposal Received by: Marion Plugging operations attended by agent? Completed: Hour: 5:45P.M., Day: 27, Mor Actual plugging report: White and Elli	J. Schmidt All[], Part[], None[X] th: April , Year: 94
all plugs - no arbuckle. 25 sxs. @ 2620 1810' - 40 sxs. @ 360' - 10 sxs. @ 40' Plugging Proposal Received by: Marion Plugging operations attended by agent? Completed: Hour: 5:45P.M., Day: 27, Mor Actual plugging report: White and Elli	J. Schmidt All[], Part[], None[X] th: April , Year: 94
all plugs - no arbuckle. 25 sxs. @ 2620 1810' - 40 sxs. @ 360' - 10 sxs. @ 40' Plugging Proposal Received by: Marion Plugging operations attended by agent? Completed: Hour: 5:45P.M., Day: 27, Mor Actual plugging report: White and Elli 6% gel and 1 sx. flocele. Circulated by cement through drill pipe - heavy mud by the same of the complete of the system.	J. Schmidt All[], Part[], None[X] th: April , Year: 94 s ordered 190 sxs. 60/40 pozmix - nole - spotted and displaced all
all plugs - no arbuckle. 25 sxs. @ 2620 1810' - 40 sxs. @ 360' - 10 sxs. @ 40' Plugging Proposal Received by: Marion Plugging operations attended by agent? Completed: Hour: 5:45P.M., Day: 27, Mor Actual plugging report: White and Elli 6% gel and 1 sx. flocele. Circulated by cement through drill pipe - heavy mud by the same of the complete of the system.	J. Schmidt All[], Part[], None[X] th: April , Year: 94 s ordered 190 sxs. 60/40 pozmix - nole - spotted and displaced all
all plugs - no arbuckle. 25 sxs. @ 2620 1810' - 40 sxs. @ 360' - 10 sxs. @ 40' Plugging Proposal Received by: Marion Plugging operations attended by agent? Completed: Hour: 5:45P.M., Day: 27, Mor Actual plugging report: White and Elli 6% gel and 1 sx. flocele. Circulated by cement through drill pipe - heavy mud be 1st. plug @ 2620' w/25 sxs. cement. 2nd. plug @ 1810' w/100 sxs. cement with	J. Schmidt All[], Part[], None[X] th: April , Year: 94 s ordered 190 sxs. 60/40 pozmix - nole - spotted and displaced all
all plugs - no arbuckle. 25 sxs. @ 2620 1810' - 40 sxs. @ 360' - 10 sxs. @ 40' Plugging Proposal Received by: Marion Plugging operations attended by agent? Completed: Hour: 5:45P.M., Day: 27, Mor Actual plugging report: White and Elli 6% gel and 1 sx. flocele. Circulated the cement through drill pipe - heavy mud the st. plug @ 2620' w/25 sxs. cement. 2nd. plug @ 1810' w/100 sxs. cement with 3rd. plug @ 360' w/40 sxs. cement.	J. Schmidt All[], Part[], None[X] Ath: April , Year: 94 As ordered 190 sxs. 60/40 pozmix - nole - spotted and displaced all petween all plugs.
all plugs - no arbuckle. 25 sxs. @ 2620 1810' - 40 sxs. @ 360' - 10 sxs. @ 40' Plugging Proposal Received by: Marion Plugging operations attended by agent? Completed: Hour: 5:45P.M., Day: 27, Mor Actual plugging report: White and Elli 6% gel and 1 sx. flocele. Circulated homent through drill pipe - heavy mud homent through drill pipe - heavy mud homent plug @ 2620' w/25 sxs. cement. 2nd. plug @ 1810' w/100 sxs. cement with 3rd. plug @ 360' w/40 sxs. cement. 4th. plug @ 40' w/10 sxs. cement.	J. Schmidt All[], Part[], None[X] th: April , Year: 94 s ordered 190 sxs. 60/40 pozmix - nole - spotted and displaced all
all plugs - no arbuckle. 25 sxs. @ 2620 1810' - 40 sxs. @ 360' - 10 sxs. @ 40' Plugging Proposal Received by: Marion Plugging operations attended by agent? Completed: Hour: 5:45P.M., Day: 27, Mor Actual plugging report: White and Elli 6% gel and 1 sx. flocele. Circulated the cement through drill pipe - heavy mud the st. plug @ 2620' w/25 sxs. cement. 2nd. plug @ 1810' w/100 sxs. cement with 3rd. plug @ 360' w/40 sxs. cement.	J. Schmidt All[], Part[], None[X] Ath: April , Year: 94 Is ordered 190 sxs. 60/40 pozmix - nole - spotted and displaced all between all plugs. STATE CORPORATION COMMISSION AND STATE OF THE
all plugs - no arbuckle. 25 sxs. @ 2620 1810' - 40 sxs. @ 360' - 10 sxs. @ 40' Plugging Proposal Received by: Marion Plugging operations attended by agent? Completed: Hour: 5:45P.M., Day: 27, Mor Actual plugging report: White and Elli 6% gel and 1 sx. flocele. Circulated rement through drill pipe - heavy mud rest. plug @ 2620' w/25 sxs. cement. 2nd. plug @ 1810' w/100 sxs. cement with 3rd. plug @ 360' w/40 sxs. cement. 4th. plug @ 40' w/10 sxs. cement. 15 sxs. in rathole (circulate)	J. Schmidt All[], Part[], None[X] Ath: April , Year: 94 As ordered 190 sxs. 60/40 pozmix - nole - spotted and displaced all between all plugs. STATE CORPORATION COMMICSION CONSERVATOS - 1994
all plugs - no arbuckle. 25 sxs. @ 2620 1810' - 40 sxs. @ 360' - 10 sxs. @ 40' Plugging Proposal Received by: Marion Plugging operations attended by agent? Completed: Hour: 5:45P.M., Day: 27, Mor Actual plugging report: White and Elli 6% gel and 1 sx. flocele. Circulated rement through drill pipe - heavy mud rest. plug @ 2620' w/25 sxs. cement. 2nd. plug @ 1810' w/100 sxs. cement with 3rd. plug @ 360' w/40 sxs. cement. 4th. plug @ 40' w/10 sxs. cement. 15 sxs. in rathole (circulate) Remarks: By: Allied Cement.	J. Schmidt All[], Part[], None[X] Ath: April , Year: 94 Is ordered 190 sxs. 60/40 pozmix - nole - spotted and displaced all between all plugs. STATE CORPORATION COMMICSION Wichita, Kancaca
all plugs - no arbuckle. 25 sxs. @ 2620 1810' - 40 sxs. @ 360' - 10 sxs. @ 40' Plugging Proposal Received by: Marion Plugging operations attended by agent? Completed: Hour: 5:45P.M., Day: 27, Mor Actual plugging report: White and Elli 6% gel and 1 sx. flocele. Circulated rement through drill pipe - heavy mud rest. plug @ 2620' w/25 sxs. cement. 2nd. plug @ 1810' w/100 sxs. cement with 3rd. plug @ 360' w/40 sxs. cement. 4th. plug @ 360' w/40 sxs. cement. 4th. plug @ 40' w/10 sxs. cement. Sxs. in rathole (circulate) Remarks: By: Allied Cement. Condition of casing(in hole): GOOD X BA	J. Schmidt All[], Part[], None[X] ath: April , Year: 94 Ls ordered 190 sxs. 60/40 pozmix - nole - spotted and displaced all between all plugs. STATE CORPORATION COMMICSION Wichita, Kansas AD Anhy.plug: YES X NO
all plugs - no arbuckle. 25 sxs. @ 2620 1810' - 40 sxs. @ 360' - 10 sxs. @ 40' Plugging Proposal Received by: Marion Plugging operations attended by agent? Completed: Hour: 5:45P.M., Day: 27, Mor Actual plugging report: White and Elli 6% gel and 1 sx. flocele. Circulated by cement through drill pipe - heavy mud by 1st. plug @ 2620' w/25 sxs. cement. 2nd. plug @ 1810' w/100 sxs. cement with 3rd. plug @ 360' w/40 sxs. cement. 4th. plug @ 360' w/40 sxs. cement. 4th. plug @ 40' w/10 sxs. cement. Sxs. in rathole (circulate) Remarks: By: Allied Cement. Condition of casing(in hole):GOOD X BA Bottom plug(in place):YES , CALC	J. Schmidt All[], Part[], None[X] Ath: April, Year: _94 Ls ordered 190 sxs. 60/40 pozmix - Tole - spotted and displaced all Detween all plugs. STATE CORPORATION COMMICSION Wichita. Kansas ADAnhy.plug:YESXNO
all plugs - no arbuckle. 25 sxs. @ 2620 1810' - 40 sxs. @ 360' - 10 sxs. @ 40' Plugging Proposal Received by: Marion Plugging operations attended by agent? Completed: Hour: 5:45P.M., Day: 27, Mor Actual plugging report: White and Elli 6% gel and 1 sx. flocele. Circulated by cement through drill pipe - heavy mud by 1st. plug @ 2620' w/25 sxs. cement. 2nd. plug @ 1810' w/100 sxs. cement with 3rd. plug @ 360' w/40 sxs. cement. 4th. plug @ 360' w/40 sxs. cement. 4th. plug @ 40' w/10 sxs. cement. Sxs. in rathole (circulate) Remarks: By: Allied Cement. Condition of casing(in hole):GOOD X BA Bottom plug(in place):YES , CALC	J. Schmidt All[], Part[], None[X] Ath: April, Year: _94 Ls ordered 190 sxs. 60/40 pozmix - Tole - spotted and displaced all Detween all plugs. STATE CORPORATION COMMICSION Wichita. Kansas ADAnhy.plug:YESXNO
all plugs - no arbuckle. 25 sxs. @ 2620 1810' - 40 sxs. @ 360' - 10 sxs. @ 40' Plugging Proposal Received by:Marion Plugging operations attended by agent? Completed: Hour: 5:45P.M., Day: _27 , Mor Actual plugging report:White and Elli 6% gel and 1 sx. flocele. Circulated rement through drill pipe - heavy mud related by the system of the sys	J. Schmidt All[], Part[], None[X] Ath: April , Year: 94 Is ordered 190 sxs. 60/40 pozmix - nole - spotted and displaced all between all plugs. STATE CORPORATION COMMICSION Wichita, Kansas AD Anhy.plug:YES X NO P. Elevation: 3062 GL
all plugs - no arbuckle. 25 sxs. @ 2620 1810' - 40 sxs. @ 360' - 10 sxs. @ 40' Plugging Proposal Received by: Marion Plugging operations attended by agent? Completed: Hour: 5:45P.M., Day: 27, Mor Actual plugging report: White and Elli 6% gel and 1 sx. flocele. Circulated by cement through drill pipe - heavy mud by 1st. plug @ 2620' w/25 sxs. cement. 2nd. plug @ 1810' w/100 sxs. cement with 3rd. plug @ 360' w/40 sxs. cement. 4th. plug @ 360' w/40 sxs. cement. 4th. plug @ 40' w/10 sxs. cement. Sxs. in rathole (circulate) Remarks: By: Allied Cement. Condition of casing(in hole):GOOD X BA Bottom plug(in place):YES , CALC	J. Schmidt All[], Part[], None[X] Ath: April , Year: 94 Is ordered 190 sxs. 60/40 pozmix - nole - spotted and displaced all between all plugs. STATE CORPORATION COMMICSION Wichita, Kansas AD Anhy.plug:YES X NO P. Elevation: 3062 GL
all plugs - no arbuckle. 25 sxs. @ 2620 1810' - 40 sxs. @ 360' - 10 sxs. @ 40' Plugging Proposal Received by: Marion Plugging operations attended by agent? Completed: Hour: 5:45P.M., Day: 27, Mor Actual plugging report: White and Elli 6% gel and 1 sx. flocele. Circulated by cement through drill pipe - heavy mud by 1st. plug @ 2620' w/25 sxs. cement. 2nd. plug @ 1810' w/100 sxs. cement with 3rd. plug @ 360' w/40 sxs. cement. 4th. plug @ 360' w/40 sxs. cement. 4th. plug @ 40' w/10 sxs. cement. 15 sxs. in rathole (circulate) Remarks: By: Allied Cement. Condition of casing(in hole):GOOD X BA Bottom plug(in place):YES , CALC Plugged through TUBING , CASING D. I did V O did not [X] observe the pl	J. Schmidt All[], Part[], None[X] ath: April , Year: 94 Is ordered 190 sxs. 60/40 pozmix - nole - spotted and displaced all between all plugs. STATE CORPORATION COMMICSION Wichita, Kansas AD Anhy.plug:YES X NO NO X Dakota plug:YES X, NO P. Elevation: 3062 GL sugging. Maxion Annual Maxion Annu
all plugs - no arbuckle. 25 sxs. @ 2620 1810' - 40 sxs. @ 360' - 10 sxs. @ 40' Plugging Proposal Received by: Marion Plugging operations attended by agent? Completed: Hour: 5:45P.M., Day: 27, Mor Actual plugging report: White and Elli 6% gel and 1 sx. flocele. Circulated by cement through drill pipe - heavy mud by 1st. plug @ 2620' w/25 sxs. cement. 2nd. plug @ 1810' w/100 sxs. cement with 3rd. plug @ 360' w/40 sxs. cement. 4th. plug @ 360' w/10 sxs. cement. 4th. plug @ 40' w/10 sxs. cement. Condition of casing(in hole):GOOD x BA Bottom plug(in place):YES,CALC_ Plugged through TUBING, CASINGD. I didw volume of the plugged through TUBING, CASINGD.	J. Schmidt All[], Part[], None[X] Ath: April , Year: 94 Is ordered 190 sxs. 60/40 pozmix - nole - spotted and displaced all between all plugs. STATE CORPORATION COMMICSION Wichita, Kansas AD Anhy.plug:YES X NO P. Elevation: 3062 GL
all plugs - no arbuckle. 25 sxs. @ 2620 1810' - 40 sxs. @ 360' - 10 sxs. @ 40' Plugging Proposal Received by: Marion Plugging operations attended by agent? Completed: Hour: 5:45P.M., Day: 27, Mor Actual plugging report: White and Elli 6% gel and 1 sx. flocele. Circulated rement through drill pipe - heavy mud related by the standard of the standard plug @ 2620' w/25 sxs. cement. 2nd. plug @ 1810' w/100 sxs. cement with standard plug @ 360' w/40 sxs. cement. 4th. plug @ 40' w/10 sxs. cement. 15 sxs. in rathole (circulate) Remarks: By: Allied Cement. Condition of casing(in hole):GOOD x BABOTTO BROTTO BROT	J. Schmidt All[], Part[], None[X] ath: April , Year: 94 Is ordered 190 sxs. 60/40 pozmix - nole - spotted and displaced all between all plugs. STATE CORPORATION COMMICSION Wichita, Kansas AD Anhy.plug:YES X NO NO X Dakota plug:YES X, NO P. Elevation: 3062 GL sugging. Maxion Annual Maxion Annu
all plugs - no arbuckle. 25 sxs. @ 2620 1810' - 40 sxs. @ 360' - 10 sxs. @ 40' Plugging Proposal Received by: Marion Plugging operations attended by agent? Completed: Hour: 5:45P.M., Day: 27, Mor Actual plugging report: White and Elli 6% gel and 1 sx. flocele. Circulated by cement through drill pipe - heavy mud by 1st. plug @ 2620' w/25 sxs. cement. 2nd. plug @ 1810' w/100 sxs. cement with 3rd. plug @ 360' w/40 sxs. cement. 4th. plug @ 40' w/10 sxs. cement. 15 sxs. in rathole (circulate) Remarks: By: Allied Cement. Condition of casing(in hole):GOOD X BA Bottom plug(in place):YES,CALC Plugged through TUBING, CASINGD. I did	J. Schmidt All[], Part[], None[X] ath: April , Year: 94 Ls ordered 190 sxs. 60/40 pozmix - nole - spotted and displaced all between all plugs. STATE CONFORATION COMMICSION Wichita Kansas AD Anhy.plug:YES X NO P. Elevation: 3062 GL Lugging. Maximul June (agent)
all plugs - no arbuckle. 25 sxs. @ 2620 1810' - 40 sxs. @ 360' - 10 sxs. @ 40' Plugging Proposal Received by: Marion Plugging operations attended by agent? Completed: Hour: 5:45P.M., Day: 27, Mor Actual plugging report: White and Elli 6% gel and 1 sx. flocele. Circulated rement through drill pipe - heavy mud related by the standard of the standard plug @ 2620' w/25 sxs. cement. 2nd. plug @ 1810' w/100 sxs. cement with standard plug @ 360' w/40 sxs. cement. 4th. plug @ 40' w/10 sxs. cement. 15 sxs. in rathole (circulate) Remarks: By: Allied Cement. Condition of casing(in hole):GOOD x BABOTTO BROTTO BROT	J. Schmidt All[], Part[], None[X] ath: April , Year: 94 Ls ordered 190 sxs. 60/40 pozmix - nole - spotted and displaced all between all plugs. STATE CONFORATION COMMICSION Wichita Kansas AD Anhy.plug:YES X NO P. Elevation: 3062 GL Lugging. Maximul June (agent)