



WM. H. AVERY
WILLIAM L. MITCHELL
JAMES O. GREENLEAF
HARRY G. WILES
RAYMOND B. HARVEY

E. EDWARD JOHNSON

Governor Chairman Commissioner Commissioner Secretary Gen. Counsel

## State Corporation Commission

## CONSERVATION DIVISION

(Oil, Gas and Water)
500 Insurance Bldg. 212 N. Market
WICHITA, KANSAS 67202

VERBAL PERMIT FORM (To Be Filed By Plugging Agent)

STATE STREET OF THE STREET OF

15-179-20056-00-00 NAV 13 1967
11-13-1967
CONSERVATION DIVISION
Withits, Kansas

J. P. Roberts
Administrator
500 Insurance Building
Wichita 2, Kansas

near	DIT.

date requested permission to plug the following described well:  Mr. Michaels guarantees payment of the plugging fee.  Operator's full Name: Thunderbird Drilling, Incorporated,  Complete Address: 400 No. Woodlawn, Suite #7, Wichita, Kansas.  Lease Name: Chestnut Well No. 1  Location: Appr. NE-NE-SW Sec. 22 Twp. 9 Rge. (E) (W) 26  County Sheridan Total Depth 4157:011 Well  Gas Well Input Well SWD Well D & A X Lost Hole  Mr. Michaels was instructed to plug the well as follows:  2h7!8 5/8" Surface pipe, cement circulated with 165 Sx.  Dakota section from 1130' to 1305'.  Circulate hole with heavy mud. Pull DP to 1330' and displace 100 Sx. cement thru DP. Pull DP to 270' and displace 20 Sx. cement thru DP. Pull DP, set bridge 40' with 5 sack hulls and 10 Sx. cement to bottom of cellar.	mr. clarence michaels of Sage Drig. Co., Inc., has this		
Operator's full Name:	date requested permission to plug the following described well:		
Complete Address: 400 No. Woodlawn, Suite #7, Wichita, Kansas.  Lease Name: Chestnut Well No. 1  Location: Appr. NE-NE-SW Sec. 22 Twp. 9 Rge. (E) (W) 26  County Sheridan Total Depth 4157:011 Well  Gas Well Input Well SWD Well D & A X Lost Hole  Mr. Michaels was instructed to plug the well as follows:  247:-8 5/8" Surface pipe, cement circulated with 165 Sx.  Dakota section from 1130' to 1305'.  Circulate hole with heavy mud. Pull DP to 1330' and displace 100 Sx.  cement thru DP. Pull DP to 270' and displace 20 Sx. cement thru DP.  Pull DP, set bridge @ 40' with ½ sack hulls and 10 Sx. cement to	Mr. Michaels guarantees payment of the plugging fee.		
Lease Name: Chestnut Well No. 1  Location: Appr. NE-NE-SW Sec. 22 Twp. 9 Rge. (E) (W) 26  County Sheridan Total Depth 4157'.0il Well  Gas Well Input Well SWD Well D & A X Lost Hole  Mr. Michaels was instructed to plug the well as follows:  247'-8 5/8" Surface pipe, cement circulated with 165 Sx.  Dakota section from 1130' to 1305'.  Circulate hole with heavy mud. Pull DP to 1330' and displace 100 Sx.  cement thru DP. Pull DP to 270' and displace 20 Sx. cement thru DP.  Pull DP, set bridge @ 40' with ½ sack hulls and 10 Sx. cement to	Operator's full Name: Thunderbird Drilling, Incorporated,		
Location: Appr. NE-NE-SW Sec. 22 Twp. 9 Rge. (E) (W) 26  County Sheridan Total Depth 4157 Oil Well  Gas Well Input Well SWD Well D & A X Lost Hole  Mr. Michaels was instructed to plug the well as follows:  247'-8 5/8" Surface pipe, cement circulated with 165 Sx.  Dakota section from 1130' to 1305'.  Circulate hole with heavy mud. Pull DP to 1330' and displace 100 Sx.  cement thru DP. Pull DP to 270' and displace 20 Sx. cement thru DP.  Pull DP, set bridge @ 40' with ½ sack hulls and 10 Sx. cement to	Complete Address: 400 No. Woodlawn, Suite #7, Wichita, Kansas.		
County Sheridan Total Depth 4157'011 Well  Gas Well Input Well SWD Well D & A X Lost Hole  Mr. Michaels was instructed to plug the well as follows:  247'-8 5/8" Surface pipe, cement circulated with 165 Sx.  Dakota section from 1130' to 1305'.  Circulate hole with heavy mud. Pull DP to 1330' and displace 100 Sx.  cement thru DP. Pull DP to 270' and displace 20 Sx. cement thru DP.  Pull DP, set bridge @ 40' with ½ sack hulls and 10 Sx. cement to	Lease Name: Chestnut Well No. 1		
Gas Well Input Well SWD Well D & A X Lost Hole  Mr. Michaels was instructed to plug the well as follows:  217'-8 5/8" Surface pipe, cement circulated with 165 Sx.  Dakota section from 1130' to 1305'.  Circulate hole with heavy mud. Pull DP to 1330' and displace 100 Sx.  cement thru DP. Pull DP to 270' and displace 20 Sx. cement thru DP.  Pull DP, set bridge @ 40' with ½ sack hulls and 10 Sx. cement to	Location: Appr. NE-NE-SW Sec. 22 Twp. 9 Rge. (E) (W) 26		
Mr. Michaels was instructed to plug the well as follows:  247'-8 5/8" Surface pipe, cement circulated with 165 Sx.  Dakota section from 1130' to 1305'.  Circulate hole with heavy mud. Pull DP to 1330' and displace 100 Sx.  cement thru DP. Pull DP to 270' and displace 20 Sx. cement thru DP.  Pull DP, set bridge @ 40' with ½ sack hulls and 10 Sx. cement to	County Sheridan Total Depth 4157 Oil Well		
247'8 5/8" Surface pipe, cement circulated with 165 Sx.  Dakota section from 1130' to 1305'.  Circulate hole with heavy mud. Pull DP to 1330' and displace 100 Sx.  cement thru DP. Pull DP to 270' and displace 20 Sx. cement thru DP.  Pull DP, set bridge @ 40' with ½ sack hulls and 10 Sx. cement to	Gas Well Input Well SWD Well D & A X Lost Hole		
Dakota section from 1130' to 1305'.  Circulate hole with heavy mud. Pull DP to 1330' and displace 100 Sx. cement thru DP. Pull DP to 270' and displace 20 Sx. cement thru DP. Pull DP, set bridge @ 40' with ½ sack hulls and 10 Sx. cement to	Mr. <u>Michaels</u> was instructed to plug the well as follows:		
rement thru DP. Pull DP to 270' and displace 20 Sx. cement thru DP. Pull DP. set bridge @ 40' with ½ sack hulls and 10 Sx. cement to			
	rement thru DP. Pull DP to 270' and displace 20 Sx. cement thru DP. Pull DP. set bridge @ 40' with ½ sack hulls and 10 Sx. cement to		

Very truly yours,

Conservation Division Agent