KANSAS CORPORATION COMMISSION OIL & GAS CONSERVATION DIVISION

Form CDP-4 April 2004 Form must be Typed

CLOSURE OF SURFACE PIT

Operator Name: OXY USA Inc.	License Number: 5447
Operator Address: P. O.Box 2528, Liberal KS 67905	
Contact Person: Harold Jones	Phone Number: (620) 356 - 3032
Permit Number (API No. if applicable): 15-067-21665 000	Lease Name & Well No.: Alderman ATU "A" #4
Type of Pit:	Pit Location (QQQQ):
Emergency Pit Burn Pit	NW NW NW NW
Settling Pit ✓ Drilling Pit	Sec. 18 Twp. 29S R. 35 East West
Workover Pit Haul-Off Pit	000
	Peet from V North / South Line of Section
	Grant Line of Section
	County
Date of closure: 07/24/2008	
Was an artificial liner used? ☐ Yes ✓ No	
If no, how were the sides and bottom sealed to prevent downward migration of the pit contents?	
Coated with Bentonite and natural cuttings.	
Coated with Bentonite and natural cuttings.	
Coated with Bentonite and natural cuttings.	
Coated with Bentonite and natural cuttings. Abandonment procedure of pit:	RECEIVED KANSAS CORPORATION COMMISSION
	KANSAS CORPORATION COMMISSION
Abandonment procedure of pit:	d with manure. AUG 0 5 2008
Abandonment procedure of pit:	KANSAS CORPORATION COMMISSION
Abandonment procedure of pit: Pushed and backfilled with original material, then covered	d with manure. AUG 0 5 2008 CONSERVATION DIVISION WICHITA, KS
Abandonment procedure of pit: Pushed and backfilled with original material, then covered The undersigned hereby certifies that he / she is Kenny Andrews, Production	d with manure. AUG 0 5 2008 CONSERVATION DIVISION WICHITA, KS ON Lead for OXY USA, Inc. (Co.),
Abandonment procedure of pit: Pushed and backfilled with original material, then covered	d with manure. AUG 0 5 2008 CONSERVATION DIVISION WICHITA, KS ON Lead for OXY USA, Inc. (Co.),
Abandonment procedure of pit: Pushed and backfilled with original material, then covered The undersigned hereby certifies that he / she is Kenny Andrews, Production	CONSERVATION DIVISION WICHITA, KS On Lead for OXY USA, Inc. (Co.), e best of his liver knowledge and belief.
Abandonment procedure of pit: Pushed and backfilled with original material, then covered The undersigned hereby certifies that he / she is Kenny Andrews, Production	d with manure. AUG 0 5 2008 CONSERVATION DIVISION WICHITA, KS ON Lead for OXY USA, Inc. (Co.),
Abandonment procedure of pit: Pushed and backfilled with original material, then covered The undersigned hereby certifies that he / she is Kenny Andrews, Production a duly authorized agent, that all information shown hereon is true and correct to the Subscribed and sworn to me on this day of	CONSERVATION DIVISION WICHITA, KS On Lead for OXY USA, Inc. (Co.), e best of his liver knowledge and belief.
Abandonment procedure of pit: Pushed and backfilled with original material, then covered The undersigned hereby certifies that he / she is a duly authorized agent, that all information shown hereon is true and correct to the	CONSERVATION DIVISION WICHITA, KS On Lead for OXY USA, Inc. (Co.), e best of his liver knowledge and belief.