## Kansas Corporation Commission Oil & Gas Conservation Division

Form CDP-4 April 2004 Form must be Typed

## **CLOSURE OF SURFACE PIT**

Operator Name: Layne Energy Operating, LLC	License Number: 33365
Operator Address: 1900 Shawnee Mission Parkway, Mission Woods, KS 66205	
Contact Person: Kimberlee Dixon	Phone Number: ( 620 ) 627 - 2499
Permit Number (API No. if applicable): 15-205-27572-0000	Lease Name & Well No.: Hummer 9-28
Type of Pit:	Pit Location (QQQQ):
Emergency Pit Burn Pit	<u>N2 _ NE _ SE </u>
Settling Pit ✓ Drilling Pit	Sec. 28 Twp. 30S R. 14
Workover Pit Haul-Off Pit	2270 Feet from North / South Line of Section
	577 Feet from 🗸 East / West Line of Section
	Wilson County
Date of closure: November 4, 2008  Was an artificial liner used? Yes V No	
If no, how were the sides and bottom sealed to prevent downward migration of the pit contents?	
Self-Sealing Pit	
Self-Sealing Fit	RECEIVED KANSAS CORPORATION COMMISSION
Abandonment procedure of pit:	RECEIVED KANSAS CORPORATION COMMISSION NOV 2 6 2008
	KANSAS CORPORATION COMMISSION
Abandonment procedure of pit:	KANSAS CORPORATION COMMISSION  NOV 2 6 2008  CONSERVATION DIVISION
Abandonment procedure of pit:  Let evaporate until dry, then backfilled and restored.	NOV 2 6 2008  CONSERVATION DIVISION WICHITA, KS
Abandonment procedure of pit:	NOV 2 6 2008  CONSERVATION DIVISION WICHITA, KS  Layne Energy Operating, LLC (Co.),
Abandonment procedure of pit:  Let evaporate until dry, then backfilled and restored.  The undersigned hereby certifies that he / she isAgent	NOV 2 6 2008  CONSERVATION DIVISION WICHITA, KS  for Layne Energy Operating, LLC (Co.), best of his /her knowledge and belief.  Mulas Lay Mary Lay Lay Lay Lay Lay Lay Lay Lay Lay La
Abandonment procedure of pit:  Let evaporate until dry, then backfilled and restored.  The undersigned hereby certifies that he / she is Agent  a duly authorized agent, that all information shown hereon is true and correct to the	NOV 2 6 2008  CONSERVATION DIVISION WICHITA, KS  Layne Energy Operating, LLC (Co.),
Abandonment procedure of pit:  Let evaporate until dry, then backfilled and restored.  The undersigned hereby certifies that he / she is	MOV 2 6 2008  CONSERVATION DIVISION WICHITA, KS  for Layne Energy Operating, LLC (Co.), best of his /her knowledge and belief.  Signature of Applicant or Agent  Signature of Applicant or Agent
Abandonment procedure of pit:  Let evaporate until dry, then backfilled and restored.  The undersigned hereby certifies that he / she is	NOV 2 6 2008  CONSERVATION DIVISION WICHITA, KS  for Layne Energy Operating, LLC (Co.), best of his /her knowledge and belief.  May Lay Lay Lay Lay Lay Lay Lay Lay Lay L