My Commission expires Hon S. 2007

KANSAS CORPORATION COMMISSION CONSERVATION DIVISION 130 S. MARKET – ROOM 2078 WICHITA STATE OFFICE BUILDING WICHITA, KANSAS 67202

RECEIVED KANSAS CORPORATION COMMISSION

SEP 0 4 2008

CLOSURE OF SURFACE POND

CONSERVATION DIVISION WICHITA, KS

OPERATOR NAME	LICENCE NO.
PETROSANTANDER (USA) INC	32198
OPERATOR ADDRESS	
6363 WOODWAY, #350, HOUSTON, TEXAS 77057	
CONTACT PERSON	PHONE NUMBER
LILIANA HERNANDEZ	<u>(713) 784-8700</u>
PERMIT NUMBER (API # if applicable)	LEASE NAME
<u>15-093-20757</u> ტტ ც ი	ODD WILLIAMS 3
TYPE OF POND:	PIT LOCATION
Emergency Pit Burn pit	Sec <u>12</u> Twp <u>21</u> S Rng <u>35</u> E/W
Treatment Pit Drilling Pit	660 Ft from N/S line of Sec (circle one)
Workover Pit	1980 Ft from E/W line of Sec (circle one)
	KEARNY County
Date of Closure: July 2nd, 2008	
Was an artificial liner used? Yes X No	
	•
Was an artificial liner used? Yes X No If no, how were the sides and bottom sealed to prevent downward migration o	
Was an artificial liner used? Yes X No If no, how were the sides and bottom sealed to prevent downward migration o Native muds and clays Abandonment procedure of pond: Backfill and replace topsoil then level as close as possible to its natural st	
Was an artificial liner used? If no, how were the sides and bottom sealed to prevent downward migration o Native muds and clays Abandonment procedure of pond: Backfill and replace topsoil then level as close as possible to its natural st	DEZ nt, that all information shown hereon is true and

April 05, 2009