Kansas Corporation Commission Oil & Gas Conservation Division

Form CDP-4 April 2004 Form must be Typed

CLOSURE OF SURFACE PIT

Operator Name: Kansas Natural Gas Operating, Inc.	License Number: 32787
Operator Address: P.O. Box 815 Sublette, KS 67877	
Contact Person: Steve Lehning	Phone Number: (620) 675 - 8185
Permit Number (API No. if applicable): 15-055-21947-0000	Lease Name & Well No.: Spratt 6-3
Type of Pit:	Pit Location (QQQQ):
Emergency Pit Burn Pit	SW _ NE _ NE _ 1/4
Settling Pit	Sec. 13 Twp. 25 R. 34 East West
Workover Pit Haul-Off Pit	1180_1250 North / South Line of Section
(On-Site_Reserve_Pit)→	1245 125 Feet from East / West Line of Section
	<u>Finney</u> County
Date of closure: February 29, 2008 Was an artificial liner used? Yes No If no, how were the sides and bottom sealed to prevent downward migration of the pit contents?	
Fresh water and drilling mud. Evaporate till dry and backfill to complete.	
	iii to confibrato.
	·
	RECEIVED KANSAS CORPORATION COMMISSION
	RECEIVED
Abandonment procedure of pit: Evaporate till dry. Backfill to complete. Spread Manure.	RECEIVED KANSAS CORPORATION COMMISSION
Abandonment procedure of pit:	RECEIVED KANSAS CORPORATION COMMISSION MAR 0 6 2008 CONSERVATION DIVISION
Abandonment procedure of pit: Evaporate till dry. Backfill to complete. Spread Manure.	RECEIVED KANSAS CORPORATION COMMISSION MAR 0 6 2008 CONSERVATION DIVISION WICHITA, KS
Abandonment procedure of pit: Evaporate till dry. Backfill to complete. Spread Manure. The undersigned hereby certifies that he / she is Supt.	RECEIVED KANSAS CORPORATION COMMISSION MAR 0 6 2008 CONSERVATION DIVISION WICHITA, KS
Abandonment procedure of pit: Evaporate till dry. Backfill to complete. Spread Manure.	RECEIVED KANSAS CORPORATION COMMISSION MAR 0 6 2008 CONSERVATION DIVISION WICHITA, KS
Abandonment procedure of pit: Evaporate till dry. Backfill to complete. Spread Manure. The undersigned hereby certifies that he / she is Supt.	RECEIVED KANSAS CORPORATION COMMISSION MAR 0 6 2008 CONSERVATION DIVISION WICHITA, KS
Abandonment procedure of pit: Evaporate till dry. Backfill to complete. Spread Manure. The undersigned hereby certifies that he / she is Supt. a duly authorized agent, that all information shown hereon is true and correct to the	RECEIVED KANSAS CORPORATION COMMISSION MAR 0 6 2008 CONSERVATION DIVISION WICHITA, KS
Abandonment procedure of pit: Evaporate till dry. Backfill to complete. Spread Manure. The undersigned hereby certifies that he / she is Supt. a duly authorized agent, that all information shown hereon is true and correct to the	RECEIVED KANSAS CORPORATION COMMISSION MAR 0 6 2008 CONSERVATION DIVISION WICHITA, KS for Kansas Natural Gas Operating, Inc. (Co.), best of his /her knowledge and belief. Signature of Applicant or Agent