## Kansas Corporation Commission Oil & Gas Conservation Division

Form CDP-4 April 2004 Form must be Typed

## **CLOSURE OF SURFACE PIT**

Operator Name: Lario Oil & Gas Co.	License Number: 5214
Operator Address: 301 S. Market St. Wichita, KS	67202
Contact Person: Jay G. Schweikert	Phone Number: ( 316 ) 265 - 5611
Permit Number (API No. if applicable): 15-171-20673 0000	Lease Name & Well No.: Hansen #1-9
Type of Pit:	Pit Location (QQQQ):
Emergency Pit Burn Pit	SE SE SE
Settling Pit	Sec. 9 Twp. 19 R. 33 East West
Workover Pit Haul-Off Pit	330 Feet from North / ✓ South Line of Section
	330 Feet from 🗸 East / West Line of Section
	Scott County
Date of closure: 3-8-08	
Was an artificial liner used? ☐ Yes ✓ No	
If no, how were the sides and bottom sealed to prevent downward migration of the pit contents?	
Bentonite in mud.	
Bertonite in mad.	RECEIVED KANSAS CORPORATION COMMISSION
Bertonite in mad.	KANSAS CORPORATION COMMISSIO
Bentonite in mad.	KANSAS CORPORATION COMMISSIO  MAR 2 7 2008
Abandonment procedure of pit:	KANSAS CORPORATION COMMISSIO  MAR 2 7 2008  CONSERVATION DIVISION WICHITA, KS
	KANSAS CORPORATION COMMISSIO  MAR 2 7 2008  CONSERVATION DIVISION WICHITA, KS
Abandonment procedure of pit:	KANSAS CORPORATION COMMISSIO  MAR 2 7 2008  CONSERVATION DIVISION WICHITA, KS
Abandonment procedure of pit:	KANSAS CORPORATION COMMISSIO  MAR 2 7 2008  CONSERVATION DIVISION WICHITA, KS
Abandonment procedure of pit:  Evaporate water holding in pit. Cut walls. Pits filled in a	KANSAS CORPORATION COMMISSIO  MAR 2 7 2008  CONSERVATION DIVISION WICHITA, KS  Indeer for Lario Oil & Gas Company (Co.),
Abandonment procedure of pit:  Evaporate water holding in pit. Cut walls. Pits filled in all and an Operations English	KANSAS CORPORATION COMMISSIO  MAR 2 7 2008  CONSERVATION DIVISION WICHITA, KS  Indeer for Lario Oil & Gas Company (Co.),
Abandonment procedure of pit:  Evaporate water holding in pit. Cut walls. Pits filled in a	MAR 2 7 2008  CONSERVATION DIVISION WICHITA, KS  Indeer for Lario Oil & Gas Company (Co.),  the best of his /her knowledge and belief.
Abandonment procedure of pit:  Evaporate water holding in pit. Cut walls. Pits filled in all the second of the sec	MAR 2 7 2008  CONSERVATION DIVISION WICHITA, KS  Indeer for Lario Oil & Gas Company (Co.),  the best of his /her knowledge and belief.  Signature of Applicant or Agent
Abandonment procedure of pit:  Evaporate water holding in pit. Cut walls. Pits filled in all the undersigned hereby certifies that he / she is an Operations Engraduly authorized agent, that all information shown hereon is true and correct to the subscribed and sworn to me on this day of	MAR 2 7 2008  CONSERVATION DIVISION WICHITA, KS  Indeer for Lario Oil & Gas Company (Co.),  the best of his /her knowledge and belief.
Abandonment procedure of pit:  Evaporate water holding in pit. Cut walls. Pits filled in all the second of the sec	MAR 2 7 2008  CONSERVATION DIVISION WICHITA, KS  Indeer for Lario Oil & Gas Company (Co.),  the best of his /her knowledge and belief.  March 2008
Abandonment procedure of pit:  Evaporate water holding in pit. Cut walls. Pits filled in a structure of pit:  The undersigned hereby certifies that he / she is	MAR 2 7 2008  CONSERVATION DIVISION WICHITA, KS  Indeer for Lario Oil & Gas Company (Co.),  the best of his /her knowledge and belief.  Signature of Applicant or Agent