## KANSAS CORPORATION COMMISSION OIL & GAS CONSERVATION DIVISION

Form CDP-4 April 2004 Form must be Typed

## **CLOSURE OF SURFACE PIT**

	T
Operator Name: Kansas Natural Gas Operating, Inc.	License Number: 32787
Operator Address: P O Box 815 Sublette, KS 67877	
Contact Person: Steve Lehning	Phone Number: ( 620 ) 675 - 8185
Permit Number (API No. if applicable): 15-093-21811-0000	Lease Name & Well No.: Hamlin 3-3
Type of Pit:	Pit Location (QQQQ):
Emergency Pit Burn Pit	SW _ NE _ NW _ 1/4
Settling Pit	Sec. 25 Twp. 24 R. 35 East  West
Workover Pit Haul-Off Pit	1300' Feet from North / South Line of Section
(Small On-Site Pit)	1800' Feet from ☐ East / ✓ West Line of Section  Kearny County
	County
Date of closure: 12-18-2007  Was an artificial liner used? Yes No	
If no, how were the sides and bottom sealed to prevent downward migration of the pit contents?	
Fresh water and drilling mud. Evaporate till dry and backfill.	
Fresh water and drilling mud. Evaporate till dry and back	fill.
Fresh water and drilling mud. Evaporate till dry and back	fill.
Fresh water and drilling mud. Evaporate till dry and back	RECEIVED
Abandonment procedure of pit:	RECEIVED KANSAS CORPORATION COMMISSI
	RECEIVED
Abandonment procedure of pit:	RECEIVED KANSAS CORPORATION COMMISSI  DEC 2 6 2007  CONSERVATION DIVISION
Abandonment procedure of pit:	RECEIVED KANSAS CORPORATION COMMISSI DEC 2 6 2007
Abandonment procedure of pit:  Evaporate till dry. Backfill to complete.	RECEIVED KANSAS CORPORATION COMMISSI  DEC 2 6 2007  CONSERVATION DIVISION
Abandonment procedure of pit:  Evaporate till dry. Backfill to complete.	RECEIVED  KANSAS CORPORATION COMMISSI  DEC 2 6 2007  CONSERVATION DIVISION WICHITA, KS  for Kansas Natural Gas Operating, Inc. (Co.),
Abandonment procedure of pit:  Evaporate till dry. Backfill to complete.  The undersigned hereby certifies that he / she isSupt.	RECEIVED KANSAS CORPORATION COMMISSI  DEC 2 6 2007  CONSERVATION DIVISION WICHITA, KS  for Kansas Natural Gas Operating, Inc. (Co.), best of his /her knowledge and belief.
Abandonment procedure of pit:  Evaporate till dry. Backfill to complete.  The undersigned hereby certifies that he / she is	RECEIVED  KANSAS CORPORATION COMMISSI  DEC 2 6 2007  CONSERVATION DIVISION WICHITA, KS  for Kansas Natural Gas Operating, Inc. (Co.),
Abandonment procedure of pit:  Evaporate till dry. Backfill to complete.  The undersigned hereby certifies that he / she isSupt.	RECEIVED KANSAS CORPORATION COMMISSI  DEC 2 6 2007  CONSERVATION DIVISION WICHITA, KS  for Kansas Natural Gas Operating, Inc. (Co.), best of his /her knowledge and belief.
Abandonment procedure of pit:  Evaporate till dry. Backfill to complete.  The undersigned hereby certifies that he / she is	RECEIVED KANSAS CORPORATION COMMISSI  DEC 2 6 2007  CONSERVATION DIVISION WICHITA, KS  for Kansas Natural Gas Operating, Inc. (Co.), best of his /her knowledge and belief.  Signature of Applicant of Agent
Abandonment procedure of pit:  Evaporate till dry. Backfill to complete.  The undersigned hereby certifies that he / she is	RECEIVED KANSAS CORPORATION COMMISSI  DEC 2 6 2007  CONSERVATION DIVISION WICHITA, KS  for Kansas Natural Gas Operating, Inc. (Co.), best of his /her knowledge and belief.  Signature of Applicant of Agent