Kansas Corporation Commission Oil & Gas Conservation Division

Form CDP-4 April 2004 Form must be Typed

CLOSURE OF SURFACE PIT

Operator Name: John O. Farmer, Inc.	License Number: 5135
Operator Address: P.O. Box 352, Russell, KS 67665	
Contact Person: Marge Schulte	Phone Number: (785) 483 - 3145, Ext. 214
Permit Number (API No. if applicable): 15-197-20,270-00-00	Lease Name & Well No.: Davis Trust #1
Type of Pit:	Pit Location (QQQQ):
Emergency Pit Burn Pit	SE _ NW _ SW _ SW
Settling Pit	Sec. 4
Workover Pit Haul-Off Pit	860 Feet from North / 🗸 South Line of Section
	470 Feet from East / West Line of Section
	Wabaunsee County
Date of closure: 1-13-09	
Was an artificial liner used? ☐ Yes ✓ No	
If no, how were the sides and bottom sealed to prevent downward migration of the pit contents? Sealed with clay soil, native and fresh mud	
Tours and That Tour Tour That	
Abandonment procedure of pit: Allowed liquid contents to evaporate, let cuttings dry and I	RECEIVED JAN 23 2009 CONSERVATION DIVISION WICHITA, KS
Abandonment procedure of pit: Allowed liquid contents to evaporate, let cuttings dry and I	conservation Division backfilled WICHITA, KS
Abandonment procedure of pit:	CONSERVATION DIVISION backfilled WICHITA, KS for John O. Farmer, Inc(Co.),
Abandonment procedure of pit: Allowed liquid contents to evaporate, let cuttings dry and I The undersigned hereby certifies that the she is	conservation Division backfilled Wichita, ks for John O. Farmer, Inc(Co.), best of his /her knowledge and belief.
Abandonment procedure of pit: Allowed liquid contents to evaporate, let cuttings dry and let undersigned hereby certifies that he let undersigned hereby certif	conservation Division backfilled WICHITA, KS for John O. Farmer, Inc(Co.), be best of his /her knowledge and belief. Signature of Applicant or Agent
Abandonment procedure of pit: Allowed liquid contents to evaporate, let cuttings dry and I The undersigned hereby certifies that he had she is	conservation Division backfilled WICHITA, KS for John O. Farmer, Inc(Co.), be best of his /her knowledge and belief. Signature of Applicant or Agent
Abandonment procedure of pit: Allowed liquid contents to evaporate, let cuttings dry and let undersigned hereby certifies that he let undersigned hereby certif	conservation Division backfilled WICHITA, KS for John O. Farmer, Inc(Co.), be best of his /her knowledge and belief. Signature of Applicant or Agent