KANSAS STATE CORPORATION COMMISSION

CONSERVATION DIVISION AGENT'S REPORT

TO: J. P. Roberts Assistant Director 500 Insurance Building 212 North Market Wichita 2, Kansas

Location; SW NW SW Sec. 29 Twp. 9 Rec. (E) (W) 24	Wichita 2, Kans	385							
Name of Field: Total Depth: 4150 244 I have this date completed supervision of plugging of: Lease Name: Pettett Well No. 1 Operator's Full Name: J. A. Terteling & Sons Complete Address: 320 Petroleum Club Bldg Denver, Colo Plugging Contractor Kimbark Exploration Address: Denver, Colo License No. Oil Well Gas Well Input Well SWD Well D&A X Other well as hereafter indicated; Was any delay in plugging operations caused by Conservation Division Agent? Yes No X If Yes how long? Reason: Operation Completed: Hour 3AM Day 20 Month 12 Year 61 The above well was plugged as follows: 8 5/8" 202' circulated with cement. Circulated hole with heavy mud, set cementing plug at 550', displaced 20 sax cement through drill pipe, heavy mud to 180', set plug and 20 sax cemen heavy mud to 35', set plug, 1/2 sack hulls and filled to bottom cellar with cement. Reviewed: Advances Field Supervisor Reviewed: Advances Field Supervisor	File No.	· · · · · · · · · · · · · · · · · · ·		Coun	ity: <u>B</u>	Gr	aham		
I have this date completed supervision of plugging of: Lease Name: Pettett	Location;	SW NW SW		Sec. 29	Twp. 9	Rge.	(E)	(W) 24
Lease Name: Pettett	Name of Field:					Total	Depth:	4150	PECC
Operator's Full Name: J. A. Terteling & Sons Complete Address: 320 Petroleum Club Bldg Denver, Colo Plugging Contractor Kimbark Exploration Address: Denver, Colo License No. Oil Weil Gas Well Input Well SWD Well D&A X Other well as hereafter indicated; Was any delay in plugging operations caused by Conservation Division Agent? Yes No X If Yes how long? Reason: Operation Completed: Hour 3AM Day 20 Month 12 Year 61 The above well was plugged as follows: 8 5/8" 202' circulated with cement. Circulated hole with heavy mud, set cementing plug at 550', displaced 20 sax cement through drill pipe, heavy mud to 180', set plug and 20 sax cement heavy mud to 35', set plug, 1/2 sack hulls and filled to bottom cellar with cement. Reviewed: Advances Field Supervisor Remarks: Reviewed: Advances Field Supervisor Remarks:	I have this dat	te completed	supervisi	on of pluggin	ng of:				
Complete Address: 320 Petroleum Club Bldg Denver, Colo Plugging Contractor Kimbark Exploration Address: Denver, Colo License No. Oil Well Gas Well Input Well SWD Well D&A X Other well as hereafter indicated; Was any delay in plugging operations caused by Conservation Division Agent? Yes No X If Yes how long? Reason: Operation Completed: Hour SAM Day 20 Month 12 Year 61 The above well was plugged as follows: 8 5/8" 202' circulated with cement. Circulated hole with heavy mud, set cementing plug at 550', displaced 20 sax cement through drill pipe, heavy mud to 180', set plug and 20 sax ceme heavy mud to 35', set plug, 1/2 sack hulls and filled to bottom cellar with cement. Reviewed: Acceptable Supervisor Reviewed: A	Lease Name: Pe	ettett			Well No	1			
Plugging Contractor Kimbark Exploration Address: Denver, Colo License No. Oil Weil Gas Weil Input Weil SWD Weil D & A X Other well as hereafter indicated; Was any delay in plugging operations caused by Conservation Division Agent? Yes No X If Yes how long? Reason: Operation Completed: Hour 3AM Day 20 Month 12 Year 61 The above well was plugged as follows: 8 5/8" 202' circulated with cement. Circulated hole with heavy mud, set cementing plug at 550', displaced 20 sax cement through drill pipe, heavy mud to 180', set plug and 20 sax cement heavy mud to 35', set plug, 1/2 sack hulls and filled to bottom cellar with cement. Reviewed: Address Field Supervisor Reviewed: Address Field Supervisor Reviewed: Address Field Supervisor Remarks: PACE 18 C. 1	Operator's Full	l Name:	J. A. T	erteling &	Sons			-,	·
Address: Denver, Colo License No. Oli Well Gas Well Input Well SWD Well D&A X Other well as hereafter indicated; Was any delay in plugging operations caused by Conservation Division Agent? Yes No X If Yes how long? Reason: Operation Completed: Hour 3AM Day 20 Month 12 Year 61 The above well was plugged as follows: 8 5/8" 202' circulated with cement. Circulated hole with heavy mud, set cementing plug at 550', displaced 20 sax cement through drill pipe, heavy mud to 180', set plug and 20 sax cement heavy mud to 35', set plug, 1/2 sack hulls and filled to bottom cellar with cement. Signed: Conservation Division Agent RECE! V List Field Supervisor Reviewed: Advantage Conservation Division Agent Reviewed: Advantage Conservation Division Agent RECE! V List Field Supervisor Recommends:	Complete Addres	3S:	320 Pet	roleum Club	Bldg	Denve	er, Colo)	
Other well as hereafter indicated; Was any delay in plugging operations caused by Conservation Division Agent? Yes No X If Yes how long? Reason; Operation Completed: Hour 3AM Day 20 Month 12 Year 61 The above well was plugged as follows: 8 5/8" 202' circulated with cement. Circulated hole with heavy mud, set cementing plug at 550', displaced 20 sax cement through drill pipe, heavy mud to 180', set plug and 20 sax cement heavy mud to 35', set plug, 1/2 sack hulls and filled to bottom cellar with cement. Reviewed: Hour Adams Conservation Division Agent Reviewed: Hour Adams Conservat	Plugging Contra	actor	Kimbark	Exploration	on	·····		; iuuru (1111 - 1111 - 1111 - 1111 - 1111 - 1111 - 1111 - 1111 - 1111 - 1111 - 1111 - 1111 - 1111 - 1111 - 1111	
Other well as hereafter indicated; Was any delay in plugging operations caused by Conservation Division Agent? Yes NoX If Yes how long?	Address:		Denver,	Coló	Lic	ense No			
Was any delay in plugging operations caused by Conservation Division Agent? Yes No X If Yes how long? Reason: Operation Completed: Hour 3AM Day 20 Month 12 Year 61 The above well was plugged as follows: 8 5/8" 202' circulated with cement. Circulated hole with heavy mud, set cementing plug at 550', displaced 20 sax cement through drill pipe, heavy mud to 180', set plug and 20 sax ceme heavy mud to 35', set plug, 1/2 sack hulls and filled to bottom cellar with cement. Signed: Conservation Division Agent Reviewed: Harvel Advances Field Supervisor Reviewed: DATE Supervisor Remarks: DATE DATE Agent RECE! V L.: PEC 22 1961 Remarks:	Oil Well	Gas Well	In	put Well	SWD	Well_	D	& A	x
If Yes how long? Reason: Operation Completed: Hour 3AM Day 20 Month 12 Year 61 The above well was plugged as follows: 8 5/8" 202' circulated with cement. Circulated hole with heavy mud, set cementing plug at 550', displaced 20 sax cement through drill pipe, heavy mud to 180', set plug and 20 sax ceme heavy mud to 35', set plug, 1/2 sack hulls and filled to bottom cellar with cement. Signed: Conservation Division Agent Reviewed: April 3 Supervisor Reviewed: PECEIV 13-1-2-2-6 PEC 2 2 1961 Remarks:	Other well as I	nereafter in	dicated;			· · · · · · · · · · · · · · · · · · ·			
Operation Completed: Hour 3AM Day 20 Month 12 Year 61 The above well was plugged as follows: 8 5/8" 202' circulated with cement. Circulated hole with heavy mud, set cementing plug at 550', displaced 20 sax cement through drill pipe, heavy mud to 180', set plug and 20 sax ceme heavy mud to 35', set plug, 1/2 sack hulls and filled to bottom cellar with cement. Signed: Conservation Division Agent Reviewed: ARECE! V 12-22-6/ Field Supervisor Remarks:	Was any delay i	in plugging	operations	caused by Co	onservatio	n Divisi	on Agent	?	·
Operation Completed: Hour 3AM Day 20 Month 12 Year 61 The above well was plugged as follows: 8 5/8" 202' circulated with cement. Circulated hole with heavy mud, set cementing plug at 550', displaced 20 sax cement through drill pipe, heavy mud to 180', set plug and 20 sax ceme heavy mud to 35', set plug, 1/2 sack hulls and filled to bottom cellar with cement. Signed: Conservation Division Agent Reviewed: ABOUTH ASSUMPTION COMMISSION First Supervisor RECEIVE 11-2-2-6/ PEC 22 1961 PEC 22 1961	Yes	No X				·			
The above well was plugged as follows: 8 5/8" 202' circulated with cement. Circulated hole with heavy mud, set cementing plug at 550', displaced 20 sax cement through drill pipe, heavy mud to 180', set plug and 20 sax ceme heavy mud to 35', set plug, 1/2 sack hulls and filled to bottom cellar with cement. Signed: Conservation Division Agent Reviewed: April April Correction Commission Field Supervisor Remarks: PLC 2 1961 Remarks:	If Yes how long	g?			Reason:		·		
The above well was plugged as follows: 8 5/8" 202' circulated with cement. Circulated hole with heavy mud, set cementing plug at 550', displaced 20 sax cement through drill pipe, heavy mud to 180', set plug and 20 sax ceme heavy mud to 35', set plug, 1/2 sack hulls and filled to bottom cellar with cement. Signed: Conservation Division Agent Reviewed: April April Correction Commission Field Supervisor Remarks: PLC 2 1961 Remarks:	***************************************			x					
The above well was plugged as follows: 8 5/8" 202' circulated with cement. Circulated hole with heavy mud, set cementing plug at 550', displaced 20 sax cement through drill pipe, heavy mud to 180', set plug and 20 sax ceme heavy mud to 35', set plug, 1/2 sack hulls and filled to bottom cellar with cement. Signed: Conservation Division Agent Reviewed: April April Correction Commission Field Supervisor Remarks: PLC 2 1961 Remarks:								· 	
Signed: Signed: Conservation Division Agent Reviewed: Agent Supervisor Remarks:	Operation Comp.	leted: Hour	3AM	Day 20	Month	12	Year	·.	61
Circulated hole with heavy mud, set cementing plug at 550', displaced 20 sax cement through drill pipe, heavy mud to 180', set plug and 20 sax ceme heavy mud to 35', set plug, 1/2 sack hulls and filled to bottom cellar with cement. Signed: Conservation Division Agent Reviewed: Agent Field Supervisor Remarks: Conservation Division Agent Record C	The above well	was plugged	as follow	s:					
sax cement through drill pipe, heavy mud to 180', set plug and 20 sax ceme heavy mud to 35', set plug, 1/2 sack hulls and filled to bottom cellar wit cement. Signed: Conservation Division Agent Reviewed: Field Supervisor Remarks: Remarks: DATE Jackson	8 5/8" .2021	circulat	ed with	cement.					
heavy mud to 35', set plug, 1/2 sack hulls and filled to bottom cellar wit cement. Signed: Conservation Division Agent Reviewed: Field Supervisor Remarks: Remarks: DATE Agent RECEIV Latter Corresponding Commission PEC 22 1961	Circulated	hole with	ı heavy m	ud, set cen	nenting	plug at	550 ' ,	disp	laced 20
Reviewed: Signed: Conservation Division Agent Reviewed: Agent Reviewed: Fiere Supervisor Remarks: Remarks:	sax cement	through d	rill pip	e, heavy mu	id to 18	0 ', set	plug s	ind 2	O sax cemer
Signed:	heavy mud	to 35 ', se	t plug,	1/2 sack hu	ills and	filled	l to bot	tom	cellar with
Reviewed: Aralf Mollis Field Supervisor Recommendation Division Agent Recommendation Division Division Division Agent Recommendation Division D	cement.				·				
Reviewed: Aralf Mollis Field Supervisor Reviewed: DEC 22 1961 Remarks: Conservation Division Agent RECEIV L. 1 RECEIV L. 1 PEC 22 1961 DATE //22/62		_							
Reviewed: Arcal Alace Supervisor Reviewed: STATE CORPORATION COMMISSION PEC 22 1961 Remarks: DATE //22/62									
Reviewed: Harald Holes Field Supervisor RECEIV 5131 STATE CORRORATION COMMISSION PEC 22 1961 Remarks: DATE 1/22/62		· · · · · · · · · · · · · · · · · · ·	•		Signe	ed:	Zedon	, Le	Quely .
Reviewed: Supervisor PEC 22 1961 Remarks: DATE CORPORATION COMMISSION DEC 22 1961						Conse	ervation	Divis	Agent
a vicinity in the part of the		Jarold (Hollis Supervisor	, , , , , , , , , , , , , , , , , , ,	R.	IN DATE _	REI VIAE GOR	PRATION EC 22	COMMISSION 12-22-61