## KANSAS CORPORATION COMMISSION OIL & GAS CONSERVATION DIVISION

## **WELL PLUGGING APPLICATION**

Please TYPE Form and File ONE Copy

Form CP-1 September 2003 This Form must be Typed Form must be Signed All blanks must be Filled

or of this well). This must be listed for wells drilled since 1967; if no API # was issued,
<u>)</u> .
KCC License #: 32334
City: Oklahoma City
3154-0496 Contact Phone: (405 ) 935 - 4775
5 Sec. 15 Twp. 31S S. R. 42 East ✓ West
County: Morton
h (from nearest outside section corner) Line of Section (Not Lease Line)
(from nearest outside section corner) Line of Section (Not Lease Line)
odic Water Supply Well
Docket # Other:
Cemented with:Sacks
Cemented with: 700 Sacks
Cemented with: 150 Sacks
'-2932' (OA), 4 spf, shut-in; Morrow 'B' 5,064'-5,122' (OA), 4 spf, shut-in;
Junk in Hole  aded): See attached sheet  KANSAS CORPORADO
S ACO-1 filled? Yes No APR 0 1 2009
CONSERVATION BY WAR
WICHITA, KS
seq. and the Rules and Regulations of the State Corporation Commission.
ing operations:
Phone: (620 ) 277 - 0803 ext. 11
City / State: Garden City, KS 67846
KCC License #:(Contractor's)
Phone: (785 ) 483 - 2627
1200 files
perator or Argent
ham. tower-King
0 S. Market - Room 2078, Wichita, Kansas 67202

## **Procedure:**

- 1. MIRU workover unit, and dig out bradenhead. TOOH with any tubing that is in the hole laying down in singles. RIH with sand line, tag TD. Order out 2-3/8" 4.7# J-55 workstring, length based on TD determined above.
- 2. MIRU wireline unit, crane, and grease. PU 5 ½" CIBP and setting tool, RIH and set CIBP at ±5,000' or higher if 5,000' cannot be reached per KCC confirmation. Dump 2 sx of cement on CIBP, POOH. PU 2nd 5 ½" CIBP and setting tool, RIH and set CIBP at ±2,750'. Dump 2 sx of cement on CIBP, POOH.
- 3. NU 5-1/2" pull sub, work 5-1/2" CSG out of slips & pull freepoint on CSG. RIH with WL and tools, cut CSG above freepoint (minimum cut: 1,558'). POOH and RDMO WL. Rig up on 5 ½" casing, open surface valve and attempt to establish circulation up 8-5/8" x 5 ½" annulus. If circulation is achieved, mix and pump 50 sx cement for stub plug/ surface CSG shoe plug. TOOH w/ 5-1/2" CSG laying down.
- 4. TIH w/ 2-3/8" TBG to check TOC after cement has had time to set up. If TOC is less than 1,425', mix & pump 40 sx cement to finish out surface CSG plug. TOOH w/ TBG to 550', mix and pump 40 sx cement of cement for the useable water horizon plug. TOOH w/ TBG to 30', mix and pump 10 sx cement to surface for surface plug.
- 5. Cut off casing 4 ft. below ground level and weld on steel ID plate. RDMO WOR.
- 6. Remove all production equipment and restore well site to original condition.



26929

REMIT TO P.O. BOX 31 RUSSELL, KANSAS 67665 SERVICE POINT:

Liberal KS

DATE 3-19-09 15 315 42 W	CALLED OUT	ON LOCATION	JOB START	JOB FINISH 5:30 pm
	0 000		COUNTY	STATE .
LEASE COllingwoodVELL# 1-15 LOCATION 7 N. O.		•	Mocten	TV-2.
OLD DR NEW (Circle one)	st Inta	<del></del>	j	
CONTRACTOR SSI #6	OWNER			
TYPE OF JOB Plus	OWNER			
HOLE SIZE T.D.	CEMENT			
CASING SIZE DEPTH	AMOUNT OR	DERED 20	OSK 1	0/110
TUBING SIZE DEPTH	4% Re		<del></del>	7 40
DRILL PIPE DEPTH	36			
TOOL DEPTH				
PRES. MAX MINIMUM	COMMON		@	
MEAS. LINE SHOE JOINT	POZMIX		_	
CEMENT LEFT IN CSG.		( <sub>O</sub> )	@20.80	4
PERFS.	CHLORIDE	-	@	<del></del> .
DISPLACEMENT	ASC		@	
EQUIPMENT		nt (60/40	<b>7</b> @	
EQUI MENT	-033	1200	@ 14.05	
7 461			@	1
PUMPTRUCK CEMENTER Kenny Yoga & Kid	<b>2</b> 9		@	
#471-469 HELPER Kicky			@	
BULK TRUCK			_@	
#472-468 DRIVER Fransisco			@	
BULK TRUCK			_@	
# DRIVER	HANDLING	190.00	_@ <u>Z.4D</u>	
	MILEAGE		·ia	45/
REMARKS:			TOTAL	
Thank You !!!!			KP.	
		SERVI	CE	
	DEPTH OF JOH	3		
	PUMP TRUCK	CHARGE		
	EXTRA FOOTA	AGE		
	MILEAGE	30,00	@ 7.00	
	MANIFOLD		_@	
			_@	
			_@	
CHARGE TO: Chesapeake				
•	*		TOTAL	<u> </u>
STREET	A *** (First			
CITYSTATEZIP	KANSAS CORPORAT	IVEL) PAGGM&USEBOAT		
CII I		<b>LUGM&amp;SBIDOAT</b>	C EQUIPMEN	ľT
	APR 0 1	2009	*** 	
			@	
	<u>Conservation</u> <u>Wichita,</u>	DIVISION	<b>_</b> @	
The Allied Committee Co. The		<u>~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~</u>	_@	
To Allied Cementing Co., Inc.			_@	
You are hereby requested to rent cementing equipment			_@	
and furnish cementer and helper to assist owner or				
contractor to do work as is listed. The above work was			TOTAL	
done to satisfaction and supervision of owner agent or		:		
contractor. I have read & understand the "TERMS AND	TAX		_	
CONDITIONS" listed on the reverse side.		~~		
	TOTAL CHAR	GE		
	DISCOUNT —		IF PAI	D IN 30 DAYS
C 0 31		. *		
\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\	· [	3.1	TON	
SIGNATURE WITH SHALL		HN DDD	ED NAME	
		PRINT	ED INVINIT	•