
GEORGE DOCKING MARION BEATTY

HARRY G. WILES

RICHARD C. BYRD

RAYMOND B. HARVEY

CLYDE E. MILLIGAN



## 15-051-00353-00-00

## State Corporation Commission

## CONSERVATION DIVISION

(Oil, Gas and Water)
500 Insurance Bldg. 212 N. Market
WICHITA, KANSAS
JEWEL M. OGDEN, Director

STATE CORPORATION COMMISSION
JUN 2 4 1959

Jewel M. Ogden, Director 500 Insurance Building 212 North Market Wichita 2. Kansas

Chairman

Secretary

Commissioner

Commissioner

CONSERVATION DIVISION Wichita, Mansas

Conservation Division Agent

Wichita 2, Ka	11548						
Dear Sir:					•		
I have this d	ate	6-17-59	,	19,	authorized	the follo	wLi
plugging opera	ation:				-		
Operator's Fu	11 Name:	Imperial (	Oil of	Kan <b>s</b> a s			
Complete Addre	ess:	Wichita, B	Kans				
Lease Name:		Fisher			Well No	A-l	
Location:	NW NW SW	Sec.			•		
	Ellis	,					
Other well as	hereafter	Input indicated:to plug well a y mud, set p	s follo	W8:		•	
Other well as Operator was	hereafter instructed with heav	indicated:to plug well a	s follo	ws: t 550',	<b>displac</b> e	20 sax (	er
Other well as Operator was: Coulate hole Cough drill p	hereafter instructed with heav	indicated:  to plug well a y mud, set p  to 215!, set	s follo plug a t plugs	ws: t 550',	<b>displac</b> e	20 sax (	er
Other well as Operator was: Culate hole Cough drill p	hereafter instructed with heav	indicated:  to plug well a y mud, set p  to 215!, set	s follo plug a t plugs	ws: t 550',	<b>displac</b> e	20 sax (	er
Other well as Operator was: Culate hole Cough drill p	hereafter instructed with heav	indicated:  to plug well a y mud, set p  to 215!, set	s follo plug a t plugs	ws: t 550',	<b>displac</b> e	20 sax (	er
Other well as Operator was: Culate hole Cough drill p	hereafter instructed with heav	indicated:  to plug well a y mud, set p  to 215!, set	s follo plug a t plugs	ws: t 550',	<b>displac</b> e	20 sax (	er
Other well as Operator was: culate hole rough drill p	hereafter instructed with heav	indicated:  to plug well a y mud, set p  to 215!, set	s follo plug a t plugs	ws: t 550',	<b>displac</b> e	20 sax (	en
Other well as Operator was: culate hole rough drill p	hereafter instructed with heav	indicated:  to plug well a y mud, set p  to 215!, set	s follo plug a t plugs	ws: t 550',	<b>displac</b> e	20 sax (	en
Other well as	hereafter instructed with heav	indicated:  to plug well a y mud, set p  to 215', set  10 sax ceme	s follo plug a t pluga ent.	ws: t 550',	displace	20 sax (	en