KANSAS CORPORATION COMMISSION OIL & GAS CONSERVATION DIVISION

Form CDP-4 April 2004 Form must be Typed

CLOSURE OF SURFACE PIT

Operator Name: John Roy Evans Oil Co, LLC	License Number: 7030
Operator Address: P.O. Box 385, Claflin, KS 67525	
Contact Person: Gary Kirmer	Phone Number: (620) 793 - 2026
Permit Number (API No. if applicable): 15-053-21220-0000	Lease Name & Well No.: Peterman A #4
Type of Pit:	Pit Location (QQQQ):
Emergency Pit Burn Pit	<u>SW _ SE _ SW</u>
☐ Settling Pit ✓ Drilling Pit	Sec. 28 _Twp. 17 _ R. 10 East
Workover Pit Haul-Off Pit	330 Feet from North / V South Line of Section
	3630 Feet from ✓ East / West Line of Section
	Ellsworth County
Date of closure: 3/5/09 Was an artificial liner used? Yes No If no, how were the sides and bottom sealed to prevent downward migration of the pit contents? Native mud and bentonite to seal off pits.	
Native mud and pentonite to seal off pits.	and the second s
Native mud and bentonite to seal off pits.	MAR 1 0 2009
Native mud and bentonite to seal off pits.	MAR 1 0 2009 RECEIVED
Abandonment procedure of pit: Clear liquids hauled off. Pits allowed to dry and backfilled.	RECEIVED
Abandonment procedure of pit:	RECEIVED
Abandonment procedure of pit: Clear liquids hauled off. Pits allowed to dry and backfilled.	RECEIVED ntendent for John Roy Evans Oil Co., LLC (Co.),
Abandonment procedure of pit: Clear liquids hauled off. Pits allowed to dry and backfilled. The undersigned hereby certifies that he / she is Gary Kirmer/ Production Superior	RECEIVED ntendent for John Roy Evans Oil Co., LLC (Co.),
Abandonment procedure of pit: Clear liquids hauled off. Pits allowed to dry and backfilled. The undersigned hereby certifies that he / she is Gary Kirmer/ Production Superior	RECEIVED ntendent for John Roy Evans Oil Co., LLC(Co.),
Abandonment procedure of pit: Clear liquids hauled off. Pits allowed to dry and backfilled. The undersigned hereby certifies that he / she is Gary Kirmer/ Production Superior	ntendent for John Roy Evans Oil Co., LLC (Co.), best of his /her knowledge and belief. Signature of Applicant or Agent
Abandonment procedure of pit: Clear liquids hauled off. Pits allowed to dry and backfilled. The undersigned hereby certifies that he / she is Gary Kirmer/ Production Superior a duly authorized agent, that all information shown hereon is true and correct to the	ntendent for John Roy Evans Oil Co., LLC (Co.), best of his /her knowledge and belief. Signature of Applicant or Agent