KANSAS CORPORATION COMMISSION OIL & GAS CONSERVATION DIVISION

Form CDP-4 April 2004 Form must be Typed

CLOSURE OF SURFACE PIT

Operator Name: H & C Oil Operating, Inc.	License Number: 8914
	200130 Number: 0914
Operator Address: P.O. Box 86 Plainville, Kansas 67663	
Contact Person: Charles R. Ramsay	Phone Number: (785) 434 - 7434
Permit Number (API No. if applicable): 15-065-23-455-00-00	Lease Name & Well No.: Roberts A
Type of Pit:	Pit Location (QQQQ):
Emergency Pit Burn Pit	W2 _ E2 _ W2 _ NE
Settling Pit	Sec. 8 Twp. 7S R. 23 ☐ East ✓ West
Workover Pit Haul-Off Pit	1320 Feet from North / South Line of Section
	1900 Feet from ✓ East / West Line of Section
	Graham
County	
Date of closure: 3/26/2009	
Was an artificial liner used? ☐ Yes ✓ No	
Was an artificial liner used? ☐ Yes ✓ No	
If no, how were the sides and bottom sealed to prevent downward migration of the pit contents?	
	VANDA - I SEE STATE
Natural gumbo seal	KANSAS CORPORATION COMMISSION
Natural gumbo seal	KANSAS CORPORATION COMMISSION MAR 3 1 2009
Natural gumbo seal	MAR 3 1 2009 CONSERVATION DIVISION
	MAR 3 1 2009
Abandonment procedure of pit:	MAR 3 1 2009 CONSERVATION DIVISION WICHITA, KS
	MAR 3 1 2009 CONSERVATION DIVISION WICHITA, KS
Abandonment procedure of pit:	MAR 3 1 2009 CONSERVATION DIVISION WICHITA, KS
Abandonment procedure of pit:	MAR 3 1 2009 CONSERVATION DIVISION WICHITA, KS
Abandonment procedure of pit: Remove mud and free fluids from drill site, let water evapor	MAR 3 1 2009 CONSERVATION DIVISION WICHITA, KS
Abandonment procedure of pit: Remove mud and free fluids from drill site, let water evaporation. The undersigned hereby certifies that he / she is President	MAR 3 1 2009 CONSERVATION DIVISION WICHITA, KS Drate, backfill when dry H & C Oil Operating, Inc (Co.).
Abandonment procedure of pit: Remove mud and free fluids from drill site, let water evapor	MAR 3 1 2009 CONSERVATION DIVISION WICHITA, KS Drate, backfill when dry for H & C Oil Operating, Inc (Co.), best of his /her knowledge and belief.
Abandonment procedure of pit: Remove mud and free fluids from drill site, let water evaporation. The undersigned hereby certifies that he / she is President	MAR 3 1 2009 CONSERVATION DIVISION WICHITA, KS Drate, backfill when dry for H & C Oil Operating, Inc (Co.), best of his /her knowledge and belief.
Abandonment procedure of pit: Remove mud and free fluids from drill site, let water evaporate to the undersigned hereby certifies that he / she is President a duly authorized agent, that all information shown hereon is true and correct to the	MAR 3 1 2009 CONSERVATION DIVISION WICHITA, KS Drate, backfill when dry for H&C Oil Operating, Inc (Co.), best of his /her knowledge and belief. Signature of Applicant or Agent
Abandonment procedure of pit: Remove mud and free fluids from drill site, let water evaporation. The undersigned hereby certifies that he / she is President	MAR 3 1 2009 CONSERVATION DIVISION WICHITA, KS Drate, backfill when dry for H&C Oil Operating, Inc (Co.), best of his /her knowledge and belief. Signature of Applicant or Agent
Abandonment procedure of pit: Remove mud and free fluids from drill site, let water evaporate and signed hereby certifies that he / she is	MAR 3 1 2009 CONSERVATION DIVISION WICHITA, KS Drate, backfill when dry for H & C Oil Operating, Inc (co.), best of his /her knowledge and belief. Signature of Applicant or Agent That a2009
Abandonment procedure of pit: Remove mud and free fluids from drill site, let water evaporate to me on this 22 th day of	MAR 3 1 2009 CONSERVATION DIVISION WICHITA, KS Drate, backfill when dry for H & C Oil Operating, Inc (co.), best of his /her knowledge and belief. Signature of Applicant or Agent
Abandonment procedure of pit: Remove mud and free fluids from drill site, let water evaporation and signed hereby certifies that he / she is	MAR 3 1 2009 CONSERVATION DIVISION WICHITA, KS Drate, backfill when dry for H & C Oil Operating, Inc (co.), best of his /her knowledge and belief. Signature of Applicant or Agent That a2009