## Kansas Corporation Commission Oil & Gas Conservation Division

Form CDP-4 April 2004 Form must be Typed

## **CLOSURE OF SURFACE PIT**

Operator Name: Layne Energy Operating, LLC	License Number: 33365
Operator Address: 1900 Shawnee Mission Parkway, Mission V	Noods, KS 66205
Contact Person: Kimberlee Dixon	Phone Number: ( 620 ) 627 - 2499
Permit Number (API No. if applicable): 15-205-27435-0000	Lease Name & Well No.: Mahaffey 3-36
Type of Pit:	Pit Location (QQQQ):
Emergency Pit Burn Pit	W2 _ E2 _ NW _
Settling Pit	Sec. 36 Twp. 30 R. 16 V East West
Workover Pit Haul-Off Pit	1267 Feet from V North / South Line of Section
	1666 Feet from ☐ East / ✓ West Line of Section
	Wilson County
	County
Date of closure: April 7, 2009	
Was an artificial liner used?	
If no, how were the sides and bottom sealed to prevent downward migration of the	pit contents?
Self-Sealing Pit	
	RECEIVED
	RECEIVED
Self-Sealing Pit	RECEIVED APR 2 7 2009
Self-Sealing Pit  Abandonment procedure of pit:	APR 2 7 2009
Self-Sealing Pit	
Self-Sealing Pit  Abandonment procedure of pit:	APR 2 7 2009
Self-Sealing Pit  Abandonment procedure of pit:	APR 2 7 2009
Self-Sealing Pit  Abandonment procedure of pit:	APR 2 7 2009 KCC WICHITA
Abandonment procedure of pit:  Let evaporate until dry, then backfilled and restored.	APR 2 7 2009  KCC WICHITA  for Layne Energy Operating, LLC (Co.),
Abandonment procedure of pit:  Let evaporate until dry, then backfilled and restored.  The undersigned hereby certifies that he / she is	APR 2 7 2009  KCC WICHITA  for Layne Energy Operating, LLC (Co.),
Abandonment procedure of pit:  Let evaporate until dry, then backfilled and restored.  The undersigned hereby certifies that he / she is	APR 2 7 2009  KCC WICHITA  for Layne Energy Operating, LLC (Co.),
Abandonment procedure of pit:  Let evaporate until dry, then backfilled and restored.  The undersigned hereby certifies that he / she is	APR 2 7 2009  KCC WICHITA   for Layne Energy Operating, LLC (Co.), a best of his /her knowledge and belief.
Abandonment procedure of pit:  Let evaporate until dry, then backfilled and restored.  The undersigned hereby certifies that he / she is	APR 2 7 2009  KCC WICHITA   for Layne Energy Operating, LLC (Co.), a best of his /her knowledge and belief.
Abandonment procedure of pit:  Let evaporate until dry, then backfilled and restored.  The undersigned hereby certifies that he / she is	APR 2 7 2009  KCC WICHITA   for Layne Energy Operating, LLC (Co.), a best of his /her knowledge and belief.  Signature of Applicant or Agent  Occ.
Abandonment procedure of pit:  Let evaporate until dry, then backfilled and restored.  The undersigned hereby certifies that he / she is	APR 2 7 2009  KCC WICHITA   for Layne Energy Operating, LLC (Co.), a best of his /her knowledge and belief.