Kansas Corporation Commission Oil & Gas Conservation Division

Form CDP-4 April 2004 Form must be Typed

CLOSURE OF SURFACE PIT

137	
Operator Name: Layne Energy Operating, LLC	License Number: 33365
Operator Address: 1900 Shawnee Mission Parkway, Mission Woods, KS 66205	
Contact Person: Kimberlee Dixon	Phone Number: (620) 627 - 2499
Permit Number (API No. if applicable): 15-205-27164-0000	Lease Name & Well No.: Mahaffey 1-36
Type of Pit:	Pit Location (QQQQ):
Emergency Pit Burn Pit	NW _ NE _ NE
Settling Pit ✓ Drilling Pit	Sec. 36 Twp. 30 R. 16 V East West
Workover Pit Haul-Off Pit	350 Feet from V North / South Line of Section
	727 Feet from 🗸 East / West Line of Section
· 	Wilson County
Date of closure: April 7, 2009 Was an artificial liner used? Yes No If no, how were the sides and bottom sealed to prevent downward migration of the pit contents? Self-Sealing Pit	
	RECEIVED
	RECEIVED
Abandonment procedure of pit:	APR 2 7 2009
Abandonment procedure of pit:	APR 2 7 2009
Abandonment procedure of pit:	APR 2 7 2009
Abandonment procedure of pit: Let evaporate until dry, then backfilled and restored.	APR 2 7 2009 KCC WICHITA for Layne Energy Operating, LLC (Co.),
Abandonment procedure of pit: Let evaporate until dry, then backfilled and restored. The undersigned hereby certifies that he / she is Agent a duly authorized agent, that all information shown hereon is true and correct to the	APR 2 7 2009 KCC WICHITA for Layne Energy Operating, LLC (Co.),
Abandonment procedure of pit: Let evaporate until dry, then backfilled and restored. The undersigned hereby certifies that he / she is Agent a duly authorized agent, that all information shown hereon is true and correct to the	APR 2 7 2009 KCC WICHITA for Layne Energy Operating, LLC (Co.),
Abandonment procedure of pit: Let evaporate until dry, then backfilled and restored. The undersigned hereby certifies that he / she is	APR 2 7 2009 KCC WICHITA for Layne Energy Operating, LLC (Co.), best of his /her knowledge and belief.
Abandonment procedure of pit: Let evaporate until dry, then backfilled and restored. The undersigned hereby certifies that he / she is	APR 2 7 2009 KCC WICHITA for Layne Energy Operating, LLC (Co.), best of his /her knowledge and belief.
Abandonment procedure of pit: Let evaporate until dry, then backfilled and restored. The undersigned hereby certifies that he / she is	APR 2 7 2009 KCC WICHITA for Layne Energy Operating, LLC (Co.), best of his /her knowledge and belief.