Notice: Fill out COMPLETELY and return to Conservation Division at the address below within 60 days from plugging date.

## KANSAS CORPORATION COMMISSION OIL & GAS CONSERVATION DIVISION

## WELL PLUGGING RECORD K.A.R. 82-3-117

Form CP-4
December 2003
Type or Print on this Form
Form must be Signed
All blanks must be Filled

Lease Operator: C&K Oil API Number: 15 - 185-20305 - 00 00 Morrison-Long "A" Address: POB 531, Claffin, KS 67525 Phone: (620 ) 786 -8744 Operator License #: 31561 Well Number: Spot Location (QQQQ): NW - SE Type of Well: Oil Docket #:. (Oil, Gas D&A, SWD, ENHR, Water Supply Well, Cathodic, Other) (If SWD or ENHR) Feet from North / South Section Line 990 The plugging proposal was approved on: \_\_(Date) Feet from Fast / West Section Line (KCC District Agent's Name) Is ACO-1 filed? ✓ Yes No. If not, is well log attached? Yes No Producing Formation(s): List All (If needed attach another sheet) Date Well Completed:. Depth to Top: \_ 2/25/09 Plugging Commenced: Depth to Top: Bottom: Plugging Completed: Depth to Top: \_\_ Bottom: Show depth and thickness of all water, oil and gas formations. Oil, Gas or Water Records Casing Record (Surface Conductor & Production) Formation Content From To Size Pulled Out Put In 8 5/8" 532' None 4 1/2" 3852' None Describe in detail the manner in which the well is plugged, indicating where the mud fluid was placed and the method or methods used in introducing it into the hole. If cement or other plugs were used, state the character of same depth placed from (bottom), to (top) for each plug set. Perferate @ 900'. Ran tubing to 3453'. Mix 15 sax gel & 50 sks cement w/ 200 lbs. hulls. Pull tubing to 900'. Pump 10 bbls water establish circualtion. Mix cement 150 sks w/ 100# hulls. Lost circulation. Wait 4 hrs. on cement. Run in with tubing to 900'. Mix 16 sks. gel, had good circulation. Mix cement 100 sks. 60/40 4 % gel, lost circulation. Pull tubing. Check top of cement w/ tubing. Bottom plug @ 3360'. Pull tubing to 900'. Mix 20 sks. gel & 300# hulls. Mix 50 sks. cement & 100# hulls. Lost Circulation. (See Additional Sheet) Name of Plugging Contractor: Classic Well Service RECEIVED KANSAS CORPORATION COMMISSION Address: POB 539, Claffin, KS 67525 MAR 3 1 2009 Name of Party Responsible for Plugging Fees: C&K Oil CONSERVATION DIVISION State of (Employee of Operator) or (Operator) on above-described well, being first duly swom on oath, says. That I have knowledge of the facts statements, and matters herein contained, and the log of the above-described well is as filed, and the same are true and correct, so help me God.

Mail to: KCC - Conservation Division, 130 S. Market - Room 2078, Wichita, Kansas 67202

State Of Kansas

Notary Public My Commission Expires

SUBSCRIBED and SWORN TO before me this 30

CLAFLIN KS 67525

My Commission Expires:\_\_\_



C & K Oil.....

Chris Haffman P.O. Box 531 Claffin, KS 67525

Telephane (620) 587-0150

(continued)

Mix 50 sks. cement w/ Thix O Tropic Additive. Pull tubing & wait on cement. Tagged cement @ 760'. Ran tubing to 758'. Mix 10 sks. gel & 300# hulls. Mix 300 sks. 60/40, 4% gel w/ 1 sk CC in first 50 sks. Good circulation out of Braiden Head & little bit of circulation out of casing. Mix 20 sks. cement and circulate out of Braiden Head. Shut in Braiden Head. No-circulation out of casing. Ran 30 sks. cement & pull tubing. Top off casing w/ 10 sks. cement. Plugging Complete.

RECEIVED KANSAS CORPORATION COMMISSION

MAR 3 1 2009

CONSERVATION DIVISION WICHITA, KS