Date: 12/02/08	L/GAS REGULA District: <u>01</u>				#:
Date: 12/02/08	New Situ		Г	Lease Ins	
		e to Request	F	Complain	
	Follow-U	-		Field Rep	
Operator License No: 3842	API Well Num	ber: <u>15-10</u> 1	1-22,139-0	00-00	
Op Name: Larson Engineering, Inc. dba Larson Operating Cor	npany Spot: NW-S	E-NE-SW	_Sec <u>3</u>	Twp <u>19</u>	_S Rng <u>30</u> E / W
Address 1: 562 W State Rd. 4					N/S Line of Section
Address 2:	2090			Feet from	E / W Line of Section
City: Olmitz	GPS: Lat: <u>38</u>	.42897	Long: <u>100</u>	).62307	Date: <u>12/2/08</u>
State: Kansas Zip Code: 67564 -85	61_ Lease Name: _	Bryant			Well #: <u>1-3</u>
Operator Phone #: <u>(620) 653-7368</u>	County: Lar	e			
Reason for Investigation:					
Witness Alt.II					
Problem:					
None cement circulated to surface					
Persons Contacted:					
Findings:					
8-5/8" @ 248'W/180sxs cement TD @ 4660' 5-1/2" @ 4659'W/225sxs cement Port Collar @ 2141' cemented with 200	sxs-smd-1/4# flo s	eal-2%cc-′	15sxs we	ent to pit	
Action/Recommendations:	Follow Up Required [	Yes No	, #T	Date: _	
Alt.II requirements have been met					
					RECEIVED KANSAS CORPORATION COMMISSIO
					DEC 1 9 2008
DEC 1 5 2008			· · · <del>-</del>		CONSERVATION DIVISION WICHITA, KS
Verification Sources:					Photos Taken:

TA Program

Courthouse

By: Michael Maier

Retain 1 Copy District Office Send 1 Copy to Conservation Division District Files

RBDMS

T-I Database
Other:

Form: <u>02/22/2008</u>