KANSAS CORPORATION COMMISSION OIL & GAS CONSERVATION DIVISION

Form CDP-4 April 2004 Form must be Typed

CLOSURE OF SURFACE PIT

Operator Name: McCoy Petroleum Corporation	License Number: 5003
Operator Address: 8080 E. Central, Suite #300, Wichita, KS 67206	
Contact Person: Brent B. Reinhardt	Phone Number: 316-636-2737x128
Permit Number (API No. if applicable): 15-153-20861-0000	Lease Name & Well No.: RYAN "A" #1-14
Type of Pit: Emergency Pit	Pit Location (QQQQ): SW SE NW Sec14Twp5S_Rng32East _ West 2310Feet from _ North / _ South Line of Section 1650Feet fromEast / _ West Line of Section RawlinsCounty
Date of closure: 3/31/09 Was an artificial liner used? Yes No	RECEIVEL KANSAS CORPORATIO I COMMISSIO APR 10 2009
If no, how were the sides and bottom sealed to prevent downward migration of the pit content	COI43EMANTON DIAISION
Native mud was used to seal the base of the pit.	1A/ICLUTA IVO
Wattve mad was used to sear the base of the pit.	WICHITA, KS
Native mad was used to sear the base of the pit.	WICHIIA, NO
Native mad was used to sear the base of the pit.	WICHIIA, NO
Abandonment procedure of pit:	
Abandonment procedure of pit:	ral state.
Abandonment procedure of pit: Remove free fluid, let dry, backfill, level as close as possible to it's nature	n for McCoy Petroleum Corporation (Co.),
Abandonment procedure of pit: Remove free fluid, let dry, backfill, level as close as possible to it's nature. The undersigned hereby certifies that he /xxxx is	ral state. n for McCoy Petroleum Corporation (Co.), is ANXX knowledge and belief. Signature of Applicant or Agent
Abandonment procedure of pit: Remove free fluid, let dry, backfill, level as close as possible to it's nature. The undersigned hereby certifies that he /xxxx is	ral state. n for McCoy Petroleum Corporation (Co.), is MXX knowledge and belief.
Abandonment procedure of pit: Remove free fluid, let dry, backfill, level as close as possible to it's nature. The undersigned hereby certifies that he /xxxx is	n for McCoy Petroleum Corporation (Co.), is ***** knowledge and belief. Signature of Applicant or Agent Scott Hampel
Abandonment procedure of pit: Remove free fluid, let dry, backfill, level as close as possible to it's natural structure. The undersigned hereby certifies that he /xxxx is	ral state. n for McCoy Petroleum Corporation (Co.), is MXX knowledge and belief. Signature of Applicant or Agent Scott Hampel Typed Name
Abandonment procedure of pit: Remove free fluid, let dry, backfill, level as close as possible to it's nature. The undersigned hereby certifies that he /xxxx is	ral state. n for McCoy Petroleum Corporation (Co.), is MXX knowledge and belief. Signature of Applicant or Agent Scott Hampel Typed Name