Kansas Corporation Commission Oil & Gas Conservation Division

Form CDP-4 ·
April 2004
Form must be Typed

CLOSURE OF SURFACE PIT

Operator Name: EOG Resources, Inc.	License Number: 5278
Operator Address: 3817 NW Expressway #500, Oklahoma City	, OK 73112
Contact Person: Sheila Rogers	Phone Number: (405) 246 - 3236
Permit Number (API No. if applicable): 175-22074 6 9	Lease Name & Well No.: Charles 14 #1H
Type of Pit:	Pit Location (QQQQ):
Emergency Pit Burn Pit	<u>N/2</u> _ <u>SE</u> _ <u>SE</u> _ <u>NW</u>
Settling Pit	Sec. 14 Twp. 34S R. 34 East West
Workover Pit Haul-Off Pit	2220' Feet from 🗸 North / 🗌 South Line of Section
	2310' Feet from East / West Line of Section
	Seward County
Date of closure: 10/20/07	
Was an artificial liner used? ☐ Yes ✓ No	
I NOUVE HUUG AHU CIAVS.	
	RECEIVED
Abandonment procedure of pit:	RECEIVED KANSAS CORPORATION COMMISSIDA
Abandonment procedure of pit:	KANSAS CORPORATION COMMISSION
Abandonment procedure of pit: Backfill and level as close as possible to its natural state.	JAN 0 3 2008 CONSERVATION DIVISION WICHITA, KS
Abandonment procedure of pit: Backfill and level as close as possible to its natural state. The undersigned hereby certifies that he / she is Applicant	KANSAS CORPORATION COMMISSIDE JAN 0 3 2008 CONSERVATION DIVISION WICHITA, KS for EOG Resources, Inc. (Co.),
Abandonment procedure of pit: Backfill and level as close as possible to its natural state.	KANSAS CORPORATION COMMISSIDE JAN 0 3 2008 CONSERVATION DIVISION WICHITA, KS for EOG Resources, Inc. (Co.),
Abandonment procedure of pit: Backfill and level as close as possible to its natural state. The undersigned hereby certifies that he / she is Applicant	KANSAS CORPORATION COMMISSIDE JAN 0 3 2008 CONSERVATION DIVISION WICHITA, KS for EOG Resources, Inc. (Co.),
Abandonment procedure of pit: Backfill and level as close as possible to its natural state. The undersigned hereby certifies that he / she is	JAN 0 3 2008 CONSERVATION DIVISION WICHITA, KS forEOG Resources, Inc. (Co.), best of his /her knowledge and belief. Signature of Applicant or Agent
Abandonment procedure of pit: Backfill and level as close as possible to its natural state. The undersigned hereby certifies that he / she is	JAN 0 3 2008 CONSERVATION DIVISION WICHITA, KS forEOG Resources, Inc. (Co.), best of his /her knowledge and belief. Signature of Applicant or Agent
Abandonment procedure of pit: Backfill and level as close as possible to its natural state. The undersigned hereby certifies that he / she is	JAN 0 3 2008 CONSERVATION DIVISION WICHITA, KS ForEOG Resources, Inc(Co.), best of his /her knowledge and belief. Signature of Applicant or Agent December
Abandonment procedure of pit: Backfill and level as close as possible to its natural state. The undersigned hereby certifies that he / she is	JAN 0 3 2008 CONSERVATION DIVISION WICHITA, KS forEOG Resources, Inc. (Co.), best of his /her knowledge and belief. Signature of Applicant or Agent
Abandonment procedure of pit: Backfill and level as close as possible to its natural state. The undersigned hereby certifies that he / she is	JAN 0 3 2008 CONSERVATION DIVISION WICHITA, KS ForEOG Resources, Inc(Co.), best of his /her knowledge and belief. Signature of Applicant or Agent December