KANSAS CORPORATION COMMISSION OIL & GAS CONSERVATION DIVISION

Form CDP-4 April 2004 Form must be Typed

CLOSURE OF SURFACE PIT

Operator Name: Hummon Corporation	License Number: 5050
Operator Address: 950 N. Tyler, Wichita, Kansas 67212	
Contact Person: Krista L. Dahlinger	Phone Number: (316) 773 - 2300
Permit Number (API No. if applicable): 15-007-23183-00-00	Lease Name & Well No.: Platt 2-6
Type of Pit:	Pit Location (QQQQ):
Emergency Pit Burn Pit	NW SE NE SW
Settling Pit ✓ Drilling Pit	Sec. 6 Twp. 34S R. 15W East West
Workover Pit Haul-Off Pit	1865 Feet from North / South Line of Section
	-2130 Feet from East / ✓ West Line of Section
	Barber County
	County
Date of closure: April 3, 2009	,
Was an artificial liner used? ☐ Yes ✓ No	·
	KANCAC CODDODATION CONTRA
·	COMMIA COULDING COMMIA
If no, how were the sides and bottom sealed to prevent downward migration. Native clays used to line bottom and sides of pit.	of the pit contents? MAY 0 4 2009
	of the pit contents? MAY 0 4 2009
	of the pit contents?
Native clays used to line bottom and sides of pit.	of the pit contents? MAY 0 4 2009
Native clays used to line bottom and sides of pit. Abandonment procedure of pit:	MAY 0 4 2009 RECEIVED
Native clays used to line bottom and sides of pit. Abandonment procedure of pit: Haul free fluids to disposal subsequent to drilling active	MAY 0 4 2009 RECEIVED vity. Allow evaporation of remaining fluids. Push
Native clays used to line bottom and sides of pit. Abandonment procedure of pit: Haul free fluids to disposal subsequent to drilling active	MAY 0 4 2009 RECEIVED vity. Allow evaporation of remaining fluids. Push
Native clays used to line bottom and sides of pit. Abandonment procedure of pit: Haul free fluids to disposal subsequent to drilling active	MAY 0 4 2009 RECEIVED vity. Allow evaporation of remaining fluids. Push
Native clays used to line bottom and sides of pit. Abandonment procedure of pit: Haul free fluids to disposal subsequent to drilling active excavated dirt into pit in several stages to restore orig	MAY 0 4 2009 RECEIVED vity. Allow evaporation of remaining fluids. Push ginal ground surface materials and contour.
Native clays used to line bottom and sides of pit. Abandonment procedure of pit: Haul free fluids to disposal subsequent to drilling active excavated dirt into pit in several stages to restore original the undersigned hereby certifies that he / she is Exploration Man	MAY 0 4 2009 RECEIVED vity. Allow evaporation of remaining fluids. Push ginal ground surface materials and contour. nager for Hummon Corporation (Co.),
Native clays used to line bottom and sides of pit. Abandonment procedure of pit: Haul free fluids to disposal subsequent to drilling active excavated dirt into pit in several stages to restore original endorsions and the undersigned hereby certifies that he / she is Exploration Management and sides of pit.	MAY 0 4 2009 RECEIVED wity. Allow evaporation of remaining fluids. Push ginal ground surface materials and contour. hager for Hummon Corporation (Co.),
Native clays used to line bottom and sides of pit. Abandonment procedure of pit: Haul free fluids to disposal subsequent to drilling active excavated dirt into pit in several stages to restore original the undersigned hereby certifies that he / she is Exploration Man	MAY 0 4 2009 RECEIVED vity. Allow evaporation of remaining fluids. Push ginal ground surface materials and contour. nager for Hummon Corporation (Co.),
Native clays used to line bottom and sides of pit. Abandonment procedure of pit: Haul free fluids to disposal subsequent to drilling active excavated dirt into pit in several stages to restore original excavated dirt into pit in several stages. Exploration Main the undersigned hereby certifies that he / she is	MAY 0 4 2009 RECEIVED vity. Allow evaporation of remaining fluids. Push ginal ground surface materials and contour. nager for Hummon Corporation (Co.),
Native clays used to line bottom and sides of pit. Abandonment procedure of pit: Haul free fluids to disposal subsequent to drilling active excavated dirt into pit in several stages to restore orig	MAY 0 4 2009 RECEIVED wity. Allow evaporation of remaining fluids. Push ginal ground surface materials and contour. nager
Native clays used to line bottom and sides of pit. Abandonment procedure of pit: Haul free fluids to disposal subsequent to drilling active excavated dirt into pit in several stages to restore original duly authorized agent, that all information shown hereon is true and correct	MAY 0 4 2009 RECEIVED wity. Allow evaporation of remaining fluids. Push ginal ground surface materials and contour. hager for Hummon Corporation (Co.), to the best of his /her knowledge and belief. Signature of Applicant or Agent
Native clays used to line bottom and sides of pit. Abandonment procedure of pit: Haul free fluids to disposal subsequent to drilling active excavated dirt into pit in several stages to restore original duly authorized agent, that all information shown hereon is true and correct	MAY 0 4 2009 RECEIVED wity. Allow evaporation of remaining fluids. Push ginal ground surface materials and contour. hager for Hummon Corporation (Co.), to the best of his /her knowledge and belief. Signature of Applicant or Agent
Native clays used to line bottom and sides of pit. Abandonment procedure of pit: Haul free fluids to disposal subsequent to drilling active excavated dirt into pit in several stages to restore original duly authorized agent, that all information shown hereon is true and correct	MAY 0 4 2009 RECEIVED wity. Allow evaporation of remaining fluids. Push ginal ground surface materials and contour. hager for Hummon Corporation (Co.), to the best of his /her knowledge and belief. Signature of Applicant or Agent