$3-\cancel{4}$ 4-031892

TO:	API number: 15 1950
STATE CORPORATION COMMISSION	
CONSERVATION DIVISION - PLUGGING	NW NW SW /4 SEC. 03 , 10 S , 17 W
200 COLORADO DERBY BUILDING	2310 feet from S section line
WICHITA, KANSAS 67202	4950 feet from E section line
Operator license# 5229	Lease Nettie Unit well #11-01
Operator: Phillips Petroleum Company Address: Rt. 3 - Box 20A	County Rooks
	$^{\prime\prime}\eta$.
Address: Rt. 3 - Box 20A	Well total depth <u>3617</u> feet
_Great Bend, Kansas 67530	Conductor Pipe: s inch @ 0 feet
	Surface pipe 8 5/8 Inch 0 184 feet
Aband oil well Y Cas well Inn	ut wall SWD DE X
Aband. oil well X, Gas well, Input well, SWD, D & A	
Plugging contractor: <u>Kelso Casing Pulling</u> License# 6050	
Address: Chase, Kansas 67524	
Company to plug at: Hour: P.M. Day:	4 Month: March Year: 94
Diversing appropriate A. Commanda and A. Comma	
Plugging proposal received from: Richard - Dennis Hamel	
Company: Kelso Casing Pulling - Kansas Corporation Commission Phone:	
company. <u>kerso casing fulling - kansas corporation commission</u> Phone:	
Were: Order 260 sxs. 60/40 pozmix -	10% mal - 400# hulls
Halliburton Order sand and	common cement.
Disamina Danas and Danas in 1	
Plugging Proposal Received by: Carl (Goodrow
Plugging operations attended by agent? All[X], Part[], None[]	
Completed: Hour: 5:30P.M., Day: 4 , Mon	nth. March Voor. 04
oomprocede nour: <u>osourems</u> , bay. 4 , Mor	nen. <u>Maren</u> , fear: 94
Actual plugging report: Sand back to 3:	170' with 5 sxs. common cement on
sand with bailer. Critical shot areas	are at Base Salt 1800' - Anhv. at
1300' - Base Dakota 800'. Shot and red	covered 630' of 5 1/2". Shot at
2200' - 1800' - 1300'. Pipe tight. Mi	ixed and pumped 85 sxs. cement
blend with 200# hulls displaced from 85	50' to 2200' with 500# P.S.I. Shot
at 800'. Pipe tight. Shot free at 630	O'. Mixed and pumped 110 sxs.cement
with 200# hulls to 800' with annulus.	circulate with heavy drill mud.
Laid down to 184' circulated cement to	5/8" with 10 sxs. Slurry. Plug complete.
Remarks:	5/6" with 10 sxs. Sturry. Plug complete.
Condition of casing(in hole):GOOD X BA	AD Anhy.pluq:YES X NO
Bottom plug(in place):YES X ,CALC	/•NO Dakota plug: VES X .NO
Plugged through TUBING, CASING_X	Elevation: GL
	_
I did not observe the pl	Lugging. Received Low
MAD 2 9 1004	STATE PARPURATION COMMISSION
DATE MAR 2 9 1994	MAR 1 6 1994 (agent)
MV. NO. 40173	3-16-94 Form CP-2/3
NO A LACK WAS CONTINUED TO SERVICE THE PARTY OF THE PARTY	CONSERVATION DIVISION