Notice: Fill out COMPLETELY and return to Conservation Division at the address below within 60 days from plugging date.

## KANSAS CORPORATION COMMISSION OIL & GAS CONSERVATION DIVISION

## WELL PLUGGING RECORD K.A.R. 82-3-117

Form CP-4
December 2003
Type or Print on this Form
Form must be Signed
All blanks must be Filled

Lease Operator: Petroleum Technologies, Inc. API Number: \_\_\_**15 -** 009-04469-00-00 Kramp Address: 801 W. 47th Suite 412 Kansas City, Mo. 64112 Lease Name: Phone: (816 ) 531 -6904 Operator License #: 8653 Well Number: Spot Location (QQQQ): \_\_ - SW - NE Type of Well: Oil (Oil, Gas D&A, SWD, ENHR, Water Supply Well, Cathodic, Other) 4290 (If SWD or ENHR) Feet from North / South Section Line The plugging proposal was approved on:\_ 990 Feet from East / West Section Line by: Patrick Staab \_\_\_\_\_(KCC District Agent's Name) County:\_\_\_ Is ACO-1 filed? Yes No If not, is well log attached? Yes No Producing Formation(s): List All (If needed attach another sheet) Date Well Completed: Depth to Top: \_ Bottom: 5-11-09 Plugging Commenced: Depth to Top:\_ Bottom: 5-13-09 Depth to Top: \_\_\_ Bottom: \_\_ Show depth and thickness of all water, oil and gas formations. Oil, Gas or Water Records Casing Record (Surface Conductor & Production) Formation Content From To Size Put In Pulled Out 8-5/8" None 5-1/2" 3364' None Describe in detail the manner in which the well is plugged, indicating where the mud fluid was placed and the method or methods used in introducing it into the hole. If cement or other plugs were used, state the character of same depth placed from (bottom), to (top) for each plug set. Perforated well @1300', 500' & 300'. Ran 2-7/8" tubing to 3100', pumped 12 sxs. gel & 60 sxs. cement, pulled tubing up to 1350', pumped 75 sxs. cement w/150# hulls, pulled up to 600', pumped 175 sxs. cement. Tied onto annulas, pumped 5 sxs. cement, pessured up to 300#, shut in. Top of cement @390', ran tubing to 390' and circulated 110 sxs. cement to surface. Topped off with 10 sxs. Used 60/40 pos, 4% gel. Plugging Complete. Name of Plugging Contractor: Mike's Testing & Salvage, Inc. Address: P.O. Box 467 Chase, Kansas 67524 Name of Party Responsible for Plugging Fees: State of Kansas Mike Kelso (Employee of Operator) or (Operator) on above-described well, being first duly sworn on oath, says: That I have knowledge of the facts statements, and matters herein contained, and the log of the above-described well is as filed, and the same are true and correct, so help me God. P.O. Box 467 Chase, Kansas 67524 (Address)\_ SUBSCRIBED and SWORN TO before me this 19th day of May My Commission Expires: \_ NOTARY PUBLIC - State of Kansas IRENE HERZBERG

Mail to: KCC - Conservation Division, 130 S. Market - Room 2078, Wichita, Kar

QU

My Appt. Exp. 8-24-09