KANSAS CORPORATION COMMISSION OIL & GAS CONSERVATION DIVISION

Form CDP-5 August 2004 Form must be Typed

EXPLORATION & PRODUCTION WASTETRANSFER

Operator Name: American Warrior, Inc.	License Number: 4058
Operator Address: PO Box 399, Garden City, KS 67846	
Contact Person: Scott Corsair	Phone Number: (785) 398 - 2270
Permit Number (API No. if applicable): 15-135-24782 (5 6 0 5	Lease Name: V Strecker
Source of Waste:	Well Number: 1-31
☐ Emergency Pit ☐ Settling Pit ☐ Workover Pit ☐ Drilling Pit ☐ Burn Pit ☐ Haul-off Pit ☐ Steel Pit ☐ Spill / Escape	Source Location (QQQQ): NE - SE - SW - SE Sec. 31 Twp. 18S R. 21 East West 510 Feet from North / South Line of Section 1550 Feet from East / West Line of Section Ness County
Type of waste to be disposed:	Other:
Amount of waste: 1 No. of loads 80 Barrels	Tons YDS
Destination of waste: ☐ Reserve Pit ✓ Disposal Well ☐ Lease Road ☐ Dike / Berm ☐ Other:	
If waste is transferred to another reserve pit, is the lease active? Yes No	
Location of waste disposal: Operator Name: American Warrior, Inc Lease Name: Foos Docket No.: D-25978	Date of Waste Transfer: 10-1-2008 License No.: 4058 Sec. 09 Twp.19 R. 21 ☐ East ✓ West County: Ness
	RECEIVED KANSAS CORPORATION COMMIS OCT 2 3 2008 CONSERVATION DIVISION WICHITA, KS
The undersigned herby certifies that he / she is Petroleum Enginee for American Warrior, Inc. (Co.), a duly aut and correct to the best of his / her knowledge and belief. Subscribed and sworn to before me on this 21st day of October My Commission Expires: 8-15-12	Agent Signature Agent Signature Notary Public
Mail to: KCC - Conservation Division, 130 S. Market -	NOTARY PUBLIC State of Kansas Room 2018 Winna Kansas GRUSE CORSAIR
10. 100 - Conscitation Division, 130 C. Market -	My Appt. Exp. 6-15-12

KANSAS CORPORATION COMMISSION OIL & GAS CONSERVATION DIVISION

EXPLORATION & PRODUCTION WASTE TRANSFER (FORM CDP-5)

Instructions

General Instruction.

1. Form must be typed.

Section 1: Operator Information.

- Operator Name. Enter the operator's full name as it appears on operator's license.
- License #. Enter the operator's license number. To verify KCC operator license information check the Commission's website at http://www.kcc.state.ks.us/conservation/oil_license.cg or contact the Conservation Division's Licensing Department at (316) 337-6194.
- Operator Address. Enter the operator's mailing address: street or PO box number, city, state, and zip code.
- 1d. Contact Person. Enter the name of the individual who will be the operator's contact person for this Exploration and Production Waste Transfer Form, should the Conservation Division Staff need to contact the operator about the form. The contact person may be the operator or the operator's agent.
- Phone. Enter the phone number of the contact person that the Conservation Division Staff may easily reach if necessary to discuss the form.

Section 2: Waste Source.

- 2a. Permit Number (API No. if applicable). Enter the KCC permit number for the pit where the waste to be disposed of or transferred originated. For workover, drilling, and haul-off pits, the Permit Number is the API Number. For emergency, settling, and burn pits, the Permit Number is listed at the bottom of the approved Application for Surface Pit (CDP-1) Form in the "KCC Office Use Only" Section.
- Source of Waste. Mark the appropriate box to indicate the waste origin.
- 2c. Lease Name. Enter the lease name where the waste originated.
- 2d. Well Number. Enter the well number where the waste originated.
- 2e. Waste Origin Geographic Location.
 - 2e(1). QQQQ. Enter the ¼ ¼ ¼ ¼ location within the section of the waste origin.
 - 2e(2). Sec., Twp., and R. Enter the section, township and range number where the waste origin is located and mark the appropriate box to indicate if the range is East or West of the Sixth Principal Meridian.
 - 2e(3). Footage from Section Lines. Enter the number of feet the waste origin is located from the North or South section line and mark the appropriate box to indicate from which section line the measurement was taken. Enter the number of feet the waste origin is located from the East or West section line and mark the appropriate box to indicate from which section line the measurement was taken.
 - 2e(4). County. Enter the county where the waste originated.

Section 3: Type and Amount of Waste.

- 3a. Type of Waste. Mark the appropriate box to indicate the type of waste to be transferred and disposed. If the type of waste is not fluid, soil, or drilling mud/cuttings, mark the "Other" box and give a simple but specific description of the type of waste.
- Amount of Waste. Enter the amount of waste to be transferred and disposed in the appropriate box, according to how the quantity of waste is measured.

Section 4: Waste Destination.

- 4a. Destination. Mark the appropriate box to indicate how the waste will be disposed. If the disposal method is not provided, mark the "Other" box and give a simple but specific description of the disposal method.
- 4b. Transfers to Reserve Pit. Mark the appropriate box to indicate if the waste is being transferred to a reserve pit on an active lease.

4c. Location of Waste Disposal.

- 4c(1). **Operator Name**. Enter the disposing operator's full name as it appears on operator's license.
- Lease Name. Enter the name of the lease where the subject waste will be disposed.
- 4c(3). Docket No. Enter the KCC Docket Number under which the disposing operator is permitted for disposal on the disposing lease.
- 4c(4). Date of Waste Transfer. Enter the date when the subject waste will be transferred.
- 4c(5). License No. Enter the disposing operator's license number. To verify KCC operator license information check the Commission's website at http://www.kcc.state.ks.us/conservation/oil_license.cg or contact the Conservation Division's Licensing Department at (316) 337-6194.
- 4c(6). **Sec., Twp., R.** Enter the section, township and range number where the waste disposal is located and mark the appropriate box to indicate if the range is East or West of the Sixth Principal Meridian.
- 4c(7). County. Enter the county where the waste disposal is located.

Section 5: Verification.

- Position with operator. Enter the position the person completing the Exploration & Production Waste Transfer Form holds with the operator.
- Operator Name. Enter the operator's full name as it appears in Section 1a.
- Signature. The applicant must sign the Closure of Surface Pit Form in front of a legal notary to verify that the information on the form is true and correct.
- 5d. Legal Notary. A legal notary will complete the 5d sections.